



# Asbestos Reassessment

Cathedral High School  
30 Wentworth Street North,  
Hamilton, Ontario

Prepared for:

**Hamilton-Wentworth Catholic  
District School Board**

90 Mulberry Street  
Hamilton, Ontario, L8N 3R9

August 29, 2022

Pinchin File: 303992.004



**Asbestos Reassessment**

Cathedral High School, 30 Wentworth Street North, Hamilton, Ontario  
Hamilton-Wentworth Catholic District School Board

August 29, 2022  
Pinchin File: 303992.004

**Issued to:** Hamilton-Wentworth Catholic District  
School Board  
**Issued on:** August 29, 2022  
**Pinchin File:** 303992.004  
**Issuing Office:** Hamilton, ON  
**Pinchin Contact:** Emily Balfour, Project Manager  
365.889.5147  
[ebalfour@pinchin.com](mailto:ebalfour@pinchin.com)

---



Author: Luke Thompson ADip.T.(Arch)  
Project Technologist  
289.922.8960  
[lthompson@pinchin.com](mailto:lthompson@pinchin.com)

Reviewer: Damian Palus, C.E.T.  
Operations Manager  
289.678.0694  
[dpalus@pinchin.com](mailto:dpalus@pinchin.com)



## **EXECUTIVE SUMMARY**

Hamilton-Wentworth Catholic District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment at the subject building.

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM), and develop corrective action plans as required for the purposes of long-term management. The results of this reassessment are not intended for construction, renovation, demolition or project tendering purposes.

### **Summary of Recommendations**

The following is a summary of significant recommendations; refer to the body of the report for detailed recommendations:

- Perform a reassessment of asbestos materials on an annual basis.
- Perform a pre-construction assessment and remove all asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work.
- Follow appropriate safe work procedures when handling or disturbing asbestos.
- Sample any presumed ACM prior to alteration or maintenance work if presumed ACM may be disturbed by the work.

*This Executive Summary is subject to the same standard limitations as contained in the report and must be read in conjunction with the entire report.*



## Asbestos Reassessment

Cathedral High School, 30 Wentworth Street North, Hamilton, Ontario  
Hamilton-Wentworth Catholic District School Board

August 29, 2022  
Pinchin File: 303992.004

### TABLE OF CONTENTS

1.0	INTRODUCTION AND SCOPE .....	1
1.1	Scope of Assessment .....	1
2.0	BACKGROUND INFORMATION .....	1
2.1	Building Year of Construction .....	1
2.2	Existing Reports .....	1
3.0	FINDINGS .....	2
3.1	Excluded Asbestos Materials .....	2
3.2	Confirmed/Presumed Asbestos-Containing Materials and Confirmed Non-Asbestos Materials .....	2
4.0	RECOMMENDATIONS .....	4
4.1	General .....	4
4.2	Remedial Work .....	4
4.3	On-going Management and Maintenance .....	4
5.0	TERMS AND LIMITATIONS .....	5
6.0	REFERENCES .....	5

### APPENDICES

APPENDIX I	Asbestos Analytical Certificates
APPENDIX II	Location List
APPENDIX III	Hazardous Materials Summary / Sample Log Report
APPENDIX IV	All Data Report
APPENDIX V	Drawings



## 1.0 INTRODUCTION AND SCOPE

Hamilton-Wentworth Catholic District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment at Cathedral High School, located at 30 Wentworth Street North, Hamilton, Ontario.

The reassessment was performed by Luke Thompson, Project Technologist on May 20, 2022.

The objectives of the reassessment were to document the locations, quantities and conditions of previously identified asbestos-containing building materials, and develop corrective action plans as required. This reassessment is only to be used for the purposes of long-term management and routine maintenance. The results of this reassessment are not to be used for construction, renovation, demolition or project tendering purposes.

### 1.1 Scope of Assessment

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM's), and develop corrective action plans as required.

Refer to the Asbestos Building Materials Reassessment Methodology report and Annex A dated 2022, Pinchin File 303992.004, for the methodology used during the reassessment.

## 2.0 BACKGROUND INFORMATION

### 2.1 Building Year of Construction

Item	Details
Year of Construction	1995

### 2.2 Existing Reports

#### 2.2.1 Review of Previous Reports

Pinchin previously prepared the following report, which has been reviewed and relied upon as part of this assessment:

- “Asbestos Assessment, Cathedral High School, 30 Wentworth Street North, Hamilton, Ontario”, September 2018, Prepared by Pinchin Ltd., Pinchin File: 224334.
- “Asbestos Reassessment, Cathedral High School, 30 Wentworth Street North, Hamilton, Ontario”, August 2019, Prepared by Pinchin Ltd., Pinchin File: 243241.
- “Asbestos Reassessment, Cathedral High School, 30 Wentworth Street North, Hamilton, Ontario”, June 2020, Prepared by Pinchin Ltd., Pinchin File: 272113.



## Asbestos Reassessment

Cathedral High School, 30 Wentworth Street North, Hamilton, Ontario  
Hamilton-Wentworth Catholic District School Board

August 29, 2022  
Pinchin File: 303992.004

- “Asbestos Reassessment, Cathedral High School, 30 Wentworth Street North, Hamilton, Ontario”, July 2021, Prepared by Pinchin Ltd., Pinchin File: 286533.001.

### 3.0 FINDINGS

Previous analytical sample results have been relied upon and were included in the original asbestos assessment report completed by MTE Consultants Inc. Additional samples results where collected by Pinchin have been included in Appendix I.

The following section summarizes the findings of the reassessment and provides a general description of the asbestos materials identified. For details on quantities, assessment, sample numbers, friability, condition, and locations of asbestos materials; refer to the Hazardous Materials Summary / Sample Log Report and All Data Report in Appendix III and IV, respectively.

#### 3.1 Excluded Asbestos Materials

A number of materials which might contain asbestos were not sampled during this reassessment due to limitations in scope and methodology. Where present, these materials are assumed to contain asbestos until otherwise proven by sampling and analysis. These materials are not shown on the drawings in Appendix V. Materials presumed to contain asbestos include:

Material	Friability
Elevator and lift brakes	Non-friable
Vermiculite in concrete block wall cavities	Friable
Caulking and butyl seals	Non-friable
Mechanical packing, ropes and gaskets	Non-friable
Firestopping	Non-friable
Mastics and adhesives	Non-friable
Vinyl baseboards	Non-friable
Ceramic tile thin-set	Non-friable


#### 3.2 Confirmed/Presumed Asbestos-Containing Materials and Confirmed Non-Asbestos Materials

This section includes materials that have been confirmed asbestos-containing by sample analysis or determined to be non-asbestos based on the date of construction of the building. Refer to the drawings in



Appendix V for the locations of confirmed ACMs indicated via hatching or symbols. The locations of samples from the historical assessment, performed by Pinchin, have been included on the drawings.

<b>Material and Application</b>	<b>Asbestos Type/Friability</b>	<b>Photo</b>
Non-asbestos containing fireproofing is present on structural steel including beams, trusses, joists, corrugated steel deck, concrete deck, columns.	None	
Non-asbestos texture finish is present on the concrete deck	None	
Pipes are either uninsulated or insulated with non-asbestos fibreglass or elastomeric insulation (Armaflex).	None	
Ducts are either uninsulated or insulated with non-asbestos fibreglass (foil-faced or canvas).	None	
Mechanical equipment is either uninsulated or insulated with non-asbestos fibreglass.	None	
All ceiling tiles are presumed to be non-asbestos based on the date of manufacture determined from the date stamp applied to the top of the tiles or the age of the materials determined from the age of the building.	None	
Asbestos in drywall joint compound was banned in Canada in 1980. Drywall joint compound in the building was installed after 1986 (1980 plus a reasonable non-compliance period based on our experience) and is assumed to contain no asbestos.	None	
Vinyl floor tiles were presumed to be non-asbestos based on historical knowledge of the date of installation.	None	

Material and Application	Asbestos Type/Friability	Photo
Gaskets are present in the mechanical rooms.	Chrysotile/Non-friable	

## 4.0 RECOMMENDATIONS

### 4.1 General

Perform a detailed intrusive assessment prior to building renovation or demolition operations. The assessment should include; destructive testing (i.e. coring and/or removal of building finishes and components), sampling of other hazardous materials (lead, mercury, PCBs, mould, etc.), and materials not tested in this study (i.e. excluded asbestos materials).

### 4.2 Remedial Work

There is no remedial work recommended.

### 4.3 On-going Management and Maintenance

The following recommendations are made regarding on-going management and maintenance work involving the asbestos materials identified.

#### 4.3.1 Asbestos

Maintain the Asbestos Management Program (AMP).

Perform a re-assessment of asbestos materials on an annual basis.

Remove asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work. Follow appropriate asbestos precautions for the classification of work being performed.

Sample presumed ACM prior to alteration or maintenance work if the presumed ACM may be disturbed by the work.





Update the asbestos inventory report upon completion of any abatement and removal of asbestos-containing materials.

## **5.0 TERMS AND LIMITATIONS**

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.

## **6.0 REFERENCES**

The following legislation and documents were referenced in completing the assessment and this report:

1. Asbestos on Construction Projects and in Buildings and Repair Operations, Ontario Regulation 278/05.
2. Designated Substances, Ontario Regulation 490/09.

J:\303000s\0303992.000 HWCDSB,Various2022Projects,ASB,CONS\0303992.004 HWCDSB,AllFacilities,2022,ASB,REASSMT\Deliverables\Secondary\Cathedral HS\Report\303992.004 Cathedral ACM Reassmnt Report HWCDSB Aug 29 2022.docx

Template: Master Report for Asbestos Reassessment, HAZ, April 23, 2019

**APPENDIX I**  
**Asbestos Analytical Certificates**



## Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

**Project Name:** HWCDSB - Cathedral High School, 30 Wentworth St. N, Hamilton, ON  
**Project No.:** 0224334.000  
**Prepared For:** R. Bertin-Fenney  
**Lab Reference No.:** b194334  
**Analyst(s):** R. Dacey / N. Barinque  
**Date Received:** August 3, 2018      **# Samples submitted:** 3  
**Date Analyzed:** August 13, 2018      **# Phases analyzed:** 5

---

**Method of Analysis:**

**EPA 600/R-93/116 - Method for the Determination of Asbestos in Bulk Building Materials dated July, 1993**

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold (see chart below) indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

Provincial Jurisdiction	Regulatory Threshold	Provincial Jurisdiction	Regulatory Threshold
Ontario, British Columbia, Nova Scotia	0.5%	Alberta	Undefined
Quebec	0.1%	Saskatchewan	0.5% friable 1% non-friable
PEI, NWT, Yukon, Nunavut, Newfoundland and Labrador, and New Brunswick	1%	Manitoba	0.1% friable 1% non-friable

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

Pinchin Ltd. is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA-600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2005.

This report relates only to the items tested.

**NOTE:** *This test report may not be reproduced, except in full, without the written approval of the laboratory. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. This report is valid only when signed in blue ink by the analyst. Vinyl asbestos floor tiles contain very fine fibres of asbestos and may be missed by some laboratories using the PLM method. Internal verification studies performed by Pinchin indicate that the chance of missing asbestos in floor tiles is no higher than about 2%. The vinyl tile study and laboratory documentation on measurement uncertainty is available upon request. The analysis of dust samples by PLM cannot be used as an indicator of past or present airborne asbestos fibre levels.*



**Pinchin Ltd. Asbestos Laboratory**  
***Certificate of Analysis***

**Project Name:** HWCDSB - Cathedral High School, 30 Wentworth St. N, Hamilton, ON  
**Project No.:** 0224334.000  
**Prepared For:** R. Bertin-Fenney

**Lab Reference No.:** b194334  
**Date Analyzed:** August 13, 2018

**BULK SAMPLE ANALYSIS**

SAMPLE IDENTIFICATION	SAMPLE DESCRIPTION	% COMPOSITION (VISUAL ESTIMATE)	
		ASBESTOS	OTHER
0001A Gasket, Penthouse Mechanical Room	2 Phases: a) Homogeneous, brown, layered, compressed fibrous material.	Chrysotile > 75%	Non-Fibrous Material 10-25%
	b) Homogeneous, grey, compressed fibrous material.	Chrysotile > 75%	Non-Fibrous Material 5-10%
0001B Gasket, Penthouse Mechanical Room	Homogeneous, brown, compressed fibrous material.	None Detected	Man-made Vitreous Fibres 10-25%
			Non-Fibrous Material > 75%
0001C Gasket, Penthouse Mechanical Room	2 Phases: a) Homogeneous, brown, compressed fibrous material.	None Detected	Man-made Vitreous Fibres 10-25%
	b) Homogeneous, grey, fibrous material.	Chrysotile > 75%	Non-Fibrous Material > 75%
Comments:		Phase b) is small in size.	

**Reviewed by:**

**Reporting Analyst:**



C. C

Analyzed by: Ru  
Reviewed by: K  
Report Sent by: EL

Instructions: No Stop Positive

**Pinchin Ltd. - Asbestos Laboratory**  
**Internal Asbestos Bulk Sample Chain of Custody**

Client Name:	HWCDSD - Cathedral High School	Project Address:	30 Wentworth Street N, Hamilton, ON
Portfolio/Building No:		Pinchin File:	224334
Submitted by:	Robert Bertin-Fenney	Email:	<a href="mailto:rbertin-fenney@pinchin.com">rbertin-fenney@pinchin.com</a>
CC Results to:	Michael Maiorana	CC Email:	<a href="mailto:mmaioranan@pinchin.com">mmaioranan@pinchin.com</a>
Invoice to:	Accounts Payable	Invoice Email:	<a href="mailto:ap@pinchin.com">ap@pinchin.com</a>
Date Submitted:	August 1 2018	Required by:	August 10 2018
# of Samples:	3	Priority:	5 Day Turnaround
Year of Building Construction (Mandatory Field):			
Do NOT Stop on Positive (Sample Numbers):			
Pinchin Group Company (Mandatory Field):		Pinchin	

**To be Completed by Lab Personnel Only:**

Lab Reference #:	D94334		Time:	24 hour clock		
Received by:	AUG 5 2018		Date:	Month	Day	Year
Name(s) of Analyst(s):	RD/MB. 8.13.18 (5)					
Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)			
	0001	A	Gasket, Penthouse Mechanical Room @ CH > 75% (6) CH > 75%			
	0001	B	Gasket, Penthouse Mechanical Room <del>ND</del> ND			
	0001	C	Gasket, Penthouse Mechanical Room @ ND (5) CH > 75%			

**APPENDIX II**  
**Location List**

**Client:**Hamilton-Wentworth Catholic District Sch  
**Building Name:** Cathedral High School  
**Survey Date:** 2019-08-01

**Site:** 30 Wentworth St N, Hamilton, ON  
**Last Re-Assessment:** 2022-05-18

Location No.	Name or Description	Area ft <sup>2</sup>	Floor No.	Bldg. Phase	Notes
1001	Entire Building	0		A	

**APPENDIX III**

**Hazardous Materials Summary / Sample Log Report**



**Client:** Hamilton-Wentworth Catholic District Sch

**Site:** 30 Wentworth St N, Hamilton, ON

**Building Name:** Cathedral High School

**Survey Date:** 2019-08-01

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	S0001	Other     Gasket   Gasket On Water Line	1001	A	0	0	0	100	Chrysotile	Yes	NF
Asbestos	V9500	Other     Adhesive/mastic   Vinyl Baseboards And Adhesive, Elevator And Lift Brakes	1001	A	0	0	0	33	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other     Caulking	1001	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Wall     Vermiculite/concrete Block Walls	1001	A	0	0	0	100	Presumed Asbestos	Yes	F
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)	1001	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling   Bulkhead   Drywall And Joint Compound	1001	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Duct     Mastic	1001	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Carpet	1001	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Ceramic Tiles	1001	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile And Mastic	1001	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Wood	1001	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Other   Fumehood   Metal	1001	A	0	0	2	0	Non Asbestos	No	
Asbestos	V0000	Piping     Fibreglass	1001	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Structure     Thermal Insulation	1001	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Wall     Concrete (precast)	1001	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Wall     Drywall And Joint Compound	1001	A	0	0	0	100	Non Asbestos	No	

## Legend:

Sample number		Units			
S####	Asbestos sample collected	SF	Square feet	NF	Non Friable material.
L####	Paint sample collected	LF	Linear feet	F	Friable material
P####	PCB sample collected	EA	Each	PF	Potentially Friable material
M####	Mould sample collected	%	Percentage		
V####	Material visually similar to numbered sample collected				
V0000	Known non Hazardous Material				
V9000	Material is visually identified as Hazardous Material				
V9500	Material is presumed to be Hazardous Material				
[Loc. No.]	Abated Material				

**APPENDIX IV**  
**All Data Report**

# ALL DATA REPORT

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1001 : Entire Building  
**Survey Date:** 2019-08-01

**Site:** Secondary  
**Floor:**

**Building Name:** Cathedral High School  
**Room #:**  
**Last Re-Assessment:** 2022-05-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Drywall and joint compound		Texture Coat	C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Mastic			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		vinyl baseboards and adhesive			A	Y		100()			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Wood			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Carpet			A	Y		100			%	V0000	Non-Asbestos		None	
Other		Elevator and lift brakes			A	Y		100()			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other		Adhesive/mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other		Gasket, Gasket on water line in Penthouse			B	Y		100(7)			%	S0001	Chrysotile	>75%	Confirmed Asbestos	NF
Other		Caulking			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Fumehood	Metal			A	Y		2			EA	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	Y		100			%	V0000	Non-Asbestos		None	
Structure		Thermal Insulation			C	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Vermiculite/concrete block walls			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

## Legend:



Sample number		Units		Other	
S####	Asbestos sample collected	SF	Square feet	A	Access
V####	Material visually similar to numbered sample collected	LF	Linear feet	V	Visible
V0000	Known non-asbestos material	EA	Each	AP	Air Plenum
V9000	Visually identified as an asbestos material	%	Percentage	F	Friable material
V9500	Material is presumed to be an asbestos material			NF	Non Friable material
				PF	Potentially Friable material

Access	
A	Accessible to all building occupants
B	Accessible to maintenance and operations staff without a ladder
C	Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas
D	Not normally accessible

Condition	
Good	No visible damage or deterioration
Fair	Minor, repairable damage, cracking, delamination or deterioration
Poor	Irreparable damage or deterioration with exposed and missing material


Visible	
Y	The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels).
N	The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points.

Air Plenum	
Yes or No	The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation.

Colour Coding	
	The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code).
	The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling.

Action					
(1)	Clean up of ACM Debris	(2)	Precautions for Access Which may Disturb ACM Debris	(3)	ACM removal
(4)	Precautions for Work Which may Disturb ACM in Poor Condition	(5)	Proactive ACM removal (Minimum repair required for fair condition)	(6)	ACM repair
(7)	Management program and surveillance				

**APPENDIX V**  
**Drawings**



905-577-6206

www.pinchin.com

LEGEND:

(X) LOCATION NUMBER

⊙ ASBESTOS BULK SAMPLE

ASBESTOS-CONTAINING MATERIALS:

G GASKETS

NOT ALL KNOWN OR SUSPECTED ASBESTOS-CONTAINING BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS REASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS-CONTAINING BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.

CLIENT:



LOCATION:

CATHEDRAL HIGH SCHOOL  
30 WENTWORTH STREET NORTH  
HAMILTON, ONTARIO

TITLE:

ASBESTOS REASSESSMENT  
FLOOR LEVEL 1

DATE:

AUGUST 2022

PROJECT # :

303992.004

DRAWN BY:

EB

CHECKED BY:


EB


SCALE:

NTS

DRAWING:

1 OF 3





905-577-6206

www.pinchin.com

LEGEND:

(X) LOCATION NUMBER

⊙ ASBESTOS BULK SAMPLE

ASBESTOS-CONTAINING MATERIALS:

G GASKETS

NOT ALL KNOWN OR SUSPECTED ASBESTOS-CONTAINING BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS REASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS-CONTAINING BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.

CLIENT:



LOCATION:

CATHEDRAL HIGH SCHOOL  
30 WENTWORTH STREET NORTH  
HAMILTON, ONTARIO

TITLE:

ASBESTOS REASSESSMENT  
FLOOR LEVEL 2

DATE:  
AUGUST 2022

PROJECT # :  
303992.004


DRAWN BY:  
EB

CHECKED BY:  
EB

SCALE:  
NTS

DRAWING:

2 OF 3







NOT ALL KNOWN OR SUSPECTED ASBESTOS-CONTAINING BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS REASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS-CONTAINING BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.



905-577-6206 [www.pinchin.com](http://www.pinchin.com)

LEGEND:

(X) LOCATION NUMBER

◎ ASBESTOS BULK SAMPLE

ASBESTOS-CONTAINING MATERIALS:

G GASKETS

NOT ALL KNOWN OR SUSPECTED ASBESTOS-CONTAINING BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS REASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS-CONTAINING BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.

CLIENT:



LOCATION:  
CATHEDRAL HIGH SCHOOL  
30 WENTWORTH STREET NORTH  
HAMILTON, ONTARIO

TITLE:  
  
ASBESTOS REASSESSMENT  
PENTHOUSE

DATE: AUGUST 2022	PROJECT # : 303992.004
----------------------	---------------------------

DRAWN BY: EB	DRAWING:  3 OF 3
CHECKED BY: EB	
SCALE: NTS	