



Asbestos Reassessment

St. Luke
345 Albright Road, Hamilton,
Ontario

Prepared for:

**Hamilton-Wentworth Catholic
District School Board**

90 Mulberry Street
Hamilton, Ontario, L8N 3R9

August 26, 2022

Pinchin File: 303992.004



Asbestos Reassessment

St. Luke, 345 Albright Road, Hamilton, Ontario
Hamilton-Wentworth Catholic District School Board

August 26, 2022
Pinchin File: 303992.004

Issued to: Hamilton-Wentworth Catholic District
School Board
Issued on: August 26, 2022
Pinchin File: 303992.004
Issuing Office: Hamilton, ON
Pinchin Contact: Emily Balfour, Project Manager
365.889.5147
ebalfour@pinchin.com



Author: Luke Thompson ADip.T.(Arch)
Project Technologist
289.922.8960
lthompson@pinchin.com

Reviewer: Damian Palus, C.E.T.
Operations Manager
289.678.0694
dpalus@pinchin.com



EXECUTIVE SUMMARY

Hamilton-Wentworth Catholic District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment at the subject building.

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM), and develop corrective action plans as required for the purposes of long-term management. The results of this reassessment are not intended for construction, renovation, demolition or project tendering purposes.

Summary of Recommendations

The following is a summary of significant recommendations; refer to the body of the report for detailed recommendations:

- Perform a reassessment of asbestos materials on an annual basis.
- Perform a pre-construction assessment and remove all asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work.
- Follow appropriate safe work procedures when handling or disturbing asbestos.
- Sample any presumed ACM prior to alteration or maintenance work if presumed ACM may be disturbed by the work.

This Executive Summary is subject to the same standard limitations as contained in the report and must be read in conjunction with the entire report.



Asbestos Reassessment

St. Luke, 345 Albright Road, Hamilton, Ontario
Hamilton-Wentworth Catholic District School Board

August 26, 2022
Pinchin File: 303992.004

TABLE OF CONTENTS

1.0	INTRODUCTION AND SCOPE	1
1.1	Scope of Assessment	1
2.0	BACKGROUND INFORMATION	1
2.1	Building Year of Construction and Additions	1
2.2	Existing Reports	1
3.0	FINDINGS	2
3.1	Excluded Asbestos Materials	2
3.2	Confirmed/Presumed Asbestos-Containing Materials and Confirmed Non-Asbestos Materials	3
4.0	RECOMMENDATIONS	5
4.1	General	5
4.2	Remedial Work	5
4.3	On-going Management and Maintenance	5
5.0	TERMS AND LIMITATIONS	6
6.0	REFERENCES	6

APPENDICES

APPENDIX I	Asbestos Analytical Certificates
APPENDIX II	Location List
APPENDIX III	Hazardous Materials Summary / Sample Log Report
APPENDIX IV	All Data Report
APPENDIX V	Drawings



Asbestos Reassessment

St. Luke, 345 Albright Road, Hamilton, Ontario
Hamilton-Wentworth Catholic District School Board

August 26, 2022
Pinchin File: 303992.004

1.0 INTRODUCTION AND SCOPE

Hamilton-Wentworth Catholic District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment at St. Luke, located at 345 Albright Road, Hamilton, Ontario.

The reassessment was performed by Luke Thompson, Project Technologist on May 11, 2022.

The objectives of the reassessment were to document the locations, quantities and conditions of previously identified asbestos-containing building materials and develop corrective action plans as required. This reassessment is only to be used for the purposes of long-term management and routine maintenance. The results of this reassessment are not to be used for construction, renovation, demolition or project tendering purposes.

1.1 Scope of Assessment

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM's), and develop corrective action plans as required.

Refer to the Asbestos Building Materials Reassessment Methodology report and Annex A dated 2022, Pinchin File 303992.004, for the methodology used during the reassessment.

2.0 BACKGROUND INFORMATION

2.1 Building Year of Construction and Additions

Item	Details
Year of Construction	1974
Year(s) of Additions	2005

2.2 Existing Reports

2.2.1 Review of Previous Reports

Pinchin previously prepared the following reports, which have been reviewed and relied upon as part of this assessment:

- Asbestos Assessment, St. Luke, 345 Albright Road, Hamilton, Ontario, September 2018, Prepared by Pinchin Ltd., Pinchin File: 224334.
- Asbestos Reassessment, St. Luke, 345 Albright Road, Hamilton, Ontario, August 2019, Prepared by Pinchin Ltd., Pinchin File: 243241.



Asbestos Reassessment

St. Luke, 345 Albright Road, Hamilton, Ontario
Hamilton-Wentworth Catholic District School Board

August 26, 2022
Pinchin File: 303992.004

- Asbestos Reassessment, St. Luke, 345 Albright Road, Hamilton, Ontario, April 2020, Prepared by Pinchin Ltd., Pinchin File: 272113.
- Revised Asbestos Reassessment, St. Luke, 345 Albright Road, Hamilton, Ontario, June 2021, Prepared by Pinchin Ltd., Pinchin File: 286533.001.

3.0 FINDINGS

The following section summarizes the findings of the reassessment and provides a general description of the asbestos materials identified. For details on quantities, assessment, sample numbers, friability, condition, and locations of asbestos materials; refer to the Summary Report and All Data Report in Appendix III and IV.

Previous analytical sample results have been relied upon and were included in the original asbestos assessment report completed by MTE Consultants Inc. Additional samples results where collected by Pinchin have been included in Appendix I.

3.1 Excluded Asbestos Materials

A number of materials which might contain asbestos were not sampled during this reassessment due to limitations in scope and methodology. Where present, these materials are assumed to contain asbestos until otherwise proven by sampling and analysis. These materials are not shown on the drawings in Appendix V. Excluded materials presumed to contain asbestos include:

Material	Friability
Roofing, felts and tar	Non-friable
Concrete floor levelling compound	Non-friable
Electrical components or wiring within control centers, breakers, motors or lights, insulation on wiring	Non-friable
Vermiculite in concrete block wall cavities	Friable
Adhesives and duct mastics	Non-friable
Caulking and butyl seals	Non-friable
Fibre reinforced paints and coatings	Non-friable
Paper products	Non-friable
Soffit and fascia boards	Non-friable



Asbestos Reassessment

St. Luke, 345 Albright Road, Hamilton, Ontario
Hamilton-Wentworth Catholic District School Board



August 26, 2022
Pinchin File: 303992.004

Material	Friability
Mechanical packing, ropes and gaskets	Non-friable
Vinyl baseboards	Non-friable
Exterior cladding	Non-friable
Fire resistant doors or metal clad finishes	Non-friable
Vibration dampers on HVAC equipment	Non-friable
Ceramic tile thin-set	Non-friable

3.2 Confirmed/Presumed Asbestos-Containing Materials and Confirmed Non-Asbestos Materials

This section includes materials that have been confirmed asbestos-containing by sample analysis or presumed asbestos-containing by visual identification. Refer to the drawings in Appendix V for the locations of confirmed and presumed ACMs indicated via hatching or symbols. The locations of samples from the historical assessments, performed by Pinchin, have been included on the drawings.

Material and Application	Asbestos Type/Friability	Photo
Pipes are either uninsulated or insulated with non-asbestos fibreglass or elastomeric insulation (Armaflex).	None	
Ducts are either uninsulated or insulated with non-asbestos fibreglass (foil-faced or canvas).	None	
Mechanical equipment is either uninsulated or insulated with non-asbestos fibreglass.	None	
All ceiling tiles are presumed to be non-asbestos based on the date of manufacture determined from the date stamp applied to the top of the tiles or the age of the materials determined from the age of the building renovation.	None	
Non-asbestos drywall joint compound is present on wall and	None	

Material and Application	Asbestos Type/Friability	Photo
ceiling finishes.		
Asbestos in drywall joint compound was banned in Canada in 1980. Drywall joint compound in the 2005 addition was installed after 1986 (1980 plus a reasonable non-compliance period based on our experience) and is assumed to contain no asbestos.	None	
Vinyl sheet flooring, with grey with green and red flecks pattern is present.	Presumed/Potentially Friable	
Vinyl floor tiles, 12"x12", white with grey flecks, are present	<0.5% Chrysotile (tile) None (mastic)	
Remaining vinyl floor tiles were presumed to be non-asbestos based on historical knowledge of the date of installation. Mastic underneath the vinyl floor tiles is presumed to contain asbestos until sampling proves otherwise.	None (tile) Presumed/Non-friable (mastic)	



Additional notes on the drywall joint compound discussed above:

- Drywall (gypsum board) and drywall joint compound is present as a wall and ceiling finish in the building. As per the methodology, drywall joint compound is sampled at exterior walls, columns or other locations that are unlikely to have been renovated in an attempt to determine the presence of asbestos in the original drywall compound. A total of 9 samples of drywall joint compound were collected (samples S0001A-C, S0002A-C, S0003A-C, lab reference no. 71919572) and it was found that all samples do not contain asbestos. Therefore, drywall joint compound present on drywall finishes should be considered to be non-asbestos.

4.0 RECOMMENDATIONS

4.1 General

Perform a detailed intrusive assessment prior to building renovation or demolition operations. The assessment should include; destructive testing (i.e. coring and/or removal of building finishes and components), sampling of other hazardous materials (lead, mercury, PCBs, mould, etc.), and materials not tested in this study (i.e. excluded asbestos materials).

4.2 Remedial Work

There is no remedial work recommended.

4.3 On-going Management and Maintenance

The following recommendations are made regarding on-going management and maintenance work involving the asbestos materials identified.

4.3.1 Asbestos

Maintain the Asbestos Management Program (AMP).

Perform a reassessment of asbestos materials on an annual basis.

Remove asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work. Follow appropriate asbestos precautions for the classification of work being performed.

Sample presumed ACM prior to alteration or maintenance work if the presumed ACM may be disturbed by the work.

Update the asbestos inventory report upon completion of any abatement and removal of asbestos-containing materials.



5.0 TERMS AND LIMITATIONS

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.

6.0 REFERENCES

The following legislation and documents were referenced in completing the assessment and this report:

1. Asbestos on Construction Projects and in Buildings and Repair Operations, Ontario Regulation 278/05.
2. Designated Substances, Ontario Regulation 490/09.

\\pinchin.com\ham\Job\303000s\0303992.000 HWCDSB, Various2022Projects, ASB, CONS\0303992.004
HWCDSB, AllFacilities, 2022, ASB, REASSMT\Deliverables\Elementary\St. Luke\Report\303992.004 St. Luke ACM Reassessment HWCDSB Aug 26 2022.docx

Template: Master Report for Asbestos Reassessment, HAZ, April 23, 2019

APPENDIX I
Asbestos Analytical Certificates



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
6-875 Main St West
Suite 200
Hamilton, Ontario L8S 4P9

Attn: Emily Balfour
Michael Maiorana

Lab Order ID: 71919572
Analysis ID: 71919572_PLM
Date Received: 7/25/2019
Date Reported: 7/30/2019

Project: 230748,345 Albright Road, Hamilton, Ontario, Hamilton-Wentworth Catholic School Board, St. Luke Catholic Elementary School

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
S0001A	Drywall joint compound on wall, Classroom, Location 1008	None Detected		100% Other	White Non Fibrous Homogeneous
71919572PLM_1					Crushed
S0001B	Drywall joint compound on wall, Classroom, Location 1019	None Detected		100% Other	White Non Fibrous Homogeneous
71919572PLM_2					Crushed
S0001C	Drywall joint compound on wall, Classroom, Location 1004	None Detected		100% Other	White Non Fibrous Homogeneous
71919572PLM_3					Crushed
S0002A	Drywall joint compound on wall, Library, Location 1015	None Detected		100% Other	White Non Fibrous Homogeneous
71919572PLM_4					Crushed
S0002B	Drywall joint compound on wall, Special Education Activity Room, Location 1031	None Detected		100% Other	White Non Fibrous Homogeneous
71919572PLM_5					Crushed
S0002C	Drywall joint compound on wall, Special Education, Location 1030	None Detected		100% Other	White Non Fibrous Homogeneous
71919572PLM_6					Crushed
S0003A	Drywall joint compound on wall, Custodian Office, Location 1061	None Detected		100% Other	White Non Fibrous Homogeneous
71919572PLM_7					Crushed
S0003B	Drywall joint compound on wall, Vice Principal, Location 1060	None Detected		100% Other	White Non Fibrous Homogeneous
71919572PLM_8					Crushed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Bart Huber (9)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
6-875 Main St West
Suite 200
Hamilton, Ontario L8S 4P9

Attn: Emily Balfour
Michael Maiorana

Lab Order ID: 71919572
Analysis ID: 71919572_PLM
Date Received: 7/25/2019
Date Reported: 7/30/2019

Project: 230748,345 Albright Road, Hamilton, Ontario, Hamilton-Wentworth Catholic School Board, St. Luke Catholic Elementary School

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
S0003C	Drywall joint compound on wall, Foyer, Location 1057	None Detected		100% Other	White Non Fibrous Homogeneous
71919572PLM_9					Crushed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.


Bart Huber (9)

Analyst

Approved Signatory

71919572

Version 1-15-2012

Client: Contact: Address: Phone: Fax: Email:	Pinchin Ltd. Emily Balfour 6-875 Main Street West, Suite 200, Hamilton ON L8S 4P9 905-577-6206 905-577-6207 ebalfour@pinchin.com mmaiorana@pinchin.com	*Instructions: Use Column "B" for your contact info To See an Example Click the bottom Example Tab. Enter samples between "<<" and ">>"	Invoice to: ap@pinchin.com
Project: Client Notes: P.O. #: Date Submitted: Analysis: TurnAroundTime:	230748,345 Albright Road, Hamilton, Ontario,Hamilton-Wentworth Catholic School Board,St. Luke Catholic Elementary School 230748 July 24,2019 PLM - Stop Positive 4days	Begin Samples with a "<<" above the first sample and end with a ">>" below the last sample. Only Enter your data on the first sheet "Sheet1" Note: Data 1 and Data 2 are optional fields that do not show up on the official report, however they will be included in the electronic data returned to you to facilitate your reintegration of the report data.	 Scientific Analytical Institute 4604 Dundas Dr. Greensboro, NC 27407 Phone: 336.292.3888 Fax: 336.292.3313 Email: lab@sailab.com

Sample Number	Data 1 (Lab use only)	Sample Description	Data 2 (Lab use only)
<<			
S0001A		Drywall joint compound on wall, Classroom, Location 1008	
S0001B		Drywall joint compound on wall, Classroom, Location 1019	
S0001C		Drywall joint compound on wall, Classroom, Location 1004	
S0002A		Drywall joint compound on wall, Library, Location 1015	
S0002B		Drywall joint compound on wall, Special Education Activity Room, Location 1031	
S0002C		Drywall joint compound on wall, Special Education, Location 1030	
S0003A		Drywall joint compound on wall, Custodian Office, Location 1061	
S0003B		Drywall joint compound on wall, Vice Principal, Location 1060	
S0003C		Drywall joint compound on wall, Foyer, Location 1057	
>>			

Accepted ☒
 Rejected ☐

Bulley 7/25
 10/24

APPENDIX II
Location List

Client: Hamilton-Wentworth Catholic District Sch
Building Name: St. Luke
Survey Date: 2018-08-01

Site: 345 Albright Road, Hamilton, ON
Last Re-Assessment: 2022-05-12

Location No.	Name or Description	Area ft ²	Floor No.	Bldg. Phase	Notes
1	Presumed Asbestos-Containing Materials	0		A	
1000	Classroom 1	0	1	A	
1001	Classroom 2	0	1	A	
1002	Classroom 3	0	1	A	
1003	Classroom 4	0	1	A	
1004	Classroom 5	0	1	A	
1005	Classroom 7	0	1	A	
1006	Classroom 9	0	1	A	
1007	Classroom 11	0	1	A	
1008	Classroom 12	0	1	A	
1009	Boiler Room	0	1	A	
1010	Classroom 6	0	1	A	
1011	Classroom 8	0	1	A	
1012	Classroom 10	0	1	A	
1013	Classroom 13	0	1	A	
1014	Corridor	0	1	A	
1015	Library	0	1	A	
1016	Computer Lab	0	1	A	
1017	Classroom 14	0	1	A	
1018	Corridor	0	1	A	
1019	Classroom 15	0	1	A	
1020	Classroom 16	0	1	A	
1021	Womens Staff Washroom	0	1	A	
1022	Mens Staff Washroom	0	1	A	
1023	Copy Room	0	1	A	
1024	French Office	0	1	A	
1025	Storage Closet	0	1	A	
1026	Server Room	0	1	A	
1027	Storage Closet	0	1	A	
1028	Staff Room	0	1	A	
1029	Storage Closet	0	1	A	
1030	Special Education	0	1	A	
1031	Special Education Activity Room	0	1	A	
1032	Special Education Washroom	0	1	A	
1033	Corridor	0	1	A	
1034	Storage	0	1	A	
1035	Storage	0	1	A	
1036	Corridor	0	1	A	
1037	Corridor	0	1	A	
1038	Corridor	0	1	A	
1039	Kindergarten	0	1	A	
1040	Gymnasium	0	1	A	
1041	Gym Storage	0	1	A	
1042	Girls Washroom	0	1	A	
1043	Girls Washroom	0	1	A	
1044	Girls Change Room	0	1	A	
1045	Supply Room	0	1	A	
1046	Electrical Room	0	1	A	
1047	Custodian Storage	0	1	A	
1049	Gym Storage	0	1	A	
1050	Boys Change Room	0	1	A	
1051	Boys Washroom	0	1	A	
1052	Storage	0	1	A	
1053	Storage	0	1	A	
1054	Literacy Room	0	1	A	
1055	Corridor	0	1	A	
1056	Corridor	0	1	A	
1057	Foyer	0	1	A	
1058	Principals Office	0	1	A	
1059	Secretary Office and Office Washroom	0	1	A	

Location No.	Name or Description	Area ft ²	Floor No.	Bldg. Phase	Notes
1060	Vice Principal	0	1	A	
1061	Custodian Office	0	1	A	

APPENDIX III

Hazardous Materials Summary / Sample Log Report

Client: Hamilton-Wentworth Catholic District Sch

Site: 345 Albright Road, Hamilton, ON

Building Name: St. Luke

Survey Date: 2018-08-01

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	S0001 ABC	Wall All Drywall And Joint Compound	1000,1001,1002,1003,1004,1005,1006,1007,1008 1013,1017,1019,1038,1039	A	0	0	0	100	None Detected	No	
Asbestos	S0002 ABC	Wall, Ceiling, Wall All, Bulkhead, All Drywall And Joint Compound	1010,1011,1012,1014,1015,1016,1018,1023,1024 1026,1028,1030,1031,1032,1033,1034,1035,1036 1037	A	0	0	0	100	None Detected	No	
Asbestos	S0003 ABC	Wall, Ceiling, Wall All Drywall And Joint Compound	1056,1057,1058,1059,1060,1061	A	0	0	0	100	None Detected	No	
Asbestos	V9500	Floor Mastic	1000,1001,1002,1010,1011,1012,1013,1016,1017 1019,1020,1021,1022,1023,1024,1025,1026,1027 1028,1029,1030,1031,1033,1034,1035,1039,1040 1041,1049,1054,1058,1059,1060,1061	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Floor All Vinyl Sheet Flooring Grey With Green And Red Flecks	1032	A	0	0	0	100	Presumed Asbestos	Yes	PF
Asbestos	V9500	Other Door, Window Caulking	1	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Electrical Panel Cement Product	1	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Roof Roofing Material	1	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Electrical Panel Textile	1	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Wall Vermiculite/concrete Block Walls	1	A	0	0	0	100	Presumed Asbestos	Yes	F
Asbestos	V0000	Ceiling All Ceiling Tiles (lay-in) 2x4 Short Fissure Random Pinhole (2005)	1000,1001,1002,1003,1004,1005,1006,1007,1008 1010,1011,1012,1013,1014,1015,1016,1017,1018 1019,1020,1021,1022,1023,1024,1025,1026,1027 1028,1029,1030,1031,1032,1033,1034,1036,1037 1038,1039,1041,1042,1043,1044,1045,1047,1049 1050,1051,1052,1053,1054,1055,1056,1058,1059 1060,1061	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor All Vinyl Floor Tile (no Mastic) 12x12 Beige With Brown Flecks (2005)	1000,1001,1002,1010,1011,1012,1013,1016,1017 1019,1020,1021,1022,1023,1024,1025,1026,1027 1028,1029,1030,1031,1033,1034,1035,1039,1040 1041,1049,1054,1058,1059,1060,1061	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor All Vinyl Floor Tile (no Mastic) 12x12 Blue (2005)	1039	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor All Vinyl Floor Tile (no Mastic) 12x12 Green (2005)	1000,1001,1002,1010,1011,1012,1013,1016,1017 1019,1054,1058,1059	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor All Vinyl Floor Tile (no Mastic) 12x12 Red (2005)	1000,1001,1002,1010,1011,1012,1013,1016,1017 1019,1039,1054,1058,1059	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor All Vinyl Floor Tile (no Mastic) 12x12 Yellow (2005)	1039	A	0	0	0	100	Non Asbestos	No	

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	V0000	Floor All Vinyl Floor Tile And Mastic 12x12 Beige With Brown Flecks (2005)	1003,1004,1005,1006,1007,1008	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor All Vinyl Floor Tile And Mastic 12x12 Green (2005)	1003,1004,1005,1006,1007,1008	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor All Vinyl Floor Tile And Mastic 12x12 Red (2005)	1003,1004,1005,1006,1007,1008	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor All Vinyl Floor Tile And Mastic 9x9 White With Grey Flecks (previously Sampled)	1046	A	0	0	0	100	Non Asbestos	No	

Legend:

Sample number	
S####	Asbestos sample collected
L####	Paint sample collected
P####	PCB sample collected
M####	Mould sample collected
V####	Material visually similar to numbered sample collected
V0000	Known non Hazardous Material
V9000	Material is visually identified as Hazardous Material
V9500	Material is presumed to be Hazardous Material
[Loc. No.]	Abated Material

Units	
SF	Square feet
LF	Linear feet
EA	Each
%	Percentage

NF	Non Friable material.
F	Friable material
PF	Potentially Friable material

APPENDIX IV
All Data Report

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1 : Presumed Asbestos-Containing Materials
Survey Date: 2018-08-01

Site: Elementary
Floor:

Building Name: St. Luke

Room #:

Area (sqft): 0

Last Re-Assessment: 2022-05-12

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Other	Door	Caulking			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Electrical Panel	Cement Product			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Electrical Panel	Textile			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Roof	Roofing material			B	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Window	Caulking			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Vermiculite/concrete block walls			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1000 : Classroom 1
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0001	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1001 : Classroom 2
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0001	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1002 : Classroom 3
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0001	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1003 : Classroom 4
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y										
Wall	All	Drywall and joint compound			A	Y		100			%	V0001	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1004 : Classroom 5
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	S0001C	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1005 : Classroom 7
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0001	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1006 : Classroom 9
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0001	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1007 : Classroom 11
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0001	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1008 : Classroom 12
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile and Mastic, 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	S0001A	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1009 : Boiler Room
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Concrete (poured)			B	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Steel			C	Y										
Wall		Masonry			B	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1010 : Classroom 6
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1011 : Classroom 8
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1012 : Classroom 10
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1013 : Classroom 13
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0001	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1014 : Corridor
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1015 : Library
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Drywall and joint compound			C	Y						V0002	None Detected	N.D.	None	
Floor		Carpet			A											
Wall		Drywall and joint compound			A	Y		100			%	S0002A	None Detected	N.D.	None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1016 : Computer Lab
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1017 : Classroom 14
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0001	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1018 : Corridor
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1019 : Classroom 15
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	S0001B	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1020 : Classroom 16
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					

Client: Hamilton-Wentworth Catholic District Sch
Location: #1021 : Womens Staff Washroom
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry		Ceramic Tiles	A	Y		100			%					

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1022 : Mens Staff Washroom
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry		Ceramic Tiles	A	Y		100			%					

Client: Hamilton-Wentworth Catholic District Sch
Location: #1023 : Copy Room
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1024 : French Office
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1025 : Storage Closet
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1026 : Server Room
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1027 : Storage Closet
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1028 : Staff Room
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass		Polyvinyl chloride (PVC)	C	Y										
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1029 : Storage Closet
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1030 : Special Education
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	S0002C	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1031 : Special Education Activity
Room
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall	All	Drywall and joint compound			A	Y		100			%	S0002B	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1032 : Special Education Washroom
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Sheet Flooring, Grey with green and red flecks			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	PF
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1033 : Corridor
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall	All	Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1034 : Storage
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall	All	Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1035 : Storage
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Drywall and joint compound			C	Y		100			%	V0002	None Detected	N.D.	None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall	All	Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1036 : Corridor
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y										
Wall		Masonry			A	Y										
Wall	All	Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1037 : Corridor
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y										
Wall		Masonry			A	Y										
Wall	All	Drywall and joint compound			A	Y		100			%	V0002	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1038 : Corridor
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y										
Wall		Masonry			A	Y										
Wall	All	Drywall and joint compound			A	Y		100			%	V0001	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1039 : Kindergarten
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 yellow (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 blue (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	V0001	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1040 : Gymnasium
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass		Polyvinyl chloride (PVC)	C	Y										
Structure	Deck	Steel			C	Y										
Wall		Masonry			A	Y		100			%					

Client: Hamilton-Wentworth Catholic District Sch
Location: #1041 : Gym Storage
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1042 : Girls Washroom
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y										
Wall		Masonry		Ceramic Tiles	A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1043 : Girls Washroom
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y										
Wall		Masonry		Ceramic Tiles	A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1044 : Girls Change Room
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y										
Wall		Masonry		Ceramic Tiles	A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1045 : Supply Room
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y										
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1046 : Electrical Room
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wall covering, Wood			C	Y										
Floor	All	Vinyl Floor Tile and Mastic, 9x9 white with grey flecks (previously sampled)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					

Client: Hamilton-Wentworth Catholic District Sch
Location: #1047 : Custodian Storage
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y										
Piping		Fibreglass		Polyvinyl chloride (PVC)	C	Y										
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1049 : Gym Storage
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					

Client: Hamilton-Wentworth Catholic District Sch
Location: #1050 : Boys Change Room
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y										
Wall		Masonry		Ceramic Tiles	A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1051 : Boys Washroom
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y										
Wall		Masonry		Ceramic Tiles	A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1052 : Storage
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y										
Piping		Fibreglass		Polyvinyl chloride (PVC)	C	Y										
Wall		Masonry		Ceramic Tiles	A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1053 : Storage
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y										
Piping		Fibreglass		Polyvinyl chloride (PVC)	C	Y										
Wall		Masonry		Ceramic Tiles	A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1054 : Literacy Room
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1055 : Corridor
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y										
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1056 : Corridor
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y										
Wall		Drywall and joint compound			A	Y		100			%	V0003	None Detected	N.D.	None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1057 : Foyer
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Ceramic Tiles			A	Y										
Wall		Drywall and joint compound			A	Y		100			%	S0003C	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1058 : Principals Office
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0003	None Detected	N.D.	None	
Wall		Masonry			A	Y		100			%					

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1059 : Secretary Office and Office Washroom
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 green (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 red (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0003	None Detected	N.D.	None	
Wall		Masonry			A	Y		100			%					

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1060 : Vice Principal
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	S0003B	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1061 : Custodian Office
Survey Date: 2018-08-01

Site: Elementary
Floor: 1

Building Name: St. Luke
Room #:
Last Re-Assessment: 2022-05-12

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (2005)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor	All	Vinyl Floor Tile (No Mastic), 12x12 beige with brown flecks (2005)			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass		Polyvinyl chloride (PVC)	C	N										
Wall		Masonry			A	Y		100			%					
Wall	All	Drywall and joint compound			A	Y		100			%	S0003A	None Detected	N.D.	None	

Legend:



Sample number		Units		Other	
S####	Asbestos sample collected	SF	Square feet	A	Access
V####	Material visually similar to numbered sample collected	LF	Linear feet	V	Visible
V0000	Known non-asbestos material	EA	Each	AP	Air Plenum
V9000	Visually identified as an asbestos material	%	Percentage	F	Friable material
V9500	Material is presumed to be an asbestos material			NF	Non Friable material
				PF	Potentially Friable material

Access	
A	Accessible to all building occupants
B	Accessible to maintenance and operations staff without a ladder
C	Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas
D	Not normally accessible

Condition	
Good	No visible damage or deterioration
Fair	Minor, repairable damage, cracking, delamination or deterioration
Poor	Irreparable damage or deterioration with exposed and missing material

Visible	
Y	The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels).
N	The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points.

Air Plenum	
Yes or No	The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation.

Colour Coding	
	The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code).
	The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling.


Action					
(1)	Clean up of ACM Debris	(2)	Precautions for Access Which may Disturb ACM Debris	(3)	ACM removal
(4)	Precautions for Work Which may Disturb ACM in Poor Condition	(5)	Proactive ACM removal (Minimum repair required for fair condition)	(6)	ACM repair
(7)	Management program and surveillance				

APPENDIX V
Drawings

NOT ALL KNOWN OR SUSPECTED ASBESTOS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS REASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.



905-577-6206 www.pinchin.com

LEGEND:

- (X) LOCATION NUMBER
- ⊙ ASBESTOS BULK SAMPLE

ASBESTOS-CONTAINING MATERIALS:

- VINYL SHEET FLOORING
- MASTIC

CLIENT:



Hamilton-Wentworth
Catholic District School Board
Believing. Achieving. Serving

LOCATION:

ST. LUKE
345 ALBRIGHT ROAD
HAMILTON, ONTARIO

TITLE:

ASBESTOS REASSESSMENT
FLOOR LEVEL 1

DATE:

AUGUST 2022

PROJECT # :

303992.004

DRAWN BY:

EB

CHECKED BY:

EB

SCALE:

NTS

DRAWING:

1 OF 1