



Asbestos Reassessment

Sts. Peter and Paul
49 Fennell Avenue East,
Hamilton, Ontario

Prepared for:

**Hamilton-Wentworth Catholic
District School Board**

90 Mulberry Street
Hamilton, Ontario, L8N 3R9

August 30, 2022

Pinchin File: 303992.004



Asbestos Reassessment

Sts. Peter and Paul, 49 Fennell Avenue East, Hamilton, Ontario
Hamilton-Wentworth Catholic District School Board

August 30, 2022
Pinchin File: 303992.004

Issued to: Hamilton-Wentworth Catholic District
School Board

Issued on: August 30, 2022

Pinchin File: 303992.004

Issuing Office: Hamilton, ON

Pinchin Contact: Emily Balfour, Project Manager
365.889.5147
ebalfour@pinchin.com



Author: _____

Luke Thompson, ADip.T.(Arch)
Project Technologist
289.922.8960
lthompson@pinchin.com

Reviewer: _____

Damian Palus, C.E.T
Operations Manager
289.678.0694
dpalus@pinchin.com



EXECUTIVE SUMMARY

Hamilton-Wentworth Catholic District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment at the subject building.

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM), and develop corrective action plans as required for the purposes of long-term management. The results of this reassessment are not intended for construction, renovation, demolition or project tendering purposes.

Summary of Recommendations

The following is a summary of significant recommendations; refer to the body of the report for detailed recommendations:

- Remediate the materials in Section 4.2.
- Perform a reassessment of asbestos materials on an annual basis.
- Perform a pre-construction assessment and remove all asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work.
- Follow appropriate safe work procedures when handling or disturbing asbestos.
- Sample any presumed ACM prior to alteration or maintenance work if presumed ACM may be disturbed by the work.

This Executive Summary is subject to the same standard limitations as contained in the report and must be read in conjunction with the entire report.



Asbestos Reassessment

Sts. Peter and Paul, 49 Fennell Avenue East, Hamilton, Ontario
Hamilton-Wentworth Catholic District School Board

August 30, 2022
Pinchin File: 303992.004

TABLE OF CONTENTS

1.0	INTRODUCTION AND SCOPE	1
1.1	Scope of Assessment	1
2.0	BACKGROUND INFORMATION	1
2.1	Building Year of Construction and Additions	1
2.2	Existing Reports	1
3.0	FINDINGS	2
3.1	Excluded Asbestos Materials	2
3.2	Confirmed/Presumed Asbestos-Containing Materials and Confirmed Non-Asbestos Materials	3
4.0	RECOMMENDATIONS	10
4.1	General	10
4.2	Remedial Work	11
4.3	On-going Management and Maintenance	11
5.0	TERMS AND LIMITATIONS	11
6.0	REFERENCES	12

APPENDICES

APPENDIX I	Asbestos Analytical Certificates
APPENDIX II	Location List
APPENDIX III	Hazardous Materials Summary / Sample Log Report
APPENDIX IV	All Data Report
APPENDIX V	Drawings



1.0 INTRODUCTION AND SCOPE

Hamilton-Wentworth Catholic District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment at Sts. Peter and Paul, located at 49 Fennell Avenue East, Hamilton, Ontario.

The reassessment was performed by Luke Thompson, Project Technologist on June 28, 2022.

The objectives of the reassessment were to document the locations, quantities and conditions of previously identified asbestos-containing building materials and develop corrective action plans as required. This reassessment is only to be used for the purposes of long-term management and routine maintenance. The results of this reassessment are not to be used for construction, renovation, demolition or project tendering purposes.

1.1 Scope of Assessment

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM's), and develop corrective action plans as required.

Refer to the Asbestos Building Materials Reassessment Methodology report and Annex A dated 2022, Pinchin File 303992.004, for the methodology used during the reassessment.

2.0 BACKGROUND INFORMATION

2.1 Building Year of Construction and Additions

Item	Details
Year of Construction	1948
Year(s) of Additions	1951, 1956, 1960, 1964, 1969, 2017

2.2 Existing Reports

2.2.1 Review of Previous Reports

Pinchin previously prepared the following reports, which have been reviewed and relied upon as part of this assessment:

- Asbestos Assessment, Sts. Peter and Paul, 49 Fennell Avenue East, Hamilton, Ontario, August 2018, Prepared by Pinchin Ltd., Pinchin File: 224334.
- Asbestos Reassessment, Sts. Peter and Paul, 49 Fennell Avenue East, Hamilton, Ontario, September 2019, Prepared by Pinchin Ltd., Pinchin File: 243241.



Asbestos Reassessment

Sts. Peter and Paul, 49 Fennell Avenue East, Hamilton, Ontario
Hamilton-Wentworth Catholic District School Board

August 30, 2022
Pinchin File: 303992.004

- Asbestos Reassessment, Sts. Peter and Paul, 49 Fennell Avenue East, Hamilton, Ontario, July 2020, Prepared by Pinchin Ltd., Pinchin File: 272113.
- Asbestos Reassessment, Sts. Peter and Paul, 49 Fennell Avenue East, Hamilton, Ontario, August 2021, Prepared by Pinchin Ltd., Pinchin File: 286533.001

3.0 FINDINGS

The following section summarizes the findings of the reassessment and provides a general description of the asbestos materials identified. For details on quantities, assessment, sample numbers, friability, condition, and locations of asbestos materials; refer to the Hazardous Materials Summary / Sample Log Report and All Data Report in Appendices III and IV, respectively.

Previous analytical sample results have been relied upon and were included in the original asbestos assessment report completed by MTE Consultants Inc. Additional samples results where collected by Pinchin have been included in Appendix I.

3.1 Excluded Asbestos Materials


A number of materials which might contain asbestos were not sampled during this reassessment due to limitations in scope and methodology. Where present, these materials are assumed to contain asbestos until otherwise proven by sampling and analysis. These materials are not shown on the drawings in Appendix V. Excluded materials presumed to contain asbestos include:



Material	Friability
Roofing, felts and tar	Non-friable
Concrete floor levelling compound	Non-friable
Electrical components or wiring within control centers, breakers, motors or lights, insulation on wiring	Non-friable
Vermiculite in concrete block wall cavities	Friable
Adhesives and duct mastics	Non-friable
Caulking and butyl seals	Non-friable
Fibre reinforced paints and coatings	Non-friable
Paper products	Non-friable
Soffit and fascia boards	Non-friable


Material	Friability
Mechanical packing, ropes and gaskets	Non-friable
Vinyl baseboards	Non-friable
Exterior cladding	Non-friable
Fire resistant doors or metal clad finishes	Non-friable
Stucco, plaster or other cementitious parge coatings	Potentially friable
Vibration dampers on HVAC equipment	Non-friable
Ceramic tile thin-set	Non-friable




3.2 Confirmed/Presumed Asbestos-Containing Materials and Confirmed Non-Asbestos Materials




This section includes materials that have been confirmed asbestos-containing by sample analysis or presumed asbestos-containing by visual identification. Refer to the drawings in Appendix V for the locations of confirmed and presumed ACMs indicated via hatching or symbols. The locations of samples from both the current assessment and historical assessments performed by Pinchin, have been included on the drawings.




Material and Application	Asbestos Type/Friability	Photo
Parging cement is present on pipe fittings (elbows, valves, tees, hangers etc.)	Chrysotile/Friable	



Material and Application	Asbestos Type/Friability	Photo
Sweatwrap insulation (brown layered paper) is present on straight sections of pipes.	None	
Remaining pipes are either uninsulated or insulated with non-asbestos fibreglass or elastomeric insulation (Armaflex).	None	
Ducts are either uninsulated or insulated with non-asbestos fibreglass (foil-faced or canvas).	None	
Mechanical equipment is either uninsulated or insulated with non-asbestos fibreglass.	None	
Vermiculite is present as insulation in perimeter masonry block walls of the Gymnasium (Location 1001). The vermiculite was analyzed and no asbestos was detected.	None	
12"x12" glued-on ceiling tiles, with a pinhole pattern are present. Non-asbestos adhesive is present on the backside on the glued-on ceiling tiles.	None (tile) None (adhesive)	


Material and Application	Asbestos Type/Friability	Photo
All lay-in ceiling tiles were determined to be non-asbestos based on previous sampling or are presumed to be non-asbestos based on the date of manufacture determined from the date stamp applied to the top of the tiles or the age of the materials determined from the age of the building or the renovation.	None	
Smooth and rough plaster present on walls and ceilings does not contain asbestos.	None	
Asbestos-containing drywall joint compound is present as a patch material on plaster in Classroom (Location 2005) and may be present in other locations.	Chrysotile/Non-friable	
Non-asbestos drywall joint compound is present on drywall wall and ceiling finishes.	None	
Asbestos in drywall joint compound was banned in Canada in 1980. Drywall joint compound in the 2017 addition was installed after 1986 (1980 plus a reasonable non-compliance period based on our experience) and is assumed to contain no asbestos.	None	

Material and Application	Asbestos Type/Friability	Photo
<p>Vinyl sheet flooring, with a brown pebble pattern is present.</p> <p>The adhesive adhered to the vinyl sheet flooring backing contains asbestos.</p>	<p>Chrysotile/Potentially Friable (sheet flooring)</p> <p>Chrysotile/Non-friable (mastic)</p>	
<p>Vinyl floor tiles, 9"x9", green with white marble, are present.</p>	<p>Chrysotile/Non-friable (tile)</p> <p>Chrysotile/Non-friable (mastic)</p>	
<p>Vinyl floor tiles, 9"x9", green with white streaks, are present.</p>	<p>Chrysotile/Non-friable (tile)</p> <p>Chrysotile/Non-friable (mastic)</p>	

Material and Application	Asbestos Type/Friability	Photo
Vinyl floor tiles, 9"x9", light green with green streaks, are present.	Chrysotile/Non-friable (tile) Chrysotile/Non-friable (mastic)	
Vinyl floor tiles, 9"x9", black and white marble, are present.	Chrysotile/Non-friable (tile) Chrysotile/Non-friable (mastic)	<div>w</div> 
Vinyl floor tiles, 9"x9", burgundy/orange, are present.	Presumed/Non-friable (tile) Presumed/Non-friable (mastic)	

Material and Application	Asbestos Type/Friability	Photo
Vinyl floor tiles, 12"x12", white with black speck, are present.	Chrysotile/Non-friable (tile) Chrysotile/Non-friable (mastic)	
Vinyl floor tiles, 12"x12" pink with dark pink streaks, are present.	Presumed/Non-friable (tile) Presumed/Non-friable (mastic)	
Vinyl floor tiles, 12"x12" white with black, are present.	Presumed/Non-friable (tile) Presumed/Non-friable (mastic)	

Material and Application	Asbestos Type/Friability	Photo
Vinyl floor tiles, 12"x12" pink marble, are present.	Presumed/Non-friable (tile) Presumed/Non-friable (mastic)	
Vinyl floor tiles, 12"x12" grey with light grey fleck, are present.	Presumed/Non-friable (tile) Presumed/Non-friable (mastic)	

Material and Application	Asbestos Type/Friability	Photo
<p>Remaining vinyl floor tiles were presumed to be non-asbestos based on historical knowledge of the date of installation.</p> <p>Mastic underneath new flooring within the original building is presumed to contain asbestos until further sampling proves otherwise.</p>	<p>None (tile)</p> <p>Presumed/Non-friable (mastic)</p>	
<p>Grey caulking is present around windows.</p>	<p>Chrysotile/Non-friable</p>	

Additional notes on the vermiculite discussed above:

- Vermiculite was analyzed when it was detected during a renovation in the Gymnasium (Location 1001). Vermiculite remaining throughout the building is presumed to contain asbestos until further sampling proves otherwise.

4.0 RECOMMENDATIONS

4.1 General

Perform a detailed intrusive assessment prior to building renovation or demolition operations. The assessment should include; destructive testing (i.e. coring and/or removal of building finishes and components), sampling of other hazardous materials (lead, mercury, PCBs, mould, etc.), and materials not tested in this study (i.e. excluded asbestos materials).



4.2 Remedial Work

Remedial work is recommended in the following Locations:

Material, Quantity & Condition	Location Name (Location #)	Recommended Procedure
Pipe Insulation, 1 LF, Poor Condition	Storage Room (Location 15)	Remove in accordance with Type 2 Glove-Bag asbestos abatement procedures
Pipe Insulation, 1 LF, Fair Condition	Custodial Sink Room (Location 1006)	Repair in accordance with Type 2 asbestos procedures

4.3 On-going Management and Maintenance

The following recommendations are made regarding on-going management and maintenance work involving the asbestos materials identified.

4.3.1 Asbestos

Maintain the Asbestos Management Program (AMP).

Perform a reassessment of asbestos materials on an annual basis.

Remove asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work. Follow appropriate asbestos precautions for the classification of work being performed.

Sample presumed ACM prior to alteration or maintenance work if the presumed ACM may be disturbed by the work.

Update the asbestos inventory report upon completion of any abatement and removal of asbestos-containing materials.

5.0 TERMS AND LIMITATIONS

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.



6.0 REFERENCES

The following legislation and documents were referenced in completing the assessment and this report:

1. Asbestos on Construction Projects and in Buildings and Repair Operations, Ontario Regulation 278/05.
2. Designated Substances, Ontario Regulation 490/09.

J:\303000s\0303992.000 HWCDSB,Various2022Projects,ASB,CONS\0303992.004 HWCDSB,AllFacilities,2022,ASB,REASSMT\Deliverables\Elementary\Sts. Peter and Paul\Report\303992.004 Sts. Peter and Paul ACM Reassessment Report HWCDSB Aug 30 2022.docx

Template: Master Report for Asbestos Reassessment, HAZ, April 23, 2019

APPENDIX I
Asbestos Analytical Certificates



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
6-875 Main St West
Suite 200
Hamilton, Ontario L8S 4P9
Project: Sts. Peter and Paul

Attn: Leslie Cantar

Lab Order ID: 51820604
Analysis ID: 51820604_PLM
Date Received: 8/13/2018
Date Reported: 8/22/2018

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
S0029A	Rough plaster, Loc: 11, Boiler Room	None Detected		80% Other 20% Quartz	Gray Non Fibrous Homogeneous
51820604PLM_1					Crushed
S0029B	Rough plaster, Loc: 11, Boiler Room	None Detected		80% Other 20% Quartz	Gray Non Fibrous Homogeneous
51820604PLM_2					Crushed
S0029C	Rough plaster, Loc: 11, Boiler Room	None Detected		80% Other 20% Quartz	Gray Non Fibrous Homogeneous
51820604PLM_3					Crushed
S0030A	Ceiling Tiles (glue-on), 1' X 1' Random Pinhole, Loc: 1009, Corridor	None Detected	60% Fiber Glass 20% Cellulose	20% Other	White, Gray Fibrous Homogeneous
51820604PLM_4					Ashed, Teased
S0030B	Ceiling Tiles (glue-on), 1' X 1' Random Pinhole, Loc: 1009, Corridor	None Detected	60% Fiber Glass 20% Cellulose	20% Other	White, Gray Fibrous Homogeneous
51820604PLM_5					Ashed, Teased
S0030C	Ceiling Tiles (glue-on), 1' X 1' Random Pinhole, Loc: 1009, Corridor	None Detected	60% Fiber Glass 20% Cellulose	20% Other	White, Gray Fibrous Homogeneous
51820604PLM_6					Ashed, Teased
S0031A	Mastic, ceiling tile debris, Loc: 2010, Classroom	None Detected		100% Other	Brown Non Fibrous Homogeneous
51820604PLM_7					Dissolved
S0031B	Mastic, ceiling tile debris, Loc: 2010, Classroom	None Detected		100% Other	Brown Non Fibrous Homogeneous
51820604PLM_8					Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Bethany Nichols (9)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
6-875 Main St West
Suite 200
Hamilton, Ontario L8S 4P9
Project: Sts. Peter and Paul

Attn: Leslie Cantar

Lab Order ID: 51820604
Analysis ID: 51820604_PLM
Date Received: 8/13/2018
Date Reported: 8/22/2018

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
S0031C	Mastic, ceiling tile debris, Loc: 2010, Classroom	None Detected		100% Other	Brown Non Fibrous Homogeneous
51820604PLM_9					Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Bethany Nichols (9)

Analyst

Approved Signatory

51820604

Version 1-15-2012

Client: Pinchin Ltd.
Contact: Leslie Cantar
Address: 6-875 Main St W, Hamilton, ON
Phone: 289.237.4294
Fax: 905.577.6207
Email: lcantar@pinchin.com

Project: Sts. Peter and Paul
 Stop positive on all samples.

Client Notes:

P.O. #: 224334 (Sts. Peter and Paul)
Date Submitted: 7/20/2018 0:00

Analysis: PLM BULK EPA 600
TurnAroundTime: 6+ days

***Instructions:**

Use Column "B" for your contact info

To See an Example Click the
bottom Example Tab.

48

**Begin Samples with a "<<" above the first sample
 and end with a ">>" below the last sample.
 Only Enter your data on the first sheet "Sheet1"**

*Note: Data 1 and Data 2 are optional
 fields that do not show up on the official
 report, however they will be included
 in the electronic data returned to you
 to facilitate your reintegration of the report data.*

Scientific
 Analytical
 Institute



**4604 Dundas Dr.
 Greensboro, NC 27407
 Phone: 336.292.3888
 Fax: 336.292.3313
 Email: lab@sailab.com**

Sample Number	Data 1 (Lab use only)	Sample Description	Data 2 (Lab use only)
<<			
S0029A		Rough plaster, Loc:11, Boiler Room	
S0029B		Rough plaster, Loc:11, Boiler Room	
S0029C		Rough plaster, Loc:11, Boiler Room	
S0030A		Ceiling Tiles (glue-on), 1' X 1' Random Pinhole, Loc:1009, Corridor	
S0030B		Ceiling Tiles (glue-on), 1' X 1' Random Pinhole, Loc:1009, Corridor	
S0030C		Ceiling Tiles (glue-on), 1' X 1' Random Pinhole, Loc:1009, Corridor	
S0031A		Mastic, ceiling tile debris, Loc:2010, Classroom	
S0031B		Mastic, ceiling tile debris, Loc:2010, Classroom	
S0031C		Mastic, ceiling tile debris, Loc:2010, Classroom	
>>			

Accepted ☒Rejected ☐

L. Hamilton

8/13/18

10:30am



Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project Name: Hamilton-Wentworth Catholic School Board, WO #031623
49 Fennell East, Hamilton, ON
Project No.: 0230747.000
Prepared For: M. Maiorana / R. Bertin-Fenney

Lab Reference No.: b199814
Analyst(s): T. Ly

Date Received: November 1, 2018
Date Analyzed: November 8, 2018
Samples submitted: 3
Phases analyzed: 7

Method of Analysis:

EPA 600/R-93/116 - Method for the Determination of Asbestos in Bulk Building Materials dated July, 1993

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold (see chart below) indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

Provincial Jurisdiction	Regulatory Threshold	Provincial Jurisdiction	Regulatory Threshold
Ontario, British Columbia, Nova Scotia	0.5%	Alberta	Undefined
Quebec	0.1%	Saskatchewan	0.5% friable 1% non-friable
PEI, NWT, Yukon, Nunavut, Newfoundland and Labrador, and New Brunswick	1%	Manitoba	0.1% friable 1% non-friable

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

Pinchin Ltd. is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA-600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2005.

This report relates only to the items tested.

NOTE: *This test report may not be reproduced, except in full, without the written approval of the laboratory. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. This report is valid only when signed in blue ink by the analyst. Vinyl asbestos floor tiles contain very fine fibres of asbestos and may be missed by some laboratories using the PLM method. Internal verification studies performed by Pinchin indicate that the chance of missing asbestos in floor tiles is no higher than about 2%. The vinyl tile study and laboratory documentation on measurement uncertainty is available upon request. The analysis of dust samples by PLM cannot be used as an indicator of past or present airborne asbestos fibre levels.*



Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project Name: Hamilton-Wentworth Catholic School Board, WO #031623
49 Fennell East, Hamilton, ON
Project No.: 0230747.000
Prepared For: M. Maiorana / R. Bertin-Fenney
Lab Reference No.: b199814
Date Analyzed: November 8, 2018

BULK SAMPLE ANALYSIS

SAMPLE IDENTIFICATION	SAMPLE DESCRIPTION	% COMPOSITION (VISUAL ESTIMATE)	
		ASBESTOS	OTHER
0032A Smooth plaster ceiling on metal lath, Classroom 16, Location 2005	2 Phases: a) Homogeneous, grey, hard, cementitious, plaster base coat.	None Detected	Non-Fibrous Material > 75%
	b) Homogeneous, white, hard, cementitious, plaster top coat.	None Detected	Non-Fibrous Material > 75%
0032B Smooth plaster ceiling on metal lath, Classroom 16, Location 2005	2 Phases: a) Homogeneous, grey, granular, cementitious material.	None Detected	Non-Fibrous Material > 75%
	b) Homogeneous, white, hard, cementitious material.	None Detected	Non-Fibrous Material > 75%
0032C Smooth plaster wall on metal lath, Classroom 16, Location 2005	3 Phases: a) Homogeneous, grey, granular, cementitious material.	None Detected	Non-Fibrous Material > 75%
	b) Homogeneous, white, hard, cementitious material.	None Detected	Non-Fibrous Material > 75%
	c) Non-homogeneous, off-white, hard, cementitious material.	Chrysotile 0.5-5%	Non-Fibrous Material > 75%
Comments:	Phase b) is small in size. Drywall is present on the surface of this sample.		

Reviewed by:

Reporting Analyst:

Special Instructions:

Approved by: [Signature]
Used by: [Signature]
Released by: [Signature]

Pinchin Ltd. - Asbestos Laboratory
Internal Asbestos Bulk Sample Chain of Custody

Client Name:	Hamilton-Wentworth Catholic School Board	Project Address:	49 Fennell East, Hamilton, ON
Portfolio/Building No:	WO #031623	Pinchin File:	230747 (WO: 031623)
Submitted by:	Michael Maiorana	Email:	mmaiorana@pinchin.com
CC Results to:	Robert Bertin-Fenney	CC Email:	rbertin-fenney@pinchin.com
Invoice to:	Accounts Payable	Invoice Email:	ap@pinchin.com
Date Submitted:	October 31 2018	Required by:	November 7 2018
# of Samples:	3	Priority:	5 Day Turnaround
Year of Building Construction (Mandatory Field):	1948		
Do NOT Stop on Positive (Sample Numbers):			
Pinchin Group Company (Mandatory Field):	Select		

To be Completed by Lab Personnel Only:

Lab Reference #:	6199814	Time:	24 hour clock		
Received by:	NOV 01 2018 [Signature]	Date:	Month	Day	Year
Name(s) of Analyst(s):	[Signature]		11	8	18

Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)
	0032	A	Smooth plaster ceiling on metal lath, Classroom 16, Location 2005 a)ND b)ND
	0032	B	Smooth plaster ceiling on metal lath, Classroom 16, Location 2005 a)ND b)ND
	0032	C	Smooth plaster wall on metal lath, Classroom 16, Location 2005 a)ND b)ND c)CH-O-S-S /



Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project Name: Hamilton-Wentworth Catholic School Board, Sts. Peter and Paul Catholic Elementary School, 49 Fennell Avenue East, Hamilton, ON
Project No.: 0230748.000
Prepared For: E. Balfour / M. Maiorana

Lab Reference No.: b215629
Analyst(s): T. Lam / K. Cockburn

Date Received: August 8, 2019
Date Analyzed: August 14, 2019
Samples submitted: 3
Phases analyzed: 3

Method of Analysis:

EPA 600/R-93/116 - Method for the Determination of Asbestos in Bulk Building Materials dated July, 1993

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold (see chart below) indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

Provincial Jurisdiction	Regulatory Threshold	Provincial Jurisdiction	Regulatory Threshold
Ontario, British Columbia, Nova Scotia	0.5%	Alberta	Undefined
Quebec	0.1%	Saskatchewan	0.5% friable 1% non-friable
PEI, NWT, Yukon, Nunavut, Newfoundland and Labrador, and New Brunswick	1%	Manitoba	0.1% friable 1% non-friable

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA-600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2005.

This report relates only to the items tested.

NOTE: *This test report may not be reproduced, except in full, without the written approval of the laboratory. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. This report is valid only when signed in blue ink by the analyst. Vinyl asbestos floor tiles contain very fine fibres of asbestos and may be missed by some laboratories using the PLM method. Internal verification studies performed by Pinchin indicate that the chance of missing asbestos in floor tiles is no higher than about 2%. The vinyl tile study and laboratory documentation on measurement uncertainty is available upon request. The analysis of dust samples by PLM cannot be used as an indicator of past or present airborne asbestos fibre levels.*



Pinchin Ltd. Asbestos Laboratory
Certificate of Analysis

Project Name: Hamilton-Wentworth Catholic School Board, Sts. Peter and Paul Catholic Elementary School, 49 Fennell Avenue East, Hamilton, ON

Project No.: 0230748.000

Prepared For: E. Balfour / M. Maiorana

Lab Reference No.: b215629

Date Analyzed: August 14, 2019

BULK SAMPLE ANALYSIS

SAMPLE IDENTIFICATION	SAMPLE DESCRIPTION	% COMPOSITION (VISUAL ESTIMATE)	
		ASBESTOS	OTHER
S0035A Vermiculite, Gymnasium, Location 1001	Homogeneous, blonde and black, loose particulate, micaceous material.	None Detected	Vermiculite > 75% Tar 0.5-5% Other Non-Fibrous 0.5-5%
Comments:	Man-made vitreous fibres and cellulose are present on the surface of this sample. This sample is consistent in analysis and visual appearance with vermiculite produced in South Africa which is known to not contain naturally occurring asbestos fibres.		
S0035B Vermiculite, Gymnasium, Location 1001	Homogeneous, blonde and black, loose particulate, micaceous material.	None Detected	Vermiculite > 75% Tar 0.5-5% Other Non-Fibrous 0.5-5%
Comments:	Cellulose is present on the surface of this sample. This sample is consistent in analysis and visual appearance with vermiculite produced in South Africa which is known to not contain naturally occurring asbestos fibres.		
S0035C Vermiculite, Gymnasium, Location 1001	Homogeneous, blonde and black, loose particulate, micaceous material.	None Detected	Vermiculite > 75% Tar 0.5-5% Other Non-Fibrous 0.5-5%
Comments:	Cellulose is present on the surface of this sample. This sample is consistent in analysis and visual appearance with vermiculite produced in South Africa which is known to not contain naturally occurring asbestos fibres.		

Reviewed by:

Reporting Analyst:

Analyzed by: TTL
Reviewed by: [Signature]
Report Sent by: [Signature]

Instructions:

**Pinchin Ltd. - Asbestos Laboratory
Internal Asbestos Bulk Sample Chain of Custody**

Client Name:	Hamilton-Wentworth Catholic School Board	Project Address:	49 Fennell Avenue East, Hamilton, ON
Portfolio/Building No:	Sts. Peter and Paul Catholic Elementary School	Pinchin File:	230748
Submitted by:	Emily Balfour	Email:	ebalfour@pinchin.com
CC Results to:	Michael Maiorana	CC Email:	mmaiorana@pinchin.com
Invoice to:	Accounts Payable	Invoice Email:	ap@pinchin.com
Date Submitted:	August 7 2019	Required by:	August 14 2019
# of Samples:	3	Priority:	5 Day Turnaround
Year of Building Construction (Mandatory Field):	1948		
Do NOT Stop on Positive (Sample Numbers):			
Pinchin Group Company (Mandatory Field):	Pinchin		

To be Completed by Lab Personnel Only:

Lab Reference #:	6215629		Time:	24 hour clock		
Received by:	AUG 14 2019 [Signature]		Date:	Month	Day	Year
Name(s) of Analyst(s):	TTL/KC		August 14 2019			
Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)			
	S0035	A	Vermiculite, Gymnasium, Location 1001 ND			
	S0035	B	Vermiculite, Gymnasium, Location 1001 ND			
	S0035	C	Vermiculite, Gymnasium, Location 1001 ND			



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
6-875 Main St West
Suite 200
Hamilton, Ontario L8S 4P9

Attn: Emily Balfour
Michael Maiorana

Lab Order ID: 71921035
Analysis ID: 71921035_PLM
Date Received: 8/9/2019
Date Reported: 8/19/2019
Date Amended: 9/9/2019

Project: 230748,49 Fennell Avenue East, Hamilton, ON, Hamilton-Wentworth Catholic School Board, Sts. Peter and Paul Catholic Elementary School

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
S0033A	Drywall joint compound on bulkhead, Common Room, Location 6	None Detected		100% Other	White Non Fibrous Homogeneous
71921035PLM_1					Crushed
S0033B	Drywall joint compound on bulkhead, Common Room, Location 6	None Detected		100% Other	White Non Fibrous Homogeneous
71921035PLM_2					Crushed
S0033C	Drywall joint compound on bulkhead, Common Room, Location 6	None Detected		100% Other	White Non Fibrous Homogeneous
71921035PLM_3					Crushed
S0034A	Drywall joint compound on wall, Girl's Changeroom, Location 1004	None Detected		100% Other	White Non Fibrous Homogeneous
71921035PLM_4					Crushed
S0034B	Drywall joint compound on wall, Girl's Changeroom, Location 1004	None Detected		100% Other	White Non Fibrous Homogeneous
71921035PLM_5					Crushed
S0034C	Drywall joint compound on wall, Girl's Changeroom, Location 1004	None Detected		100% Other	White Non Fibrous Homogeneous
71921035PLM_6					Crushed
S0036A	Drywall joint compound on wall, Classroom, Location 2016	None Detected		100% Other	White Non Fibrous Homogeneous
71921035PLM_7					Crushed
S0036B	Drywall joint compound on wall, Classroom, Location 2016	None Detected		100% Other	White Non Fibrous Homogeneous
71921035PLM_8					Crushed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Bobby Wheatley (9)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
6-875 Main St West
Suite 200
Hamilton, Ontario L8S 4P9

Attn: Emily Balfour
Michael Maiorana

Project: 230748,49 Fennell Avenue East, Hamilton, ON, Hamilton-Wentworth Catholic School
Board, Sts. Peter and Paul Catholic Elementary School

Lab Order ID: 71921035
Analysis ID: 71921035_PLM
Date Received: 8/9/2019
Date Reported: 8/19/2019
Date Amended: 9/9/2019

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
S0036C	Drywall joint compound on wall, Classroom, Location 2016	None Detected		100% Other	White Non Fibrous Homogeneous
71921035PLM_9					Crushed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.


Bobby Wheatley (9)

Analyst

Approved Signatory

71921035

Version 1-15-2012

Client: Contact: Address: Phone: Fax: Email:	Pinchin Ltd. Emily Balfour 6-875 Main Street West, Suite 200, Hamilton ON L8S 4P9 905-577-6206 905-577-6207 ebalfour@pinchin.com mmaiorana@pinchin.com 230748, 49 Fennell Avenue East, Hamilton, ON, Hamilton-Wentworth Catholic School Board, Sts. Peter and Paul Catholic Elementary School	*Instructions: Use Column "B" for your contact info To See an Example Click the bottom Example Tab. Enter samples between "<<" and ">>"	Invoice to: ap@pinchin.com
Project: Client Notes: P.O. #. Date Submitted: Analysis: TurnAroundTime:	230748 August 8, 2019 PLM - Stop Positive 4days	Begin Samples with a "<<" above the first sample and end with a ">>" below the last sample. Only Enter your data on the first sheet "Sheet1" Note: Data 1 and Data 2 are optional fields that do not show up on the official report, however they will be included in the electronic data returned to you to facilitate your reintegration of the report data.	 Scientific Analytical Institute 4604 Dundas Dr. Greensboro, NC 27407 Phone: 336.292.3888 Fax: 336.292.3313 Email: lab@sailab.com

Sample Number	Data 1 (Lab use only)	Sample Description	Data 2 (Lab use only)
<<			
S0032A		Drywall joint compound on bulkhead, Common Room, Location 6	
S0032B		Drywall joint compound on bulkhead, Common Room, Location 6	
S0032C		Drywall joint compound on bulkhead, Common Room, Location 6	
S0033A		Drywall joint compound on wall, Girl's Changeroom, Location 1004	
S0033B		Drywall joint compound on wall, Girl's Changeroom, Location 1004	
S0033C		Drywall joint compound on wall, Girl's Changeroom, Location 1004	
S0034A		Drywall joint compound on wall, Classroom, Location 2016	
S0034B		Drywall joint compound on wall, Classroom, Location 2016	
S0034C		Drywall joint compound on wall, Classroom, Location 2016	
>>			

Accepted ☒Rejected ☐
 J. Jimenez 8-9
 10:30A



Pinchin Ltd. Asbestos Laboratory *Certificate of Analysis*

Project Name:	Hamilton-Wentworth Catholic School Board, Sts. Peter and Paul Catholic Elementary School, 49 Fennell Avenue East, Hamilton, ON		
Project No.:	0272113.000		
Prepared For:	E. Balfour / M. Maiorana		
Lab Reference No.:	b230670	Date Received:	May 21, 2020
Analyst(s):	K. Cockburn	Date Analyzed:	May 28, 2020
		# Samples submitted:	3
		# Phases analyzed:	3

Method of Analysis:

EPA 600/R-93/116 - Method for the Determination of Asbestos in Bulk Building Materials dated July, 1993

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold (see chart below) indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2005.

This report relates only to the items tested.

NOTE: *This test report may not be reproduced, except in full, without the written approval of the laboratory. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. This report is valid only when signed in blue ink by the analyst. Vinyl asbestos floor tiles contain very fine fibres of asbestos and may be missed by some laboratories using the PLM method. Internal verification studies performed by Pinchin indicate that the chance of missing asbestos in floor tiles is no higher than about 2%. The vinyl tile study and laboratory documentation on measurement uncertainty is available upon request. The analysis of dust samples by PLM cannot be used as an indicator of past or present airborne asbestos fibre levels.*



Pinchin Ltd. Asbestos Laboratory
Certificate of Analysis

Project Name: Hamilton-Wentworth Catholic School Board,
Sts. Peter and Paul Catholic Elementary School,
49 Fennell Avenue East, Hamilton, ON

Project No.: 0272113.000
Prepared For: E. Balfour / M. Maiorana

Lab Reference No.: b230670
Date Analyzed: May 28, 2020

BULK SAMPLE ANALYSIS

SAMPLE IDENTIFICATION	SAMPLE DESCRIPTION	% COMPOSITION (VISUAL ESTIMATE)	
		ASBESTOS	OTHER
S0037A Sweatwrap, Storage, Location 5	Homogeneous, beige, layered, sweatwrap insulation.	None Detected	Cellulose > 75% Synthetic Fibres 0.5-5% Hair 5-10% Non-Fibrous Material 0.5-5%
Comments:	Cotton fabric reinforcement is present on the surface of this sample.		
S0037B Sweatwrap, Storage, Location 5	Homogeneous, beige, layered, sweatwrap insulation.	None Detected	Cellulose > 75% Synthetic Fibres 0.5-5% Hair 5-10% Non-Fibrous Material 0.5-5%
Comments:	Cotton fabric reinforcement is present on the surface of this sample.		
S0037C Sweatwrap, Storage, Location 5	Homogeneous, beige, layered, sweatwrap insulation.	None Detected	Cellulose > 75% Synthetic Fibres 0.5-5% Hair 5-10% Non-Fibrous Material 0.5-5%
Comments:	Cotton fabric reinforcement is present on the surface of this sample.		

Reviewed by:

Reporting Analyst:



Analysed by: *XC*
Reviewed by: *KB*
Reported by: *19*

Instructions:

**Pinchin Ltd. - Asbestos Laboratory
Internal Asbestos Bulk Sample Chain of Custody**

Client Name:	Hamilton-Wentworth Catholic School Board	Project Address:	49 Fennell Avenue East, Hamilton, ON
Portfolio/Building No:	Sts. Peter and Paul Catholic Elementary School	Pinchin File:	272113
Submitted by:	Emily Balfour	Email:	ebalfour@pinchin.com
CC Results to:	Michael Majorana	CC Email:	mmaiorana@pinchin.com
Invoice to:	Accounts Payable	Invoice Email:	ap@pinchin.com
Date Submitted:	May 19 2020	Required by:	May 19 2020
# of Samples:	3	Priority:	5 Day Turnaround
Year of Building Construction (Mandatory Field):	1948		
Do NOT Stop on Positive (Sample Numbers):			
Pinchin Group Company (Mandatory Field):	Pinchin		

To be Completed by Lab Personnel Only:			
Lab Reference #:	0230670 <i>cu</i>	Time:	24 hour clock
Received by:	MAY 21 2020	Date:	Month Day Year
Name(s) of Analyst(s):	<i>XC 2020/05/28</i>		
Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)
	S0037	A	Sweatwrap, Storage, Location 5 <i>ND</i>
	S0037	B	Sweatwrap, Storage, Location 5 <i>ND</i>
	S0037	C	Sweatwrap, Storage, Location 5 <i>ND</i>

APPENDIX II
Location List

Client: Hamilton-Wentworth Catholic District Sch
Building Name: Sts. Peter and Paul
Survey Date: 2018-08-16

Site: 49 Fennell Avenue East, Hamilton, ON
Last Re-Assessment: 2022-06-28

Location No.	Name or Description	Area ft ²	Floor No.	Bldg. Phase	Notes
0	Presumed Asbestos-Containing Materials	0		A	
1	Library	0	B	A	
2	Library Office	0	B	A	
3	Corridor	0	B	A	
4	Custodian Room	0	B	A	
5	Storage	0	B	A	
6	Common Room	0	B	A	
7	Storage	0	B	A	
8	Electrical	0	B	A	
9	Corridor	0	B	A	
10	Staff Washroom	0	B	A	
11	Boiler Room	0	B	A	
12	Storage Space	0	B	A	
13	Foyer	0	B	A	
14	Staff Washroom	0	B	A	
15	Storage	0	B	A	
16	Electrical	0	B	A	
1001	Gymnasium	0	1	A	
1002	Gymnasium Storage	0	1	A	
1003	Boys Changeroom	0	1	A	
1004	Girls Changeroom	0	1	A	
1005	Special Education	0	1	A	
1006	Custodian Sink Room	0	1	A	
1007	Corridor	0	1	A	
1008	Corridor	0	1	A	
1009	Corridor	0	1	A	
1010	Classroom	0	1	A	
1011	Classroom	0	1	A	
1012	Classroom	0	1	A	
1013	Classroom	0	1	A	
1014	Stairwell	0	1	A	
1015	Classroom	0	1	A	
1016	Classroom	0	1	A	
1017	Classroom	0	1	A	
1018	Storage	0	1	A	
1019	Girls Washroom	0	1	A	
1020	Boys Washroom	0	1	A	
1021	Vestibule	0	1	A	
1022	Classroom	0	1	A	
1023	Coat Room	0	1	A	
1024	Sink Room	0	1	A	
1025	Classroom	0	1	A	
1026	Classroom	0	1	A	
1027	Vestibule/Stairwell	0	1	A	
1028	Office	0	1	A	
1029	Office	0	1	A	
1030	Principals Office	0	1	A	
1031	Stairwell	0	1	A	
1032	Accessible Washroom	0	1	A	
1033	Washroom	0	1	A	
1034	Special Education Office	0	1	A	
2001	Staff Washroom	0	2	A	
2002	Staff Storage	0	2	A	
2003	Staff Room	0	2	A	
2004	Corridor	0	2	A	
2005	Classroom	0	2	A	
2006	Classroom	0	2	A	
2007	Boys Washroom	0	2	A	
2008	Classroom	0	2	A	
2009	Girls Washroom	0	2	A	
2010	Classroom	0	2	A	
2011	Classroom	0	2	A	

Location No.	Name or Description	Area ft ²	Floor No.	Bldg. Phase	Notes
2012	Classroom	0	2	A	
2013	Classroom	0	2	A	
2014	Classroom	0	2	A	
2015	Classroom	0	2	A	
2016	Classroom	0	2	A	
2017	Upper Office	0	2	A	
2018	Corridor	0	2	A	

APPENDIX III

Hazardous Materials Summary / Sample Log Report

Client: Hamilton-Wentworth Catholic District Sch

Site: 49 Fennell Avenue East, Hamilton, ON

Building Name: Sts. Peter and Paul

Survey Date: 2018-08-16

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	S0001	Wall Vermiculite/concrete Block Walls	1002	A	0	0	0	100	None Detected	No	
Asbestos	S0002	Piping Mastic	1002	A	0	0	0	100	None Detected	No	
Asbestos	S0003	Ceiling Ceiling Tiles (lay-in) 2' X 4' Random Pinhole	1004,1006,1007,2002	A	0	0	0	100	None Detected	No	
Asbestos	S0004	Floor Vinyl Floor Tile (no Mastic) 12" X 12" Beige Marble	10	A	0	0	0	100	None Detected	No	
Asbestos	S0005 A	Floor Vinyl Floor Tile And Mastic 9" X 9" Black And White Marble	1013,1015,1026,2005,2006	A	0	0	0	100	Chrysotile	Yes	NF
Asbestos	S0006	Floor Mastic 9" X 9" Green With White Streak	1016,1018,2014	A	0	0	0	100	Chrysotile	Yes	NF
Asbestos	S0007 A	Floor Vinyl Floor Tile And Mastic 9" X 9" Green With White Marble	1013	A	0	0	0	100	Chrysotile	Yes	NF
Asbestos	S0008	Floor Vinyl Floor Tile And Mastic 12" X 12" Brown With White Streaks	14	A	0	0	0	100	None Detected	No	
Asbestos	S0009	Floor Mastic 12" X 12" Beige With White Streaks	9	A	0	0	0	100	Chrysotile	Yes	NF
Asbestos	S0010	Ceiling Ceiling Tiles (lay-in) 2' X 4' Short Fissure And Random Pinhole	1,2,3,6,9,13,1003,1006,1007,1008,1009,1018,1021,1027,1028,1029,1030,1032,2004,2018	A	0	0	0	100	None Detected	No	
Asbestos	S0011	Ceiling Ceiling Tiles (lay-in) 2' X 4' Long Fissure And Random Pinhole	1,1005	A	0	0	0	100	None Detected	No	
Asbestos	S0012	Wall Drywall And Joint Compound	1007	A	0	0	0	100	None Detected	No	
Asbestos	S0013	Floor Vinyl Floor Tile And Mastic 9" X 9" Light Green With Green Streaks	1033	A	0	0	0	0	Chrysotile	Yes	NF
Asbestos	S0014	Floor Vinyl Floor Tile And Mastic 12" X 12" White With Black Streaks	1010,1011	A	0	0	0	100	Chrysotile	Yes	NF
Asbestos	S0015 ABC	Ceiling, Wall, Ceiling, Wall Bulkhead Drywall And Joint Compound	7,10,14,1010,1011,1012	A	0	0	0	100	None Detected	No	
Asbestos	S0016 ABC	Other Window Caulking Brown On Interior Windows	1010,1011,1012	A	0	0	0	100	None Detected	No	
Asbestos	S0017	Other Window Caulking, Grey Grey, Interior Windows	1013	A	0	0	0	100	None Detected	No	
Asbestos	S0018	Ceiling Plaster Plaster Texture Coat	1003	A	0	0	0	100	None Detected	No	
Asbestos	S0019	Other Window Caulking Caulking, Mte Sampled August 13, 2013.	0	A	0	0	0	100	Chrysotile	Yes	NF
Asbestos	S0020 ABCDG	Wall, Ceiling, Wall Bulkhead Plaster	1,2,3,4,5,6,7,8,9,1001,1007,1008,1009,1010,1011,1012,1013,1014,1015,1016,1017,1018,1019,1020,1021,1022,1023,1024,1025,1026,1027,1028,1029,1030,1031,1033,2001,2002,2003,2004,2005	A	0	0	0	100	None Detected	No	

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
			2006,2007,2008,2009,2010,2011,2012,2013,2014 2017,2018								
Asbestos	S0022 C	Piping Parging Cement	5,6,15,1002,1004,1006,1012,1013,1015,1016,1017 1018,1022,1023,1025,1026,2005,2006,2008,2010 2013	A	0	15	94	2	Chrysotile	Yes	F
Asbestos	S0023	Floor Mastic 12" X 12" White With Grey - March 17, 2014	1005,1034	A	0	0	0	100	Chrysotile	Yes	NF
Asbestos	S0024	Other Window Caulking Black Window Caulking - March 17, 2014	1031	A	0	0	0	100	None Detected	No	
Asbestos	S0025	Floor Vinyl Floor Tile And Mastic 12" X 12" Beige With Multi Flecks	1031	A	0	0	0	100	None Detected	No	
Asbestos	S0026	Floor Vinyl Sheet Flooring Brown Pebble Pattern	2003	A	0	0	0	100	Chrysotile	Yes	PF, NF
Asbestos	S0027	Other Window Caulking, Grey Grey, Windows - March 17, 2014	1005,1034	A	0	0	0	100	Chrysotile	Yes	NF
Asbestos	S0028	Ceiling Ceiling Tiles (glue-on) 1' X 1' Pinhole (march 17, 2014)	1008,1012,1016,1017,2010,2014	A	0	0	0	100	None Detected	No	
Asbestos	S0029	Wall, Ceiling Plaster	11	A	0	0	0	100	None Detected	No	
Asbestos	S0030	Ceiling Ceiling Tiles (glue-on)	1009	A	0	400	0	0	None Detected	No	
Asbestos	S0031	Other Debris Mastic Brown Ceiling Tile Mastic	2010,2011	A	0	20	0	0	None Detected	No	
Asbestos	S0032 C	Ceiling Drywall And Joint Compound	2005	A	0	0	0	100	Chrysotile	Yes	NF
Asbestos	S0033 ABC	Ceiling Bulkhead Drywall And Joint Compound	6	A	0	0	0	100	None Detected	No	
Asbestos	S0034 ABC	Wall Drywall And Joint Compound	1004,1005,1034	A	0	0	0	100	None Detected	No	
Asbestos	S0035 ABC	Wall Vermiculite/concrete Block Walls	1001	A	0	0	0	0	None Detected	No	
Asbestos	S0036 ABC	Wall Drywall And Joint Compound	2016	A	0	0	0	100	None Detected	No	
Asbestos	S0037	Piping Cold Water Return Sweatwrap	5	A	100	0	0	0	None Detected	No	
Asbestos	V9500	Floor Adhesive/mastic Vinyl Baseboards	0	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Floor Floor Levelling Compound	0	A	0	0	0	100	Presumed Asbestos	Yes	F
Asbestos	V9500	Floor Mastic	10,1017,1023,1024,1032,2010,2011,2013,2015 2016	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Floor Vinyl Floor Tile (no Mastic) 12x12 Pink Marble, 12x12 White And Black, 12x12 White With Black, 12x12 Pink Marble, 9x9 Green With White	1024,1032,2013,2015,2016	A	0	0	0	100	Presumed Asbestos	Yes	NF

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	V9500	Floor Vinyl Floor Tile And Mastic 12" X 12" White With Black Flecks Only, 12x12 Grey With Light Grey Fleck, 9 X9 Beige And Red, 9" X 9" Orange, 9x9 Burgundy	1022,1023,1034,2017	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Door Caulking	0	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Electrical Equipment Cement Product	0	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Sink Mastic, Gold	0	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Roof Roofing Material	0	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Electrical Wire Textile	0	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Wall Vermiculite/concrete Block Walls	0	A	0	0	0	100	Presumed Asbestos	Yes	F
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2' X 4' Pinhole And Flecks (2012)	2	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2' X 4' Smooth (gypsum Board)	10	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2x4 Drywall	2007	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2x4 Pinhole Long	1034	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2x4 Smooth (gypsum Board)	1019,1020,1033	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) Gypsum	1012	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceramic Tiles	4	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling Concrete (poured)	12	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling Drywall (no Compound)	14,2009	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Ceramic Tiles	4,1007,1008,1009,1010,1011,1012,1019,1020,1028 1029,1030,2001,2007,2009	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Concrete (poured)	8,11,12,15	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Laminate	2	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Laminate Wood	13	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Mastic	2005,2006,2012	A	0	0	0	100	Non Asbestos	No	

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	V0000	Floor Terrazzo	4,5,6,7,9,1003,1004,1006,1007,1011,1012,1014 1021,1027,1031,2002,2004,2015,2018	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile (no Mastic) 12x12 White With Grey	1005	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic 12 Grey Flecks	1025	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic 12x12 Beige Flecks	2008	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic 12x12 Beige With Grey Fleck (installed 2018)	1001,1002	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Piping Fibreglass	3,4,5,6,9,11,1002,1004,1005,1006,1007,1008 1009,1012,1013,1015,1016,1017,1018,1022,1023 1025,1026,1028,1029,1030,1032,1033,2005,2006 2008,2010,2011,2012,2013,2014,2018	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Piping Metal	6	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Piping Not Insulated	12	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Structure Concrete (poured)	15,1002,1004,1010,1011,2015	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Structure Concrete (precast)	2003,2016	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Structure Deck Steel	1001	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Wall Ceramic Tiles	4,10,14,1019,1020,2007,2009	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Wall Concrete (poured)	8,11,12,13,15,1001,1002,2015,2016	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Wall Masonry	1003,1004,1005,1006,1010,1011,1012,1021,1032 1034	A	0	0	0	100	Non Asbestos	No	

Legend:

Sample number	
S####	Asbestos sample collected
L####	Paint sample collected
P####	PCB sample collected
M####	Mould sample collected
V####	Material visually similar to numbered sample collected
V0000	Known non Hazardous Material
V9000	Material is visually identified as Hazardous Material
V9500	Material is presumed to be Hazardous Material
[Loc. No.]	Abated Material

Units	
SF	Square feet
LF	Linear feet
EA	Each
%	Percentage

NF	Non Friable material.
F	Friable material
PF	Potentially Friable material

APPENDIX IV
All Data Report

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #0 : Presumed Asbestos-Containing Materials
Survey Date: 2018-08-16

Site: Elementary
Floor:

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Adhesive/mastic, vinyl baseboards			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Floor Levelling Compound			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F
Other	Door	Caulking			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Electrical Equipment	Cement Product			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Electrical Wire	Textile			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Roof	Roofing material			B	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Sink	Mastic, Gold			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Window	Caulking			A	Y		100(7)			%	S0019	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall		Vermiculite/concrete block walls			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1 : Library
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2' x 4' pinhole and flecks			C	Y		100			%	V0010	None Detected		None	
Ceiling		Ceiling Tiles (lay-in), 2' x 4' pinhole and long fissures			C	Y		100			%	V0011	None Detected		None	
Floor		Laminate			A	Y										
Piping		Fibreglass			C	N										
Piping		Fibreglass			A	Y										
Piping	Rain Water Leader	Metal		Not Insulated	A	Y										
Wall		Concrete (poured)			A	Y										
Wall		Plaster			B	Y		100			%	V0020	None Detected		None	
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #2 : Library Office
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			A	Y		100			%	V0010	None Detected		None	
Ceiling		Ceiling Tiles (lay-in), 2' x 4' pinhole and flecks (2012)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Laminate			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			A	Y										
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #3 : Corridor
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2' x 4' short fissure random pinhole			C	Y		100			%	S0010	None Detected		None	
Floor		Terrazzo			A	Y		100			%					
Piping		Fibreglass			C	N		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	S0020G	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #4 : Custodian Room
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			A	Y		100			%	V0020	None Detected		None	
Ceiling		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			A	Y		4			%	V0022	[None]	50-75%	[Abated]	
Piping		Parging Cement			C	Y		7			%	V0022	[None]	50-75%	[Abated]	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	
Wall		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #5 : Storage
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			A	Y		100			%	V0020	None Detected		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			C	Y		10(7)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Piping	Cold Water Return	Sweatwrap			A	Y		100			LF	S0037	None Detected	N.D.	None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #6 : Common Room
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0010	None Detected		None	
Ceiling		Plaster			A	Y		100			%	V0020	None Detected		None	
Ceiling	Bulkhead	Drywall and joint compound			C	Y		100			%	S0033ABC	None Detected	N.D.	None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Metal		Not Insulated	A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	N		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			C	Y		2(7)			%	S0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #7 : Storage
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0015	None Detected		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	Y										
Piping		Horsehair			C	N										
Wall		Concrete (poured)			A	Y										
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #8 : Electrical
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Concrete (poured)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (poured)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #9 : Corridor
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			A	Y		100			%	V0010	None Detected		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Laminate			A	Y										
Floor		Mastic			D	N		100(7)			%	S0009	Chrysotile	5-10%	Confirmed Asbestos	NF
Floor		Abated Material			A	Y									[Abated]	
Piping		Fibreglass			C	N		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #10 : Staff Washroom
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2' x 4' smooth (gypsum board)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 beige marble			A	Y		100			%	S0004	None Detected		None	
Piping		Fibreglass			C	Y										
Wall		Drywall and joint compound			A	Y		100			%	V0015	None Detected		None	
Wall		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #11 : Boiler Room
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0029	None Detected	N.D.	None	
Floor		Concrete (poured)			B	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass		Polyvinyl chloride (PVC)	B	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (poured)			B	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			B	Y		100			%	S0029	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #12 : Storage Space
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (poured)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Concrete (poured)			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Not Insulated			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (poured)			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #13 : Foyer
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			A	Y		100			%	V0010	None Detected		None	
Floor		Laminate, wood			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (poured)			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #14 : Staff Washroom
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall (no compound)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, 12x12 beige marble			A	Y		100			%	S0008	None Detected	N.D.	None	
Piping		Fibreglass			C	Y										
Wall		Drywall and joint compound			A	Y		100			%	V0015	None Detected		None	
Wall		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #15 : Storage
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Concrete (poured)			B	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			B	Y		1(7)		1(3)	EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Structure		Concrete (poured)			B	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (poured)			B	Y		100			%	V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #16 : Electrical
Survey Date: 2018-08-16

Site: Elementary
Floor: B

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Concrete (poured)			B	Y										
Structure		Concrete (poured)			C	Y										
Wall		Plaster			B	Y		100			%					
Wall		Masonry			B	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1001 : Gymnasium
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Bulkhead	Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 12x12 beige with grey fleck (installed 2018)			A	Y						V0000	Non-Asbestos		None	
Floor		Abated Material, 12x12 white with grey			A	Y		100			%	V0023	[None]	0.5-5%	[Abated]	
Floor		Abated Material, 12x12 beige with white streak			A	Y		100			%	V0009	[None]	5-10%	[Abated]	
Structure	Deck	Steel			C	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (poured)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Vermiculite/concrete block walls			D	N						S0035ABC	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1002 : Gymnasium Storage
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Vinyl Floor Tile and Mastic, 12x12 beige with grey fleck (installed 2018)			A	Y						V0000	Non-Asbestos		None	
Floor		Abated Material, 12x12 tan with red and brown streaks			A	Y		100			%	S0021	[None]	0.5-5%	[Abated]	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			A	Y		16(5)			EA	S0022	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Mastic			D	N		100			%	S0002	None Detected		None	
Structure		Concrete (poured)			C	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (poured)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Vermiculite/concrete block walls			D	N		100			%	S0001	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1003 : Boys Changeroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			C	Y		100			%	V0010	None Detected		None	
Ceiling		Plaster, textured			C	Y		100			%	S0018	None Detected		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1004 : Girls Changeroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 pinhole			C	Y		100			%	V0003	None Detected		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	N		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement	Fitting		C	Y		5(7)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Structure		Concrete (poured)			C	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	S0034ABC	None Detected	N.D.	None	
Wall		Masonry			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1005 : Special Education
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 long fissure random pinhole			A	Y		100			%	S0011	None Detected		None	
Floor		Mastic			D	N		100(7)			%	S0023	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 white with grey			A	Y						V0000	Non-Asbestos		None	
Other	Window	Caulking, Grey			A	Y		100(7)			%	S0027	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Piping		Fibreglass			C	N		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			C	Y		100			%	V0034	None Detected	N.D.	None	
Wall		Masonry			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1006 : Custodian Sink Room
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 pinhole			A	Y		100			%	V0003	None Detected		None	
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			A	Y		100			%	V0010	None Detected		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			A	Y		3(5)	1(5)		EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Masonry			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1007 : Corridor
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			A	Y		100			%	S0010	None Detected		None	
Ceiling		Ceiling Tiles (lay-in), 2x4 pinhole			C	Y						S0003	None Detected		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	N		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	S0012	None Detected		None	
Wall		Plaster			A	Y		100			%	S0020D	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1008 : Corridor
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			A	Y		100			%	V0010	None Detected		None	
Ceiling		Ceiling Tiles (lay-in), 1x1 pinhole			A	Y		100			%	S0028	None Detected		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1009 : Corridor
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on)			C	N		400			SF	S0030	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			A	Y		100			%	V0010	None Detected		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1010 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), Gypsum			C	Y										
Ceiling		Plaster			A	Y		100			%	V0020	None Detected		None	
Ceiling	Bulkhead	Drywall and joint compound			A	Y		100			%	S0015A	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 12x12 white with black speck			A	Y		100(7)			%	S0014	Chrysotile	5-10%	Confirmed Asbestos	NF
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Other	Window	Caulking, brown			A	Y		100			%	S0016A	None Detected		None	
Structure		Concrete (poured)			C	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0015	None Detected		None	
Wall		Plaster			A	Y		100			%	S0020	None Detected		None	
Wall		Masonry			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1011 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			A	Y		100			%	V0015	None Detected		None	
Ceiling		Plaster			C	N		100			%	V0020	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 12x12 white with black speck			A	Y		100(7)			%	S0014	Chrysotile	5-10%	Confirmed Asbestos	NF
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Other	Window	Caulking, brown			A	Y		100			%	S0016B	None Detected		None	
Piping		Fibreglass			C	Y										
Structure		Concrete (poured)			C	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	S0015C	None Detected		None	
Wall		Plaster			A	Y		100			%	S0020C	None Detected		None	
Wall		Masonry			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1012 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 pinhole			A	Y		100			%	V0028	None Detected		None	
Ceiling		Ceiling Tiles (lay-in), Gypsum			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, 9x9 green with white streaks			A	Y		100			%	S0006	[None]	5-10%	[Abated]	
Floor		Vinyl Floor Tile and Mastic, 9x9 light green with green streaks			A	Y		100			%	S0013	[None]	5-10%	[Abated]	
Floor		Vinyl Floor Tile and Mastic, Brown with black and white fleck			A	Y										
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Other	Window	Caulking, brown			A	Y		100			%	S0016C	None Detected		None	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			C	Y		6(7)			EA	S0022C	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Drywall and joint compound			A	Y		100			%	S0015B	None Detected		None	
Wall		Plaster			A	Y		100			%	S0020B	None Detected		None	
Wall		Masonry			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1013 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 9x9 black and white marble			A	Y		100(7)			%	S0005A	Chrysotile	5-10%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile and Mastic, 9x9 green with white marble			A	Y		100(7)			%	S0007A	Chrysotile	5-10%	Confirmed Asbestos	NF
Other	Window	Caulking, Grey			A	Y		100			%	S0017	None Detected		None	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			C	Y		2(7)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement			A	Y		2(5)			SF	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Plaster			A	Y		100			%	S0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1014 : Stairwell
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Metal		Not Insulated	A	Y										
Wall		Plaster			A	Y		100			%	S0020A	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1015 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 9x9 black and white marble			A	Y		100(7)			%	V0005	Chrysotile	5-10%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile and Mastic, 9x9 green with white marble			A	Y		100			%	V0007	[None]	5-10%	[Abated]	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			C	Y		6(7)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement			A	Y		2(5)			SF	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1016 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 pinhole			C	Y		100			%	V0028	None Detected		None	
Ceiling		Drywall (no compound)			C	Y										
Floor		Vinyl Floor Tile and Mastic, 12x12 Brown with black and white fleck			A	Y										
Floor		Mastic			D	N		100(7)			%	V0006	Chrysotile	5-10%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9x9 green with white streaks			A	Y		100			%	V0006	[None]	5-10%	[Abated]	
Floor		Vinyl Floor Tile (No Mastic), 9x9 light green with green streaks			A	Y		100			%	V0013	[None]	5-10%	[Abated]	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			C	Y		5(7)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement			A	Y		2(5)			%	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1017 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1' x 1' pinhole			A	Y		100			%	S0028	None Detected		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 pink with dark pink streaks			A	Y		100			%	V9500	[None]		[Abated]	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			C	Y		2(7)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement			A	Y		2(5)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Structure		12x12 Brown with black and white fleck			A	Y										
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1018 : Storage
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			A	Y		100			%	V0010	None Detected		None	
Floor		Wood			A	Y										
Floor		Mastic			D	N		100(7)			%	V0006	Chrysotile	5-10%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9x9 light green with green streaks			A	Y		100			%	V0013	[None]	5-10%	[Abated]	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			A	Y		2(5)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1019 : Girls Washroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 smooth (gypsum board)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	
Wall		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1020 : Boys Washroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 smooth (gypsum board)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	
Wall		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1021 : Vestibule
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			C	Y		100			%	V0010	None Detected		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	
Wall		Masonry			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1022 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 12x12 grey with light grey fleck			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			C	Y		10(7)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement			A	Y		2(5)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1023 : Coat Room
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 9x9 burgundy			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile and Mastic, 9" x 9" orange			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			C	Y		2(7)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1024 : Sink Room
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9x9 green with white			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1025 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 12 grey flecks			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			A	Y		2(5)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement			C	Y		2(7)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1026 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 9x9 black and white marble			A	Y		100(7)			%	V0005	Chrysotile	5-10%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile and Mastic, 9x9 Green with white marble			A	Y		100			%	V0007	[None]	5-10%	[Abated]	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			A	Y		2(5)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement			C	Y		2(7)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1027 : Vestibule/Stairwell
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			C	Y		100			%	V0010	None Detected		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1028 : Office
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			A	Y		100			%	V0010	None Detected		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1029 : Office
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			A	Y		100			%	V0010	None Detected		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1030 : Principals Office
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			A	Y		100			%	V0010	None Detected		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1031 : Stairwell
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			A	Y		100			%	V0020	None Detected		None	
Floor ¹		Vinyl Floor Tile and Mastic			A	Y		100			%	S0025	None Detected	N.D.	None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Other	Window	Caulking, black			A	Y		100			%	S0024	None Detected		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

1 - Landing

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1032 : Accessible Washroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2' x 4' Pinholes/textured pinholes			A	Y		100			%	V0010	None Detected		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 pink marble			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass			C	N		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A			100			%	V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1033 : Washroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 smooth (gypsum board)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, 9x9 light green with green streaks			A	Y		100(7)				V0013	Chrysotile	5-10%	Confirmed Asbestos	NF
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1034 : Special Education Office
Survey Date: 2018-08-16

Site: Elementary
Floor: 1

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 pinhole long			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, 9 x9 beige and red			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Mastic			D	N		100(7)			%	V0023	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Other	Window	Caulking, grey			A	Y		100(7)			%	V0027	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall		Drywall and joint compound			C	Y		100			%	V0034	None Detected	N.D.	None	
Wall		Masonry			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2001 : Staff Washroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2002 : Staff Storage
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 pinhole			C	Y		100			%	V0003	None Detected		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2003 : Staff Room
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Vinyl Sheet Flooring, Brown pebble pattern			A	Y		100(7)			%	S0026	Chrysotile	10-25%	Confirmed Asbestos	PF
Floor		Mastic			D	N		100(7)			%	V0026	Chrysotile	10-25%	Confirmed Asbestos	NF
Structure		Concrete (precast)			C	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2004 : Corridor
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			C	Y		100			%	V0010	None Detected		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2005 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling ¹		Drywall and joint compound			A	Y		100(7)			%	S0032C	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Mastic			D	N		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 9X9 BLACK AND WHITE MARBLE			A	Y		100(7)			%	V0005	Chrysotile	5-10%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9X9 GREEN WITH WHITE MARBLE			A	Y		100			%	V0007	[None]	5-10%	[Abated]	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			A	Y		2(5)			SF	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

1 - Asbestos containing drywall joint compound is present as a patch material on the ceiling

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2006 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 12x12 Brown with black and white fleck			A	Y										
Floor		Mastic			D	N		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 9X9 BLACK AND WHITE MARBLE			A	Y		100(7)			%	V0005	Chrysotile	5-10%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9X9 GREEN WITH WHITE MARBLE			A	Y		100			%	V0007	[None]	5-10%	[Abated]	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			A	Y		2(5)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement			C	Y		2(7)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2007 : Boys Washroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2X4 DRYWALL			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	
Wall		Masonry			A	Y										
Wall		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2008 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 12x12 Beige flecks			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Abated Material			A	Y									[Abated]	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			C	Y		7(7)			SF	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement			A	Y		2(5)			SF	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2009 : Girls Washroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall (no compound)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			A	Y										
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	
Wall		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2010 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1X1 PINHOLE			C	Y		100			%	V0028	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 12x12 Brown with black and white fleck			A	Y										
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9X9 MEDIUM GREEN WITH WHITE			A	Y		100			%	V9500	[None]		[Abated]	
Floor		Vinyl Floor Tile (No Mastic), 9X9 WHITE WITH MEDIUM GREEN			A	Y		100			%	V9500	[None]		[Abated]	
Other	Debris	Mastic, Brown ceiling tile mastic			A	Y				10	SF	S0031	None Detected	N.D.	None	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement			A	Y		2(5)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement			C	Y		2(7)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2011 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1X1 PINHOLE			C	Y		100			%	V0020	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 12x12 Brown with black and white fleck			A	Y										
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9X9 MEDIUM GREEN WITH WHITE			A	Y		100			%	V9500	[None]		[Abated]	
Floor		Vinyl Floor Tile (No Mastic), 9X9 WITH MEDIUM GREEN			A	Y		100			%	V9500	[None]		[Abated]	
Other	Debris	Mastic, Brown ceiling tile mastic			A	Y				10	SF	V0031	None Detected	N.D.	None	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2012 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 12x12 Brown with black and white fleck			A	Y										
Floor		Mastic			D	N						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 9X9 BLACK AND WHITE MARBLE			A	Y		100			%	S0005B	[None]	5-10%	[Abated]	
Floor		Vinyl Floor Tile (No Mastic), 9X9 GREEN WITH WHITE MARBLE			A	Y		100			%	S0007	[None]	5-10%	[Abated]	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2013 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12X12 PINK MARBLE			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Parging Cement		Polyvinyl chloride (PVC)	C	Y		2(7)			EA	V0022	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2014 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 1X1 PINHOLE			C	Y		100			%	V0028	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 12x12 Brown with black and white fleck			A	Y										
Floor		Mastic			D	N		100(7)			%	V0006	Chrysotile	5-10%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9X9 GREEN WITH WHITE STREAKS			A	Y		100			%	V0006	[None]	5-10%	[Abated]	
Floor		Vinyl Floor Tile (No Mastic), 9X9 LIGHT GREEN WITH GREEN STREAKS			A	Y		100			%	V0013	[None]	5-10%	[Abated]	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2015 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12X12 WHITE AND BLACK			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Not Insulated			A	Y										
Structure		Concrete (poured)			C	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (poured)			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2016 : Classroom
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12X12 WHITE WITH BLACK			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Structure		Concrete (precast)			C	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (poured)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	S0036ABC	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2017 : Upper Office
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0020	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, 12" x 12" White with black flecks only			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2018 : Corridor
Survey Date: 2018-08-16

Site: Elementary
Floor: 2

Building Name: Sts. Peter and Paul
Room #:
Last Re-Assessment: 2022-06-28

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			C	Y		100			%	V0010	None Detected		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0020	None Detected		None	

Legend:



Sample number		Units		Other	
S####	Asbestos sample collected	SF	Square feet	A	Access
V####	Material visually similar to numbered sample collected	LF	Linear feet	V	Visible
V0000	Known non-asbestos material	EA	Each	AP	Air Plenum
V9000	Visually identified as an asbestos material	%	Percentage	F	Friable material
V9500	Material is presumed to be an asbestos material			NF	Non Friable material
				PF	Potentially Friable material

Access	
A	Accessible to all building occupants
B	Accessible to maintenance and operations staff without a ladder
C	Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas
D	Not normally accessible

Condition	
Good	No visible damage or deterioration
Fair	Minor, repairable damage, cracking, delamination or deterioration
Poor	Irreparable damage or deterioration with exposed and missing material

Visible	
Y	The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels).
N	The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points.

Air Plenum	
Yes or No	The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation.

Colour Coding	
	The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code).
	The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling.


Action					
(1)	Clean up of ACM Debris	(2)	Precautions for Access Which may Disturb ACM Debris	(3)	ACM removal
(4)	Precautions for Work Which may Disturb ACM in Poor Condition	(5)	Proactive ACM removal (Minimum repair required for fair condition)	(6)	ACM repair
(7)	Management program and surveillance				

APPENDIX V
Drawings

NOT ALL KNOWN OR SUSPECTED ASBESTOS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS REASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.



905-577-6206 www.pinchin.com

LEGEND:

- (X) LOCATION NUMBER
- ⊙ ASBESTOS BULK SAMPLE

ASBESTOS-CONTAINING MATERIALS:

- P PIPE INSULATION
- VINYL SHEET FLOORING & MASTIC
- VINYL FLOOR TILES & MASTIC
- MASTIC

NOTE:
ASBESTOS CONTAINING MATERIALS NOT HATCHED IN DRAWING:
- DRYWALL JOINT COMPOUND
- CAULKING AT WINDOW FRAMES

CLIENT:



LOCATION:

STS. PETER AND PAUL
49 FENNELL AVENUE EAST
HAMILTON, ONTARIO

TITLE:

ASBESTOS REASSESSMENT
BASEMENT LEVEL

DATE:

AUGUST 2022

PROJECT # :

303992.004

DRAWN BY:

EB

CHECKED BY:

EB

SCALE:

NTS

DRAWING:

1 OF 3

NOT ALL KNOWN OR SUSPECTED ASBESTOS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS REASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.



905-577-6206 www.pinchin.com

LEGEND:

- (X) LOCATION NUMBER
- ⊙ ASBESTOS BULK SAMPLE

ASBESTOS-CONTAINING MATERIALS:

- P PIPE INSULATION
- VINYL SHEET FLOORING & MASTIC
- VINYL FLOOR TILES & MASTIC
- MASTIC

NOTE:
ASBESTOS CONTAINING MATERIALS NOT HATCHED IN DRAWING:
- DRYWALL JOINT COMPOUND
- CAULKING AT WINDOW FRAMES

CLIENT:



LOCATION:

STS. PETER AND PAUL
49 FENNELL AVENUE EAST
HAMILTON, ONTARIO

TITLE:

ASBESTOS REASSESSMENT
FLOOR LEVEL 1

DATE:

AUGUST 2022

PROJECT # :

303992.004

DRAWN BY:

EB

CHECKED BY:


EB

SCALE:

NTS

DRAWING:

2 OF 3



NOT ALL KNOWN OR SUSPECTED ASBESTOS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS REASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.



905-577-6206 www.pinchin.com

LEGEND:

- (X) LOCATION NUMBER
- ⊙ ASBESTOS BULK SAMPLE

ASBESTOS-CONTAINING MATERIALS:

- P PIPE INSULATION
- VINYL SHEET FLOORING & MASTIC
- VINYL FLOOR TILES & MASTIC
- MASTIC

NOTE:
ASBESTOS CONTAINING MATERIALS NOT HATCHED IN DRAWING:
- DRYWALL JOINT COMPOUND
- CAULKING AT WINDOW FRAMES

CLIENT:



LOCATION:

STS. PETER AND PAUL
49 FENNELL AVENUE EAST
HAMILTON, ONTARIO

TITLE:

ASBESTOS REASSESSMENT
FLOOR LEVEL 2

DATE:
AUGUST 2022

PROJECT # :
303992.004

DRAWN BY:
EB

CHECKED BY:
EB

SCALE:
NTS

DRAWING:

3 OF 3

