



Asbestos Reassessment

St. Agnes
80 Colcrest Street, Hamilton,
Ontario

Prepared for:

**Hamilton-Wentworth Catholic
District School Board**

90 Mulberry Street
Hamilton, Ontario, L8N 3R9

August 12, 2022

Pinchin File: 303992.004



Asbestos Reassessment

St. Agnes, 80 Colcrest Street, Hamilton, Ontario
Hamilton-Wentworth Catholic District School Board

August 12, 2022
Pinchin File: 303992.004

Issued to: Hamilton-Wentworth Catholic District
School Board

Issued on: August 12, 2022

Pinchin File: 303992.004

Issuing Office: Hamilton, ON

Pinchin Contact: Emily Balfour, Project Manager
365.889.5147
ebalfour@pinchin.com



Author: _____

Emily Balfour
Project Manager
365.889.5147
ebalfour@pinchin.com

Reviewer: _____

Damian Palus, C.E.T.
Operations Manager
289.678.0694
dpalus@pinchin.com



EXECUTIVE SUMMARY

Hamilton-Wentworth Catholic District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment at the subject building.

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM) and develop corrective action plans as required for the purposes of long-term management. The results of this reassessment are not intended for construction, renovation, demolition or project tendering purposes.

Summary of Recommendations

The following is a summary of significant recommendations; refer to the body of the report for detailed recommendations:

- Perform a reassessment of asbestos materials on an annual basis.
- Perform a pre-construction assessment and remove all asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work.
- Follow appropriate safe work procedures when handling or disturbing asbestos.
- Sample any presumed ACM prior to alteration or maintenance work if presumed ACM may be disturbed by the work.

This Executive Summary is subject to the same standard limitations as contained in the report and must be read in conjunction with the entire report.



Asbestos Reassessment

St. Agnes, 80 Colcrest Street, Hamilton, Ontario
Hamilton-Wentworth Catholic District School Board

August 12, 2022
Pinchin File: 303992.004

TABLE OF CONTENTS

1.0	INTRODUCTION AND SCOPE	1
1.1	Scope of Assessment	1
2.0	BACKGROUND INFORMATION	1
2.1	Building Year of Construction and Additions	1
2.2	Existing Reports	1
3.0	FINDINGS	2
3.1	Presumed Asbestos Materials	2
3.2	Confirmed/Presumed Asbestos-Containing Materials and Confirmed Non-Asbestos Materials	3
4.0	RECOMMENDATIONS	4
4.1	General	4
4.2	Remedial Work	4
4.3	On-going Management and Maintenance	5
5.0	TERMS AND LIMITATIONS	5
6.0	REFERENCES	5

APPENDICES

APPENDIX I	Asbestos Analytical Certificates
APPENDIX II	Location List
APPENDIX III	Summary Report
APPENDIX IV	All Data Report
APPENDIX V	Drawing



1.0 INTRODUCTION AND SCOPE

Hamilton-Wentworth Catholic District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment at St. Agnes located at 80 Colcrest Street, Hamilton, Ontario.

The reassessment was performed by Emily Balfour, Project Manager on May 10, 2022.

The objectives of the reassessment were to document the locations, quantities and conditions of previously identified asbestos-containing building materials and develop corrective action plans as required. This reassessment is only to be used for the purposes of long-term management and routine maintenance. The results of this reassessment are not to be used for construction, renovation, demolition or project tendering purposes.

1.1 Scope of Assessment

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM) and develop corrective action plans as required.

Refer to the Asbestos Building Materials Reassessment Methodology report and Annex A dated 2022, Pinchin File 303992.004, for the methodology used during the reassessment.

2.0 BACKGROUND INFORMATION

2.1 Building Year of Construction and Additions

Item	Details
Year of Construction	1978
Year(s) of Additions	2005

2.2 Existing Reports

2.2.1 Review of Previous Reports

Pinchin previously prepared the following report, which has been reviewed and relied upon as part of this assessment:

- “Asbestos Assessment, St. Agnes, 80 Colcrest Street, Hamilton, Ontario”, dated December 2018, Prepared by Pinchin Ltd., Pinchin File: 224334.
- “Asbestos Reassessment, St. Agnes, 80 Colcrest Street, Hamilton, Ontario”, dated July 2019, Prepared by Pinchin Ltd., Pinchin File: 243241.



Asbestos Reassessment

St. Agnes, 80 Colcrest Street, Hamilton, Ontario
Hamilton-Wentworth Catholic District School Board

August 12, 2022
Pinchin File: 303992.004

- “Asbestos Reassessment, St. Agnes, 80 Colcrest Street, Hamilton, Ontario”, dated April 2020, Prepared by Pinchin Ltd., Pinchin File: 272113.
- “Asbestos Reassessment, St. Agnes, 80 Colcrest Street, Hamilton, Ontario”, dated July 2021, Prepared by Pinchin Ltd., Pinchin File: 286533.001.

3.0 FINDINGS

The following section summarizes the findings of the reassessment and provides a general description of the asbestos materials identified. For details on quantities, assessment, sample numbers, friability, condition, and locations of asbestos materials; refer to the Summary Report and All Data Report in Appendix III and IV.

Previous analytical sample results have been relied upon and were included in the original asbestos assessment report completed by MTE Consultants Inc. Additional samples results where collected by Pinchin have been included in Appendix I.

3.1 Presumed Asbestos Materials

A number of materials which might contain asbestos were not sampled during this reassessment due to limitations in scope and methodology. Where present, these materials are assumed to contain asbestos until otherwise proven by sampling and analysis. These materials are not shown on the drawings in Appendix V. Materials presumed to contain asbestos include:

Material	Friability
Roofing, felts and tar	Non-friable
Concrete floor levelling compound	Non-friable
Electrical components or wiring within control centers, breakers, motors or lights, insulation on wiring	Non-friable
Vermiculite in concrete block wall cavities	Friable
Caulking	Non-friable
Fibre reinforced paints and coatings	Non-friable
Paper products	Non-friable
Soffit and fascia boards	Non-friable
Mechanical packing, ropes and gaskets	Non-friable



Asbestos Reassessment

St. Agnes, 80 Colcrest Street, Hamilton, Ontario
Hamilton-Wentworth Catholic District School Board


August 12, 2022
Pinchin File: 303992.004

Material	Friability
Fire resistant doors or metal clad finishes	Non-friable
Ceramic tile thin-set	Non-friable

3.2 Confirmed/Presumed Asbestos-Containing Materials and Confirmed Non-Asbestos Materials

This section includes materials that have been confirmed asbestos-containing by sample analysis or presumed asbestos-containing by visual identification. Refer to the drawings in Appendix V for the locations of all confirmed and presumed ACMs indicated via hatching or symbols. The locations of samples from the historical assessments performed by Pinchin have been included on the drawings.

Material and Application	Asbestos Type/Friability	Photo
Non-asbestos texture finish is present on exterior soffits.	None	
Pipes are either uninsulated or insulated with non-asbestos fibreglass or elastomeric insulation (Armaflex).	None	
Ducts are either uninsulated or insulated with non-asbestos fibreglass (foil-faced or canvas).	None	
Mechanical equipment is either uninsulated or insulated with non-asbestos fibreglass.	None	
All ceiling tiles are presumed to be non-asbestos based on the date of manufacture determined from the date stamp applied to the top of the tiles or the age of the materials determined from the age of the building or the renovation.	None	
Non-asbestos drywall joint compound is present on wall and ceiling finishes.	None	
Vinyl sheet flooring is presumed to be non-asbestos based on the date of installation (2005) and historical knowledge of the type of flooring	None	

Material and Application	Asbestos Type/Friability	Photo
(foam) or based on the lack of a paper backing layer (underpad).		
Vinyl floor tiles were presumed to be non-asbestos based on historical knowledge of the date of installation (2005). The mastic below the tiles is presumed to contain asbestos.	None (tile) Presumed/Non-friable (mastic)	

Additional notes on the non-asbestos drywall joint compound discussed above:

- Drywall (gypsum board) and drywall joint compound is present as a wall and ceiling finish throughout the building. As per the methodology, drywall joint compound is sampled at exterior walls, columns or other locations that are unlikely to have been renovated in an attempt to determine the presence of asbestos in the original drywall compound. A total of 6 samples of drywall joint compound were collected (samples 0001A-C and 0002A-C, lab reference no. 51829044) and it was found that the samples do not contain asbestos. Therefore, drywall joint compound present on drywall finishes should be considered to be non-asbestos.

4.0 RECOMMENDATIONS

4.1 General

Perform a detailed intrusive assessment prior to building renovation or demolition operations. The assessment should include: destructive testing (i.e. coring and/or removal of building finishes and components), sampling of other hazardous materials (lead, mercury, PCBs, mould, etc.), and materials not tested in this study (i.e. roofing materials, caulking, mastics).

4.2 Remedial Work

There is no remedial work recommended.



4.3 On-going Management and Maintenance

The following recommendations are made regarding on-going management and maintenance work involving the asbestos materials identified.

4.3.1 Asbestos

Maintain the Asbestos Management Program (AMP).

Perform a re-assessment of asbestos materials on an annual basis.

Remove asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work. Follow appropriate asbestos precautions for the classification of work being performed.

Sample presumed ACM prior to alteration or maintenance work if the presumed ACM may be disturbed by the work.

Update the asbestos inventory report upon completion of any abatement and removal of asbestos-containing materials.

5.0 TERMS AND LIMITATIONS

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.

6.0 REFERENCES

The following legislation and documents were referenced in completing the assessment and this report:

1. Asbestos on Construction Projects and in Buildings and Repair Operations, Ontario Regulation 278/05.
2. Designated Substances, Ontario Regulation 490/09.

\\pinchin.com\ham\Job\303000s\0303992.000 HWCDSB,Various2022Projects,ASB,CONS\0303992.004
HWCDSB,AllFacilities,2022,ASB,REASSMT\Deliverables\Elementary\St. Agnes\Report\303992.004 St. Agnes ACM Reassessment Report HWCDSB August 12 2022.docx

Template: Master Report for Asbestos Reassessment, HAZ, April 23, 2019

APPENDIX I
Asbestos Analytical Certificates



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
6-875 Main St West
Suite 200
Hamilton, Ontario L8S 4P9

Attn: Robert Bertin-Fenney
Michael Maiorana

Lab Order ID: 51829044
Analysis ID: 51829044_PLM
Date Received: 11/6/2018
Date Reported: 11/9/2018

Project: 230748,80 Colcrest Street, Hamilton, ON, Hamilton-Wentworth Catholic School Board, St. Agnes

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0001A	DJC on ceiling, Boy's washroom, Location 1039	None Detected		100% Other	White Non Fibrous Homogeneous
51829044PLM_1					Crushed
0001B	DJC on ceiling, Gym Storage, Location 1040	None Detected		100% Other	White Non Fibrous Homogeneous
51829044PLM_2					Crushed
0001C	DJC on bulkhead, Corridor, Location 1044	None Detected		100% Other	White Non Fibrous Homogeneous
51829044PLM_3					Crushed
0002A	DJC on wall, Copy Room, Location 1022	None Detected		100% Other	White Non Fibrous Homogeneous
51829044PLM_4					Crushed
0002B	DJC on column, Corridor, Location 1053	None Detected		100% Other	White Non Fibrous Homogeneous
51829044PLM_5					Crushed
0002C	DJC on wall, Classroom, Location 1051	None Detected		100% Other	White Non Fibrous Homogeneous
51829044PLM_6					Crushed


Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Bethany Nichols (6)

Analyst

Approved Signatory

51829044
Version 1-15-2012

Client: Contact: Address: Phone: Fax: Email: Project: Client Notes: P.O. #: Date Submitted: Analysis: TurnAroundTime:	Pinchin Ltd. Robert Bertin-Fenney 875 Main Street W., Unit 11 Hamilton, ON L8S 4R9 905-577-6206 905-577-6207 rbertin-fenney@pinchin.com mmaiorana@pinchin.com 230748,80 Colcrest Street, Hamilton, ON,Hamilton-Wentworth Catholic School Board,St. Agnes 230748 November 5,2018 PLM - Stop Positive 4days	<p>*Instructions:</p> <p>Use Column "B" for your contact info</p> <p>To See an Example Click the bottom Example Tab.</p> <p>Enter samples between "<<" and ">>"</p> <p>Begin Samples with a "<<" above the first sample and end with a ">>" below the last sample. Only Enter your data on the first sheet "Sheet1"</p> <p>Note: Data 1 and Data 2 are optional fields that do not show up on the official report, however they will be included in the electronic data returned to you to facilitate your reintegration of the report data.</p>	<p>Invoice to:</p>  <p>Scientific Analytical Institute</p> <p>4604 Dundas Dr. Greensboro, NC 27407 Phone: 336.292.3888 Fax: 336.292.3313 Email: lab@sailab.com</p>
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Sample Number	Data 1 (Lab use only)	Sample Description	Data 2 (Lab use only)
---------------	-----------------------	--------------------	-----------------------

<<			
0001A		DJC on ceiling, Boy's washroom, Location 1039	
0001B		DJC on ceiling, Gym Storage, Location 1040	
0001C		DJC on bulkhead, Corridor, Location 1044	
0002A		DJC on wall, Copy Room, Location 1022	
0002B		DJC on column, Corridor, Location 1053	
0002C		DJC on wall, Classroom, Location 1051	
>>			

By Bailey 11/6
1030A

Accepted ☒
Rejected ☐



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
6-875 Main St West
Suite 200
Hamilton, Ontario L8S 4P9
Project: 80 Colcrest Street, Hamilton, ON

Attn: Robert Bertin-Fenney
Michael Maiorana

Lab Order ID: 51831063
Analysis ID: 51831063_PLM
Date Received: 11/28/2018
Date Reported: 12/3/2018

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0003a - A	Textured plaster on metal exterior soffit, Location 1	None Detected		100% Other	White Non Fibrous Homogeneous
51831063PLM_1	finish				Crushed
0003a - B	Textured plaster on metal exterior soffit, Location 1	None Detected		100% Other	Gray Non Fibrous Homogeneous
51831063PLM_4	base				Crushed
0003b - A	Textured plaster on metal exterior soffit, Location 1	None Detected		100% Other	White Non Fibrous Homogeneous
51831063PLM_2	finish				Crushed
0003b - B	Textured plaster on metal exterior soffit, Location 1	None Detected		100% Other	Gray Non Fibrous Homogeneous
51831063PLM_5	base				Crushed
0003c - A	Textured plaster on metal exterior soffit, Location 1	None Detected		100% Other	White Non Fibrous Homogeneous
51831063PLM_3	finish				Crushed
0003c - B	Textured plaster on metal exterior soffit, Location 1	None Detected		100% Other	Gray Non Fibrous Homogeneous
51831063PLM_6	base				Crushed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Bethany Nichols (6)

Analyst

Approved Signatory

51831063

Special Instructions:

Pinchin Ltd. - Asbestos Laboratory

Internal Asbestos Bulk Sample Chain of Custody

Client Name:	Hamilton-Wentworth Catholic School Board	Project Address:	80 Colcrest Street, Hamilton, ON				
Portfolio/Building No:	St. Agnes	Pinchin File:	230748				
Submitted by:	Robert Bertin-Fenney	Email:	rbertin-fenney@pinchin.com				
CC Results to:	Michael Maiorana	CC Email:	mmaiorana@pinchin.com				
Invoice to:	Accounts Payable	Invoice Email:	ap@pinchin.com				
Date Submitted:	November	27	2018	Required by:	December	4	2018
# of Samples:	3			Priority:	5 Day Turnaround		
Year of Building Construction (Mandatory Field):				1978			
Do NOT Stop on Positive (Sample Numbers):							
Pinchin Group Company (Mandatory Field):				Select			

To be Completed by Lab Personnel Only:							
Lab Reference #:				Time:	24 hour clock		
Received by:				Date:	Month	Day	Year
Name(s) of Analyst(s):							
Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)				
	0003	A	Textured plaster on metal exterior soffit, Location 1				
	0003	B	Textured plaster on metal exterior soffit, Location 1				
	0003	C	Textured plaster on metal exterior soffit, Location 1				

Accepted ☒
Rejected ☐

N. Kamej 11/28 10:30A

APPENDIX II
Location List

Client: Hamilton-Wentworth Catholic District Sch
Building Name: St. Agnes
Survey Date: 2018-08-02

Site: 80 Colcrest Street, Hamilton, ON
Last Re-Assessment: 2022-05-10

Location No.	Name or Description	Area ft ²	Floor No.	Bldg. Phase	Notes
1	Presumed Asbestos-containing Materials/General	0	1	A	
1001	Classroom 13, room no. 13	0	1	A	
1002	Classroom 12, room no. 12	0	1	A	
1003	Classroom 11, room no. 11	0	1	A	
1004	Classroom 10, room no. 10	0	1	A	
1005	Classroom 9, room no. 9	0	1	A	
1006	Staff Washroom	0	1	A	
1007	H/C Washroom	0	1	A	
1008	Spec. ED. Office	0	1	A	
1009	Constructed in 2006	0	1	A	
1010	Constructed in 2006	0	1	A	
1011	Constructed in 2006	0	1	A	
1012	Constructed in 2006	0	1	A	
1013	Constructed in 2006	0	1	A	
1014	Constructed in 2006	0	1	A	
1015	Boiler Room	0	1	A	
1016	Kindergarten	0	1	A	
1017	Kindergarten	0	1	A	
1018	Kindergarten	0	1	A	
1019	Classroom 2	0	2	A	
1020	Classroom 1	0	1	A	
1021	Staffroom/ Staff Washroom	0	1	A	
1022	Copy Room	0	1	A	
1023	Principal	0	1	A	
1024	Office	0	1	A	
1025	Computer Lab	0	1	A	
1026	Library	0	1	A	
1027	Library Office	0	1	A	
1028	Library Storage	0	1	A	
1029	Library Storage	0	1	A	
1030	Classroom 15	0	15	A	
1031	Classroom 14	0	14	A	
1032	Electrical Room	0	1	A	
1033	Storage	0		A	
1034	Stage	0	1	A	
1035	Gymnasium	0	1	A	
1036	Boys Washroom	0	1	A	
1037	Supply Room	0	1	A	
1038	Boys Washroom	0	1	A	
1039	Boys Washroom	0	1	A	
1040	Gym Storage	0	1	A	
1041	Boys Washroom	0	1	A	
1042	Equipmwnt Storage	0	1	A	
1043	Mechanical Room	0	1	A	
1044	Custodian Room	0	1	A	
1045	Girls Change Room	0	1	A	
1046	Girls Washroom	0	1	A	
1047	Spec ED.	0	1	A	
1048	Health Room	0	1	A	
1049	Chair Storage	0	1	A	
1050	Foyer	0	1	A	
1051	Coridoor	0		A	NO ACCESS
1053	Corridor	0	1	A	
1054	Corridor	0	1	A	

APPENDIX III
Summary Report

HAZARDOUS MATERIALS SUMMARY / SAMPLE LOG

Client: Hamilton-Wentworth Catholic District Sch

Site: 80 Colcrest Street, Hamilton, ON

Building Name: St. Agnes

Survey Date: 2018-08-02

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	S0001 ABC	Ceiling, Wall Bulkhead Drywall And Joint Compound Djc	1001,1007,1016,1020,1022,1024,1025,1028,1031,1032,1036,1037,1039,1040,1044,1048	A	0	0	0	100	None Detected	No	
Asbestos	S0002 C	Wall Drywall And Joint Compound Djc	1002,1003,1005,1006,1017,1019,1021,1023,1026,1027,1029,1030,1033,1034,1035,1038,1051,1053,1054	A	0	0	0	100	None Detected	No	
Asbestos	S0003	Other Soffit Texture Coat Textured Plaster On Metal Exterior Soffit	1	A	0	0	0	100	None Detected	No	
Asbestos	V9500	Floor Mastic Mastic.	1001,1002,1003,1004,1005,1006,1007,1008,1016,1017,1018,1019,1020,1021,1022,1023,1024,1025,1026,1027,1028,1029,1030,1031,1034,1035,1036,1037,1038,1039,1040,1041,1042,1043,1044,1045,1046,1047,1048,1049	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Door, Window Caulking	1	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Cement Product	1	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Roof Roofing Material	1	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Electrical Wire Textile Woven Jacketing And Insulation On Older Electrical Wiring	1	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Wall Interior Vermiculite/concrete Block Walls	1	A	0	0	0	100	Presumed Asbestos	Yes	F
Asbestos	V0000	Ceiling Acoustic Tile Ceiling Tiles (lay-in) 2' X 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.	1026,1029,1030,1031,1032,1033,1034,1035,1036,1037,1038,1039,1040,1041,1042,1044,1045,1046,1047,1048,1049,1050,1051,1053,1054	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling Acoustic Tile Ceiling Tiles (lay-in) 2' X 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.	1001,1002,1004,1005,1006,1007,1016,1017,1018,1019,1020,1021,1022,1023,1024,1025	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling Acoustic Tile Ceiling Tiles (lay-in) 2' X 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.	1003,1008	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling Acoustic Tile Ceiling Tiles (lay-in) 2'x4' Short Fissure Random Pinhole - Date Stamped 04/20/2011	1027	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Beige Multi-fleck - Installed 2005.	1035	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Vinyl Floor Tile 12"x 12" - Installed 2005.	1022,1026,1027,1028,1029	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005	1039	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Vinyl Floor	1030,1031,1034,1036,1037,1038,1040,1041,1042	A	0	0	0	100	Non	No	

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
		Tile 12"x 12" Beige Multi-fleck - Installed 2005.	1043,1044,1045,1046,1047,1048,1049						Asbestos		
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.	1004,1005,1006,1008,1016,1017,1018,1019,1020 1021,1024,1025	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005	1003	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.	1001,1002	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Vinyl Floor Tile 12"x 12" Blue Multi-fleck. Installed 2005.	1021	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Vinyl Floor Tile 12"x 12" Coloured Accent Tiles - Installed 2005.	1030,1031	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Vinyl Floor Tile 12"x 12" Coloured Accent Tiles. Installed 2005.	1002,1003,1005,1017,1018,1019,1020	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Vinyl Floor Tile 12"x 12" Coloured Accent Tiles. Installed 2005.	1004	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Vinyl Floor Tile 12"x 12" Yellow Multi-fleck. Installed 2005.	1021	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Vinyl Floor Tile 12"x 12" Coloured Accent Tiles. Installed 2005.	1001	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Vinyl Floor Tile 12"x 12". Installed 2005.	1023	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Sheet Flooring Pebbled, Installed 2005	1007	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Wall Exterior Masonry	1	A	0	0	0	100	Non Asbestos	No	

Legend:

Sample number	
S####	Asbestos sample collected
L####	Paint sample collected
P####	PCB sample collected
M####	Mould sample collected
V####	Material visually similar to numbered sample collected
V0000	Known non Hazardous Material
V9000	Material is visually identified as Hazardous Material
V9500	Material is presumed to be Hazardous Material
[Loc. No.]	Abated Material

Units	
SF	Square feet
LF	Linear feet
EA	Each
%	Percentage

NF	Non Friable material.
F	Friable material
PF	Potentially Friable material

APPENDIX IV
All Data Report

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1 : Presumed Asbestos-containing Materials/General
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes

Room #:

Area (sqft): 0

Last Re-Assessment: 2022-05-10

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Other		Cement Product			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Door	Caulking			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Electrical Wire	Textile, Woven Jacketing and Insulation on Older Electrical Wiring	Insulation		B	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Roof	Roofing material			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Soffit	Texture Coat			A	Y		100			%	S0003	None Detected		None	
Other	Window	Caulking			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall	Exterior	Masonry			A	Y		100			%	V0000	Non-Asbestos		None	
Wall	Interior	Vermiculite/concrete block walls			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1001 : Classroom 13
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #: 13
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" coloured Accent Tiles. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0001	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1002 : Classroom 12
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #: 12
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.			A	Y		100				V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Coloured Accent Tiles. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1003 : Classroom 11
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #: 11
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Coloured Accent Tiles. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		D	N										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1004 : Classroom 10
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #: 10
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Coloured Accent Tiles. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1005 : Classroom 9
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #: 9
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Coloured Accent Tiles. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1006 : Staff Washroom
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1007 : H/C Washroom
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Sheet Flooring, Pebbled, installed 2005			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0001	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1008 : Spec. ED. Office
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1015 : Boiler Room
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Concrete (poured)			A	Y										
Piping		Fibreglass	Insulation		C	Y										
Structure	Beam, Deck	Steel			C	Y										
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1016 : Kindergarten
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100				V0001	None Detected		None	
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1017 : Kindergarten
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Coloured Accent Tiles. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1018 : Kindergarten
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Coloured Accent Tiles. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1019 : Classroom 2
Survey Date: 2018-08-02

Site: Elementary
Floor: 2

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.			A	Y						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Coloured Accent Tiles. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1020 : Classroom 1
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Coloured Accent Tiles. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0001	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1021 : Staffroom/ Staff Washroom
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Yellow Multi-fleck. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Blue Multi-fleck. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1022 : Copy Room
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0001	None Detected		None	
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1023 : Principal
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12". Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1024 : Office
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0001	None Detected		None	
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1025 : Computer Lab
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole. Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck. Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0001	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1026 : Library
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Carpet			A	Y										
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1027 : Library Office
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2'x4' Short Fissure Random Pinhole - Date Stamped 04/20/2011			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1028 : Library Storage
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Structure	Beam, Deck	Steel			C	Y										
Wall		Drywall and joint compound			A	Y		100			%	V0001	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1029 : Library Storage
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1030 : Classroom 15
Survey Date: 2018-08-02

Site: Elementary
Floor: 15

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Coloured Accent Tiles - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1031 : Classroom 14
Survey Date: 2018-08-02

Site: Elementary
Floor: 14

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Coloured Accent Tiles - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0001	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1032 : Electrical Room
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Concrete (poured)			A	Y										
Floor		Masonry			A	Y										
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0001	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1033 : Storage
Survey Date: 2018-08-02

Site: Elementary
Floor:

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Concrete (poured)			A	Y										
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1034 : Stage
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			C	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1035 : Gymnasium
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1036 : Boys Washroom
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0001	None Detected		None	
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1037 : Supply Room
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0001	None Detected		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1038 : Boys Washroom
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1039 : Boys Washroom
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N						V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	S0001A	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1040 : Gym Storage
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	S0001B	None Detected		None	
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1041 : Boys Washroom
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Masonry			A	Y										
Wall		Ceramic Tiles			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1042 : Equipmwnt Storage
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1043 : Mechanical Room
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic, Mastic.			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass			A	N										
Structure	Beam, Deck	Steel			C	Y										
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1044 : Custodian Room
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Drywall and joint compound			C	Y		100			%	S0001C	None Detected		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1045 : Girls Change Room
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Masonry			A	Y										
Wall		Ceramic Tiles			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1046 : Girls Washroom
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Masonry			A	Y										
Wall		Ceramic Tiles			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1047 : Spec ED.
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1048 : Health Room
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0001	None Detected		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1049 : Chair Storage
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Vinyl Floor Tile 12"x 12" Beige Multi-fleck - Installed 2005.			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1050 : Foyer
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y										
Piping		Fibreglass	Insulation		C	N										
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1051 : Corridor
Survey Date: 2018-08-02

Site: Elementary
Floor:

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS - NO ACCESS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y										
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1053 : Corridor
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y										
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	S0002C	None Detected		None	
Wall		Masonry			A	Y										

Client: Hamilton-Wentworth Catholic District Sch
Location: #1054 : Corridor
Survey Date: 2018-08-02

Site: Elementary
Floor: 1

Building Name: St. Agnes
Room #:
Last Re-Assessment: 2022-05-10

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2' x 4' Short Fissure Random Pinhole - Date Stamp 04/20/2011.			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y										
Piping		Fibreglass	Insulation		C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0002	None Detected		None	
Wall		Masonry			A	Y										

Legend:



Sample number		Units		Other	
S####	Asbestos sample collected	SF	Square feet	A	Access
V####	Material visually similar to numbered sample collected	LF	Linear feet	V	Visible
V0000	Known non-asbestos material	EA	Each	AP	Air Plenum
V9000	Visually identified as an asbestos material	%	Percentage	F	Friable material
V9500	Material is presumed to be an asbestos material			NF	Non Friable material
				PF	Potentially Friable material

Access	
A	Accessible to all building occupants
B	Accessible to maintenance and operations staff without a ladder
C	Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas
D	Not normally accessible

Condition	
Good	No visible damage or deterioration
Fair	Minor, repairable damage, cracking, delamination or deterioration
Poor	Irreparable damage or deterioration with exposed and missing material

Visible	
Y	The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels).
N	The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points.

Air Plenum	
Yes or No	The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation.

Colour Coding	
	The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code).
	The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling.

Action					
(1)	Clean up of ACM Debris	(2)	Precautions for Access Which may Disturb ACM Debris	(3)	ACM removal
(4)	Precautions for Work Which may Disturb ACM in Poor Condition	(5)	Proactive ACM removal (Minimum repair required for fair condition)	(6)	ACM repair
(7)	Management program and surveillance				

APPENDIX V
Drawing

NOT ALL KNOWN OR SUSPECTED ASBESTOS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS ASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS BUILDING MATERIALS.

BASE PLAN PROVIDED BY CLIENT.




905-577-6206 www.pinchin.com

LEGEND:

- (X) LOCATION NUMBER
- ◎ ASBESTOS BULK SAMPLE
- NEW 2005 ADDITION

ASBESTOS-CONTAINING MATERIALS:

- MASTIC



CLIENT:



LOCATION:

ST. AGNES
80 COLCREST STREET
HAMILTON, ONTARIO

TITLE:

ASBESTOS REASSESSMENT
FLOOR LEVEL 1

DATE:

AUGUST 2022

PROJECT #:

303992.004

DRAWN BY:

E

DRAWING:

CHECKED BY:

EB

1 OF 1

SCALE:

NTS