



Asbestos Reassessment

St. John the Baptist
115 London Street South,
Hamilton, Ontario

Prepared for:

**Hamilton-Wentworth Catholic
District School Board**

90 Mulberry Street
Hamilton, Ontario, L8N 3R9

August 29, 2022

Pinchin File: 303992.004

**Asbestos Reassessment**

St. John the Baptist, 115 London Street South, Hamilton, Ontario
Hamilton-Wentworth Catholic District School Board

August 29, 2022
Pinchin File: 303992.004



Hamilton-Wentworth
Catholic District School Board
Believing. Achieving. Serving

Issued to: Hamilton-Wentworth Catholic District
School Board

Issued on: August 29, 2022

Pinchin File: 303992.004

Issuing Office: Hamilton, ON

Pinchin Contact: Emily Balfour, Project Manager
365.889.5147
ebalfour@pinchin.com

Author: Luke Thompson ADip.T.(Arch)
Project Technologist
289.922.8960
lthompson@pinchin.com

Reviewer: Damian Palus, C.E.T.
Operations Manager
289.678.0694
dpalus@pinchin.com



EXECUTIVE SUMMARY

Hamilton-Wentworth Catholic District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment at the subject building.

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM), and develop corrective action plans as required for the purposes of long-term management. The results of this reassessment are not intended for construction, renovation, demolition or project tendering purposes.

Summary of Recommendations

The following is a summary of significant recommendations; refer to the body of the report for detailed recommendations:

- Perform a reassessment of asbestos materials on an annual basis.
- Perform a pre-construction assessment and remove all asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work.
- Follow appropriate safe work procedures when handling or disturbing asbestos.
- Sample any presumed ACM prior to alteration or maintenance work if presumed ACM may be disturbed by the work.

This Executive Summary is subject to the same standard limitations as contained in the report and must be read in conjunction with the entire report.



TABLE OF CONTENTS

1.0	INTRODUCTION AND SCOPE	1
1.1	Scope of Assessment	1
2.0	BACKGROUND INFORMATION	1
2.1	Building Year of Construction and Additions	1
2.2	Existing Reports	1
2.3	Inaccessible Locations	2
3.0	FINDINGS	2
3.1	Presumed Asbestos Materials	2
3.2	Confirmed/Presumed Asbestos-Containing Materials and Confirmed Non-Asbestos Materials	3
4.0	RECOMMENDATIONS	8
4.1	General	8
4.2	Remedial Work	8
4.3	On-going Management and Maintenance	8
5.0	TERMS AND LIMITATIONS	9
6.0	REFERENCES	9

APPENDICES

APPENDIX I	Asbestos Analytical Certificates
APPENDIX II	Location List
APPENDIX III	Hazardous Materials Summary / Sample Log Report
APPENDIX IV	All Data Report
APPENDIX V	Drawings



1.0 INTRODUCTION AND SCOPE

Hamilton-Wentworth Catholic District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment at St. John the Baptist located at 115 London Street South, Hamilton, Ontario.

The reassessment was performed by Luke Thompson, Project Technologist on May 19, 2022.

The objectives of the reassessment were to document the locations, quantities and conditions of previously identified asbestos-containing building materials, and develop corrective action plans as required. This reassessment is only to be used for the purposes of long-term management and routine maintenance. The results of this reassessment are not to be used for construction, renovation, demolition or project tendering purposes.

1.1 Scope of Assessment

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM's), and develop corrective action plans as required.

Refer to the Asbestos Building Materials Reassessment Methodology report and Annex A dated 2022, Pinchin File 303992.004, for the methodology used during the reassessment.

2.0 BACKGROUND INFORMATION

2.1 Building Year of Construction and Additions

Item	Details
Year of Construction	1929
Year(s) of Additions	1949, 1955, 1958, 1962, 1968, 2000

2.2 Existing Reports

2.2.1 Review of Previous Reports

Pinchin previously prepared the following report, which has been reviewed and relied upon as part of this assessment:

- Asbestos Assessment, St. John the Baptist, 115 London Street South, Hamilton, Ontario, September 2018, Prepared by Pinchin Ltd., Pinchin File: 224334.
- Asbestos Reassessment, St. John the Baptist, 115 London Street South, Hamilton, Ontario, August 2019, Prepared by Pinchin Ltd., Pinchin File: 243241.



Asbestos Reassessment

St. John the Baptist, 115 London Street South, Hamilton, Ontario
Hamilton-Wentworth Catholic District School Board

August 29, 2022
Pinchin File: 303992.004

- Asbestos Reassessment, St. John the Baptist, 115 London Street South, Hamilton, Ontario, June 2020, Prepared by Pinchin Ltd., Pinchin File: 272113.
- Asbestos Reassessment, St. John the Baptist, 115 London Street South, Hamilton, Ontario, July 2021, Prepared by Pinchin Ltd., Pinchin File: 286533.001

2.3 Inaccessible Locations

The following rooms or areas, were not accessible to the surveyor and are therefore not included in the report:

Location and Location #	Reason
Storage (Location 1003)	Locked, no key

3.0 FINDINGS

The following section summarizes the findings of the reassessment and provides a general description of the asbestos materials identified. For details on quantities, assessment, sample numbers, friability, condition, and locations of asbestos materials; refer to the Hazardous Materials Summary / Sample Log Report and All Data Report in Appendix III and IV, respectively.

Previous analytical sample results have been relied upon and were included in the original asbestos assessment report completed by MTE Consultants Inc. Additional samples results where collected by Pinchin have been included in Appendix I.

3.1 Presumed Asbestos Materials

A number of materials which might contain asbestos were not sampled during this reassessment due to limitations in scope and methodology. Where present, these materials are assumed to contain asbestos until otherwise proven by sampling and analysis. These materials are not shown on the drawings in Appendix V. Materials presumed to contain asbestos include:

Material	Friability
Roofing, felts and tar	Non-friable
Concrete floor levelling compound	Non-friable
Electrical components or wiring within control centers, breakers, motors or lights, insulation on wiring	Non-friable
Vermiculite in concrete block wall cavities	Friable
Adhesives and duct mastics	Non-friable







Material	Friability
Caulking	Non-friable
Fibre reinforced paints and coatings	Non-friable
Paper products	Non-friable
Soffit and fascia boards	Non-friable
Mechanical packing, ropes and gaskets	Non-friable
Exterior cladding	Non-friable
Fire resistant doors or metal clad finishes	Non-friable
Vibration dampers on HVAC equipment	Non-friable
Ceramic tile thin-set	Non-friable




3.2 Confirmed/Presumed Asbestos-Containing Materials and Confirmed Non-Asbestos Materials




This section includes materials that have been confirmed asbestos-containing by sample analysis or presumed asbestos-containing by visual identification; this section also includes materials that have been confirmed non-asbestos by sample analysis. Refer to the drawings in Appendix V for the locations of confirmed and presumed ACMs indicated via hatching or symbols. The locations of samples from the historical assessments, performed by Pinchin, have been included on the drawings.

Material and Application	Asbestos Type/Friability	Photo
Non-asbestos fireproofing is present on structural steel including beams, trusses, joists, corrugated steel deck, concrete deck, columns.	None	

Material and Application	Asbestos Type/Friability	Photo
Parging cement asbestos, is present on pipe fittings (elbows, valves, tees, hangers etc.)	Chrysotile/Friable	
Remaining pipes are either uninsulated or insulated with non-asbestos fibreglass or elastomeric insulation (Armaflex).	None	
Ducts are either uninsulated or insulated with non-asbestos fibreglass.	None	
Mechanical equipment is either uninsulated or insulated with non-asbestos fibreglass.	None	
All ceiling tiles are presumed to be non-asbestos based on the date of manufacture determined from the date stamp applied to the top of the tiles, the age of the materials determined from the age of the building or the renovation, or by sample analysis.	None	
Textured plaster is present as a ceiling finish.	Chrysotile/Friable	

Material and Application	Asbestos Type/Friability	Photo
Smooth, textured, and rough plaster present on walls and ceilings does not contain asbestos.	None	
Non-asbestos drywall joint compound is present on wall and ceiling finishes.	None	
Asbestos in drywall joint compound was banned in Canada in 1980. Drywall joint compound in the 2000 addition was installed after 1986 (1980 plus a reasonable non-compliance period based on our experience) and is assumed to contain no asbestos.	None	
Transite pipe is present.	Presumed/ Non-friable	
Vinyl floor tiles, 12"x12", white with black speck, are present.	Presumed/Non-friable (tile) Presumed/Non-friable (mastic)	

Material and Application	Asbestos Type/Friability	Photo
Vinyl floor tiles, 12"x12", beige, are present.	Presumed/Non-friable (tile) Presumed/Non-friable (mastic)	
Vinyl floor tiles, 9"x9", grey with black and white, are present.	Presumed/Non-friable (tile) Presumed/Non-friable (mastic)	
Vinyl floor tiles, 9"x9", white with grey streaks, are present.	Presumed/Non-friable (tile) Presumed/Non-friable (mastic)	

Material and Application	Asbestos Type/Friability	Photo
Vinyl floor tiles, 9"x9", brown with cream, are present.	Presumed/Non-friable (tile) Presumed/Non-friable (mastic)	
Vinyl floor tiles, 9"x9", green with golden, are present.	Presumed/Non-friable (tile) Presumed/Non-friable (mastic)	
Vinyl floor tiles, 9"x9", golden with red, are present.	Chrysotile/Non-friable (tile) None (mastic)	
Remaining vinyl floor tiles were presumed to be non-asbestos based on historical knowledge of the date of installation or from sample analysis. The mastic below the tiles is presumed to contain asbestos.	None (tile) Presumed/Non-friable (mastic)	



Additional notes on the non asbestos-containing drywall joint compound discussed above:

- Drywall (gypsum board) and drywall joint compound is present as a wall and ceiling finish throughout the building. As per the methodology, drywall joint compound is sampled at exterior walls, columns or other locations that are unlikely to have been renovated in an attempt to determine the presence of asbestos in the original drywall compound. Pinchin collected a total of 3 samples of drywall joint compound (samples S0004A-C, lab reference 71918920) and it was found that all samples do not contain asbestos. With these results, along with those collected by previous consultants and the Hamilton-Wentworth Catholic District School Board, drywall joint compound present on drywall finishes should be considered to be non-asbestos.

Additional notes on the vinyl floor tiles and mastic discussed above:

- Mastic was analysed for asbestos content where it was present on the tiles, however a comprehensive testing program for mastic was not performed.

4.0 RECOMMENDATIONS

4.1 General

Perform a detailed intrusive assessment prior to building renovation or demolition operations. The assessment should include; destructive testing (i.e. coring and/or removal of building finishes and components), sampling of other hazardous materials (lead, mercury, PCBs, mould, etc.), and materials not tested in this study (i.e. roofing materials, caulking, mastics).

4.2 Remedial Work

There is no remedial work recommended.

4.3 On-going Management and Maintenance

The following recommendations are made regarding on-going management and maintenance work involving the asbestos materials identified.

4.3.1 Asbestos

Maintain the Asbestos Management Program (AMP).

Perform a re-assessment of asbestos materials on an annual basis.

Remove asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work. Follow appropriate asbestos precautions for the classification of work being performed.



Sample presumed ACM prior to alteration or maintenance work if the presumed ACM may be disturbed by the work.

Update the asbestos inventory report upon completion of any abatement and removal of asbestos-containing materials.

5.0 TERMS AND LIMITATIONS

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.

6.0 REFERENCES

The following legislation and documents were referenced in completing the assessment and this report:

1. Asbestos on Construction Projects and in Buildings and Repair Operations, Ontario Regulation 278/05.
2. Designated Substances, Ontario Regulation 490/09.

J:\303000s\0303992.000 HWCDSB,Various2022Projects,ASB,CONS\0303992.004 HWCDSB,AllFacilities,2022,ASB,REASSMT\Deliverables\Elementary\St. John the Baptist\Report\0303992.004 St. John the Baptist ACM Reassessment Report HWCDSB Aug 29 2022.docx

Template: Master Report for Asbestos Reassessment, HAZ, April 23, 2019

APPENDIX I
Asbestos Analytical Certificates



Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project Name:	Hamilton-Wentworth Catholic District School Board, St John the Baptist 115 London St S, Hamilton, On		
Project No.:	0224334.000		
Prepared For:	M. Gibbs	Date Received:	August 10, 2018
Lab Reference No.:	b194753	Date Analyzed:	August 16, 2018
Analyst(s):	M. Tipgos	# Samples submitted:	3
		# Phases analyzed:	3

Method of Analysis:

EPA 600/R-93/116 - Method for the Determination of Asbestos in Bulk Building Materials dated July, 1993

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold (see chart below) indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

Provincial Jurisdiction	Regulatory Threshold	Provincial Jurisdiction	Regulatory Threshold
Ontario, British Columbia, Nova Scotia	0.5%	Alberta	Undefined
Quebec	0.1%	Saskatchewan	0.5% friable 1% non-friable
PEI, NWT, Yukon, Nunavut, Newfoundland and Labrador, and New Brunswick	1%	Manitoba	0.1% friable 1% non-friable

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

Pinchin Ltd. is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA-600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2005.

This report relates only to the items tested.

NOTE: This test report may not be reproduced, except in full, without the written approval of the laboratory. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. This report is valid only when signed in blue ink by the analyst. Vinyl asbestos floor tiles contain very fine fibres of asbestos and may be missed by some laboratories using the PLM method. Internal verification studies performed by Pinchin indicate that the chance of missing asbestos in floor tiles is no higher than about 2%. The vinyl tile study and laboratory documentation on measurement uncertainty is available upon request. The analysis of dust samples by PLM cannot be used as an indicator of past or present airborne asbestos fibre levels.



Pinchin Ltd. Asbestos Laboratory
Certificate of Analysis

Project Name: Hamilton-Wentworth Catholic District School Board, St John the Baptist
115 London St S, Hamilton, On

Project No.: 0224334.000

Prepared For: M. Gibbs

Lab Reference No.: b194753

Date Analyzed: August 16, 2018

BULK SAMPLE ANALYSIS

SAMPLE IDENTIFICATION	SAMPLE DESCRIPTION	% COMPOSITION (VISUAL ESTIMATE)	
		ASBESTOS	OTHER
0001A 2x4 ceiling tile (2x2 pattern with texture) / Library, Room 1027	Homogeneous, beige, layered, compressed, acoustic ceiling tile.	None Detected	Cellulose 25-50% Man-made Vitreous 25-50% Fibres Perlite 10-25% Other Non-Fibrous 0.5-5%
0001B 2x4 ceiling tile (2x2 pattern with texture) / Library, Room 1027	Homogeneous, beige, layered, compressed, acoustic ceiling tile.	None Detected	Cellulose 25-50% Man-made Vitreous 25-50% Fibres Perlite 10-25% Other Non-Fibrous 0.5-5%
0001C 2x4 ceiling tile (2x2 pattern with texture) / Library, Room 1027	Homogeneous, beige, layered, compressed, acoustic ceiling tile.	None Detected	Cellulose 25-50% Man-made Vitreous 25-50% Fibres Perlite 10-25% Other Non-Fibrous 0.5-5%

Reviewed by:

Reporting Analyst:



Analyzed by: MT 2018/8/16
Reviewed by: [Signature]
Report Sent by: EL

Special Instructions:

**Pinchin Ltd. - Asbestos Laboratory
Internal Asbestos Bulk Sample Chain of Custody**

Client Name:	Hamilton-Wentworth Catholic District School Board	Project Address:	115 London St S, Hamilton, On
Portfolio/Building No:	St John the Baptist	Pinchin File:	224334
Submitted by:	Matt Gibbs	Email:	mgibbs@pinchin.com
CC Results to:		CC Email:	
Invoice to:	Matt Gibbs	Invoice Email:	mgibbs@pinchin.com
Date Submitted:	August 8 2018	Required by:	August 15 2018
# of Samples:	3	Priority:	5 Day Turnaround
Year of Building Construction (Mandatory Field):			
Do NOT Stop on Positive (Sample Numbers):			
Pinchin Group Company (Mandatory Field):		Pinchin	

To be Completed by Lab Personnel Only:					
Lab Reference #:	194753		Time:	24 hour clock	
Received by:	AUG 10 2018 [Signature]		Date:	Month	Day Year
Name(s) of Analyst(s):					
Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)		
	0001	A	2x4 ceiling tile (2x2 pattern with texture) / Library, Room 1027 NO		
	0001	B	2x4 ceiling tile (2x2 pattern with texture) / Library, Room 1027 NO		
	0001	C	2x4 ceiling tile (2x2 pattern with texture) / Library, Room 1027 NO		



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
6-875 Main St West
Suite 200
Hamilton, Ontario L8S 4P9

Attn: Emily Balfour
Michael Maiorana

Lab Order ID: 71918920
Analysis ID: 71918920_PLM
Date Received: 7/18/2019
Date Reported: 7/23/2019

Project: 230748,115 London Street South, Hamilton, Ontario,Hamilton-Wentworth Catholic School Board,St. John the Baptist

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
S0002A	Textured Plaster on Ceiling, Classroom, Location 2017	5% Chrysotile		95% Other	White Non Fibrous Heterogeneous
71918920PLM_1					Crushed
S0002B	Textured Plaster on Ceiling, Classroom, Location 2017	Not Analyzed			
71918920PLM_2					
S0002C	Textured Plaster on Ceiling, Classroom, Location 1016	Not Analyzed			
71918920PLM_3					
S0003A - A	Smooth Plaster on Ceiling, Corridor, Location 3009	None Detected		100% Other	White Non Fibrous Homogeneous
71918920PLM_4	finish				Crushed
S0003A - B	Smooth Plaster on Ceiling, Corridor, Location 3009	None Detected	2% Hair	98% Other	Gray Non Fibrous Heterogeneous
71918920PLM_20	base				Crushed
S0003B - A	Smooth Plaster on Ceiling, Classroom, Location 3003	None Detected		100% Other	White Non Fibrous Homogeneous
71918920PLM_5	finish				Crushed
S0003B - B	Smooth Plaster on Ceiling, Classroom, Location 3003	None Detected	2% Hair	98% Other	Gray Non Fibrous Heterogeneous
71918920PLM_21	base				Crushed
S0003C - A	Smooth Plaster on Ceiling, Classroom, Location 3004	None Detected		100% Other	White Non Fibrous Homogeneous
71918920PLM_6	finish				Crushed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Bart Huber (26)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
6-875 Main St West
Suite 200
Hamilton, Ontario L8S 4P9

Attn: Emily Balfour
Michael Maiorana

Project: 230748,115 London Street South, Hamilton, Ontario,Hamilton-Wentworth Catholic School Board,St. John the Baptist

Lab Order ID: 71918920
Analysis ID: 71918920_PLM
Date Received: 7/18/2019
Date Reported: 7/23/2019

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
S0003C - B	Smooth Plaster on Ceiling, Classroom, Location 3004	None Detected	2% Hair	98% Other	Gray Non Fibrous Heterogeneous
71918920PLM_22	base				Crushed
S0003D - A	Smooth Plaster on Ceiling, Classroom, Location 1010	None Detected		100% Other	White Non Fibrous Homogeneous
71918920PLM_7	finish				Crushed
S0003D - B	Smooth Plaster on Ceiling, Classroom, Location 1010	None Detected	2% Hair	98% Other	Gray Non Fibrous Heterogeneous
71918920PLM_23	base				Crushed
S0003E - A	Smooth Plaster on Ceiling, Classroom, Location 1012	None Detected		100% Other	White Non Fibrous Homogeneous
71918920PLM_8	finish				Crushed
S0003E - B	Smooth Plaster on Ceiling, Classroom, Location 1012	None Detected	2% Hair	98% Other	Gray Non Fibrous Heterogeneous
71918920PLM_24	base				Crushed
S0003F - A	Smooth Plaster on Ceiling, Classroom, Location 2005	None Detected		100% Other	White Non Fibrous Homogeneous
71918920PLM_9	finish				Crushed
S0003F - B	Smooth Plaster on Ceiling, Classroom, Location 2005	None Detected	2% Hair	98% Other	Gray Non Fibrous Heterogeneous
71918920PLM_25	base				Crushed
S0003G - A	Smooth Plaster on Ceiling, Classroom, Location 2021	None Detected		100% Other	White Non Fibrous Homogeneous
71918920PLM_10	finish				Crushed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Bart Huber (26)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
6-875 Main St West
Suite 200
Hamilton, Ontario L8S 4P9

Attn: Emily Balfour
Michael Maiorana

Lab Order ID: 71918920
Analysis ID: 71918920_PLM
Date Received: 7/18/2019
Date Reported: 7/23/2019

Project: 230748,115 London Street South, Hamilton, Ontario,Hamilton-Wentworth Catholic School Board,St. John the Baptist

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
S0003G - B	Smooth Plaster on Ceiling, Classroom, Location 2021	None Detected	2% Hair	98% Other	Gray Non Fibrous Heterogeneous
71918920PLM_26	base				Crushed
S0004A	Drywall Joint Compound on Bulkhead, Gym Sink Room, Location 1013	None Detected		100% Other	White Non Fibrous Homogeneous
71918920PLM_11					Crushed
S0004B	Drywall Joint Compound on Ceiling, Storage, Location 1023	None Detected		100% Other	White Non Fibrous Homogeneous
71918920PLM_12					Crushed
S0004C	Drywall Joint Compound on Ceiling, Corridor, Location 1026	None Detected		100% Other	White Non Fibrous Homogeneous
71918920PLM_13					Crushed
S0005A	Textured Plaster on Ceiling, Library, Location 1027	5% Chrysotile		95% Other	White Non Fibrous Heterogeneous
71918920PLM_14					Crushed
S0005B	Textured Plaster on Ceiling, Library, Location 1027	Not Analyzed			
71918920PLM_15					
S0005C	Textured Plaster on Ceiling, Library, Location 1027	Not Analyzed			
71918920PLM_16					
S0006A	Rough Plaster on Ceiling, Crawlspace, Location 1030	None Detected	2% Hair	98% Other	Gray Non Fibrous Heterogeneous
71918920PLM_17					Crushed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Bart Huber (26)


Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,
App.E



Customer: Pinchin Ltd.
6-875 Main St West
Suite 200
Hamilton, Ontario L8S 4P9

Attn: Emily Balfour
Michael Maiorana

Project: 230748,115 London Street South, Hamilton, Ontario,Hamilton-Wentworth Catholic
School Board,St. John the Baptist

Lab Order ID: 71918920
Analysis ID: 71918920_PLM
Date Received: 7/18/2019
Date Reported: 7/23/2019

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
S0006B	Rough Plaster on Wall, Crawlspace, Location 1030	None Detected	2% Hair	98% Other	Gray Non Fibrous Heterogeneous
71918920PLM_18					Crushed
S0006C	Rough Plaster on Ceiling, Crawlspace, Location 1031	None Detected	2% Hair	98% Other	Gray Non Fibrous Heterogeneous
71918920PLM_19					Crushed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Bart Huber (26)

Analyst

Approved Signatory

71918920

Version 1-15-2012

Client: Pinchin Ltd.
Contact: Emily Balfour
 6-875 Main Street West, Suite 200,
 Hamilton ON L8S 4P9
Address:
Phone: 905-577-6206
Fax: 905-577-6207
Email: ebalfour@pinchin.com
 mmaiorana@pinchin.com
 230748, 115 London Street South,
 Hamilton, Ontario, Hamilton-
 Wentworth Catholic School
 Board, St. John the Baptist
Project:
Client Notes:
P.O. #. 230748
Date Submitted: July 17, 2019
Analysis: PLM - Stop Positive
TurnAroundTime: 4days

***Instructions:**
 Use Column "B" for your contact info

To See an Example Click the
 bottom Example Tab.

Enter samples between "<<" and ">>"

Begin Samples with a "<<" above the first sample
 and end with a ">>" below the last sample.
 Only Enter your data on the first sheet "Sheet1"

Note: Data 1 and Data 2 are optional
 fields that do not show up on the official
 report, however they will be included
 in the electronic data returned to you
 to facilitate your reintegration of the report data.

Invoice to:

ap@pinchin.com



Scientific
 Analytical
 Institute

4604 Dundas Dr.
 Greensboro, NC 27407
 Phone: 336.292.3888
 Fax: 336.292.3313
 Email: lab@sailab.com

Sample Number	Data 1 (Lab use only)	Sample Description	Data 2 (Lab use only)
<<			
S0002A		Textured Plaster on Ceiling, Classroom, Location 2017	
S0002B		Textured Plaster on Ceiling, Classroom, Location 2017	
S0002C		Textured Plaster on Ceiling, Classroom, Location 1016	
S0003A		Smooth Plaster on Ceiling, Corridor, Location 3009	
S0003B		Smooth Plaster on Ceiling, Classroom, Location 3003	
S0003C		Smooth Plaster on Ceiling, Classroom, Location 3004	
S0003D		Smooth Plaster on Ceiling, Classroom, Location 1010	
S0003E		Smooth Plaster on Ceiling, Classroom, Location 1012	
S0003F		Smooth Plaster on Ceiling, Classroom, Location 2005	
S0003G		Smooth Plaster on Ceiling, Classroom, Location 2021	
S0004A		Drywall Joint Compound on Bulkhead, Gym Sink Room, Location 1013	
S0004B		Drywall Joint Compound on Ceiling, Storage, Location 1023	
S0004C		Drywall Joint Compound on Ceiling, Corridor, Location 1026	

Accepted



Rejected



S0005A

S0005B

S0005C

S0006A

S0006B

S0006C

>>

Textured Plaster on Ceiling, Library, Location 1027

Textured Plaster on Ceiling, Library, Location 1027

Textured Plaster on Ceiling, Library, Location 1027

Rough Plaster on Ceiling, Crawlspace, Location 1030

Rough Plaster on Wall, Crawlspace, Location 1030

Rough Plaster on Ceiling, Crawlspace, Location 1031



Pinchin Ltd. Asbestos Laboratory *Certificate of Analysis*

Project Name:	Hamilton-Wentworth Catholic School Board, St. John the Baptist, 115 London Street South, Hamilton, Ontario		
Project No.:	0272113.000		
Prepared For:	E. Balfour / M. Maiorana		
Lab Reference No.:	b230655	Date Received:	May 21, 2020
Analyst(s):	K. Cockburn	Date Analyzed:	June 1, 2020
		# Samples submitted:	3
		# Phases analyzed:	1

Method of Analysis:

EPA 600/R-93/116 - Method for the Determination of Asbestos in Bulk Building Materials dated July, 1993

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold (see chart below) indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2005.

This report relates only to the items tested.

NOTE: *This test report may not be reproduced, except in full, without the written approval of the laboratory. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. This report is valid only when signed in blue ink by the analyst. Vinyl asbestos floor tiles contain very fine fibres of asbestos and may be missed by some laboratories using the PLM method. Internal verification studies performed by Pinchin indicate that the chance of missing asbestos in floor tiles is no higher than about 2%. The vinyl tile study and laboratory documentation on measurement uncertainty is available upon request. The analysis of dust samples by PLM cannot be used as an indicator of past or present airborne asbestos fibre levels.*



Pinchin Ltd. Asbestos Laboratory
Certificate of Analysis

Project Name: Hamilton-Wentworth Catholic School Board, St. John the Baptist,
115 London Street South, Hamilton, Ontario
Project No.: 0272113.000
Prepared For: E. Balfour / M. Maiorana
Lab Reference No.: b230655
Date Analyzed: June 1, 2020

BULK SAMPLE ANALYSIS

SAMPLE IDENTIFICATION	SAMPLE DESCRIPTION	% COMPOSITION (VISUAL ESTIMATE)	
		ASBESTOS	OTHER
S0007A Parging cement, Corridor, Location 2020	Homogeneous, grey, soft, parging cement.	Chrysotile 50-75%	Non-Fibrous Material 25-50%
Comments:	Cotton fabric reinforcement is present on the surface of this sample.		
S0007B Parging cement, Corridor, Location 2020			Not Analyzed
Comments:	Analysis was stopped due to a previous positive result.		
S0007C Parging cement, Corridor, Location 2020			Not Analyzed
Comments:	Analysis was stopped due to a previous positive result.		

Reviewed by:

Reporting Analyst:



Analyzed by: HC
Reviewed by: HB
Report Sent by: 14



Instructions:

**Pinchin Ltd. - Asbestos Laboratory
Internal Asbestos Bulk Sample Chain of Custody**

Client Name:	Hamilton-Wentworth Catholic School Board	Project Address:	115 London Street South, Hamilton, Ontario
Portfolio/Building No:	St. John the Baptist	Pinchin File:	272113
Submitted by:	Emily Balfour	Email:	ebalfour@pinchin.com
CC Results to:	Michael Maiorana	CC Email:	mmaiorana@pinchin.com
Invoice to:	Accounts Payable	Invoice Email:	ap@pinchin.com
Date Submitted:	May 19 2020	Required by:	May 26 2020
# of Samples:	3	Priority:	5 Day Turnaround
Year of Building Construction (Mandatory Field):	1929		
Do NOT Stop on Positive (Sample Numbers):			
Pinchin Group Company (Mandatory Field):	Pinchin		

To be Completed by Lab Personnel Only:				
Lab Reference #:	6236655 CH		Time:	24 hour clock
Received by:	MAY 21 2020		Date:	Month Day Year
Name(s) of Analyst(s):	HC 2020/06/01			
Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)	
	S0007	A	Parging cement, Corridor, Location 2020 CH50-757.	
	S0007	B	Parging cement, Corridor, Location 2020 - NA -	
	S0007	C	Parging cement, Corridor, Location 2020 - NA -	

APPENDIX II
Location List

Client: Hamilton-Wentworth Catholic District Sch
Building Name: St. John the Baptist
Survey Date: 2018-07-19

Site: 115 London Street South, Hamilton, ON
Last Re-Assessment: 2022-05-18

Location No.	Name or Description	Area ft ²	Floor No.	Bldg. Phase	Notes
1	Presumed Asbestos	0		A	
1001	Kindergarten, room no. 1	0		A	
1002	Kindergarten, room no. 2	0		A	
1003	Storage	0		A	
1004	Washroom	0		A	
1005	Classroom	0		A	
1006	Room Amalgamated	0		A	Amalgamated to Loc. 1005
1007	Room Amalgamated	0		A	Amalgamated to Loc. 1005
1008	Custodian Closet	0		A	
1009	Stairwell	0		A	
1010	Book Room	0		A	
1011	Boiler Room	0		A	
1012	Storage	0		A	
1013	Gym Sink Room	0		A	
1014	Special ED	0		A	
1015	Language Room	0		A	
1016	Classroom 10	0		A	
1017	Stairwell	0		A	
1018	Girls Washroom	0		A	
1019	Boys Washroom	0		A	
1020	Boys Storage	0		A	Part of 1019
1021	Gym Corridor	0		A	
1022	Boys Storage	0		A	Part of 1019
1023	Storage	0		A	
1024	Kitchenette	0		A	
1025	Gym	0		A	
1026	Corridor	0		A	
1027	Library	0		A	
1028	Corridor	0		A	
1029	Corridor	0		A	
1030	Crawlspace	0		A	
1031	Crawlspace	0		A	
2001	Classroom 21	0		A	
2002	Classroom	0		A	
2003	Classroom 15	0		A	
2004	Classroom 14	0		A	
2005	Lamination Room	0		A	
2006	Staff Room	0		A	
2007	Boys Washroom	0		A	
2008	Girls Washroom	0		A	
2009	Custodian	0		A	
2010	Classroom 18	0		A	
2011	Classroom 17	0		A	
2012	Classroom 16	0		A	
2013	Office, room no. 13	0		A	
2014	Conference Room	0		A	
2015	Main Office	0		A	
2016	Office	0		A	
2017	Classroom 22	0		A	
2018	Corridor	0		A	
2019	Corridor	0		A	
2020	Corridor	0		A	
2021	Classroom Storage	0		A	
3001	Storage	0		A	
3002	Storage	0		A	
3003	Classroom 24	0		A	
3004	Classroom 25	0		A	
3005	Classroom 26	0		A	
3006	Classroom 27	0		A	
3007	Classroom 23	0		A	
3008	Storage	0		A	
3009	Corridor	0		A	
3010	Custodian Room	0		A	

Location No.	Name or Description	Area ft ²	Floor No.	Bldg. Phase	Notes
3011	Alcove	0		A	
3012	Entry	0		A	

APPENDIX III

Hazardous Materials Summary / Sample Log Report

Client: Hamilton-Wentworth Catholic District Sch

Site: 115 London Street South, Hamilton, ON

Building Name: St. John the Baptist

Survey Date: 2018-07-19

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	S0001 ABC	Ceiling Acoustic Tile Ceiling Tiles (lay-in) 2x2 Textured Pattern	1027,2019	A	0	0	0	100	None Detected	No	
Asbestos	S0002 ABC	Ceiling Plaster	1016,2017	A	0	0	0	100	Chrysotile	Yes	PF
Asbestos	S0003 ABCDEFG	Ceiling Plaster	1010,1012,2003,2004,2005,2006,2013,2014,2015 2016,2019,2021,3001,3002,3003,3004,3005,3006 3007,3008,3009,3010,3011,3012	A	0	0	0	100	None Detected	No	
Asbestos	S0004 ABC	Ceiling, Wall Bulkhead Drywall And Joint Compound	1013,1023,1024,1026	A	0	0	0	100	None Detected	No	
Asbestos	S0005 ABC	Ceiling Plaster	1027	A	0	0	0	103	Chrysotile	Yes	PF
Asbestos	S0006 ABC	Ceiling, Wall Plaster	1030,1031	A	0	0	0	100	None Detected	No	
Asbestos	S0007 ABC	Piping Parging Cement	1028,2020	A	0	0	36	0	Chrysotile	Yes	F
Asbestos	V9000	Floor Vinyl Floor Tile (no Mastic) 9x9 Golden With Red	3004,3005,3006	A	0	0	0	100	Confirmed Asbestos	Yes	NF
Asbestos	V9500	Floor Mastic	1014,1015,1016,1027,2001,2002,2003,2004,2005 2006,2009,2010,2011,2012,2013,2017,2021,3006 3010,3011,3012	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Floor Vinyl Floor Tile (no Mastic) 12x12, 12x12 Beige, 12x12 White With Black Speck, 9"x9" Green With Golden, 9x9 Brown With Cream, 9x9 Green With Golden, 9x9 Grey With Black And White, 9x9 White With Grey Streaks	1014,1015,1027,2006,2009,2010,2011,2012,2021 3004,3005,3006,3012	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Mechanical Equipment Boiler Refractory Ceramic Fibre	1	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Mechanical Equipment Boiler Thermal Insulation	1	A	0	0	0	0	Presumed Asbestos	Yes	F
Asbestos	V9500	Other Door, Window Caulking	1	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Electrical Equipment Cement Product Transite Components In Electrical And Switchgear Equipment	1	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Soffit Plaster	1	A	0	0	0	100	Presumed Asbestos	Yes	PF
Asbestos	V9500	Other Electrical Wire Textile Woven Jacketing And Insulation	1	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Piping Cement Product	2007,2020	A	6	0	0	0	Presumed Asbestos	Yes	NF
Asbestos	V9500	Structure Roof Roofing Material	1	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Wall Interior Vermiculite/concrete Block Walls	1	A	0	0	0	100	Presumed Asbestos	Yes	F
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2x2 Textured	2014	A	0	0	0	0	Non	No	

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
		Pinhole							Asbestos		
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2x2 Textured Pinhole (date Stamped 2005)	2016	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2x4 Drywall	2007,2008	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2x4 Pinhole	2002	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2x4 Pinhole (date Stamped 2005)	2001	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2x4 Short Fissure Random Pinhole	2020	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2x4 Short Fissure Random Pinhole (date Stamped 2005)	1009	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2x4 Short Fissure Random Pinhole (date Stamped 2005)	1021,1026,1028,1029	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2x4 Textured Pinhole	2018	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2x4 Textured Pinhole (date Stamped 2005)	1017	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2x5 Short Fissure Random Pinhole (date Stamped 2005)	1002	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Concrete (poured)	1020,1022	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Concrete (precast)	1001,1002,1005,1008,1009,1011,1014,1015,1018 1019,2009,2010,2011,2012	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Beam Deck Joist Steel	1025	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Carpet	1027	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Carpet Grey With White Streaks	1027	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Ceramic Tiles	1004,1018,1019,1020,1021,1022,1026,1029,2014 2018,3010,3011	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Concrete (poured)	1011	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Mastic	1001,1002,1005,3002,3003,3004,3005,3007,3008	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Terrazzo	1008,1009,1010,1012,1017,1028,2007,2008,2019 2020,3009	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile (no Mastic) 12x12 Beige Multi Fleck	3007	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile (no Mastic) 12x12 Beige Multi Fleck (installed 2013)	2013	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile (no Mastic) 12x12	3002,3003,3008	A	0	0	0	0	Non	No	

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
		Beige Multi-fleck							Asbestos		
Asbestos	V0000	Floor Vinyl Floor Tile (no Mastic) 12x12 Beige Multi-fleck (installed 2013)	1001	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile (no Mastic) 12x12 Beige Multi-fleck (installed 2000)	1025	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile (no Mastic) 12x12 Beige Multi-fleck (installed In 2013)	1005	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile (no Mastic) 12x12 Beige With Beige Speck (installed Post 1990)	2004	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile (no Mastic) 12x12 Multi-fleck (installed 2013)	1002	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile (no Mastic) 12x12 Pink Marble (installed Post 1990)	2005	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile (no Mastic) 12x12 White With Beige Speck (installed Post 1990)	2003	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile (no Mastic) 12x12 White With Grey (1990)	2017	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile (no Mastic) 12x12 White With White And Grey Fleck (installed Post 1990)	2001,2002	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile (no Mastic) 12x12 Beige Multit-fleck	1016	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic 12x12 Blue (installed Post 1990)	1023,1024	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic Blue, Installed Post 1990	1013	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Wood	2015,2016,3001	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Other Fireproofing (cementitious) (previously Sampled)	2018	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Other Exterior Masonry	1	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Piping All Fibreglass	1008,1010,1011,1012,1014,1015,1016,1018,1019 1020,1022,1023,1024,1025,1028,2003,2004,2005 2006,2010,2011,2013,2015,2017,2020,2021,3005 3006	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Wall Ceramic Tiles	1004	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Wall Drywall (no Compound)	2015	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Wall Drywall And Joint Compound	1004,2014,3004,3006,3007,3008,3010	A	0	0	0	75	Non Asbestos	No	
Asbestos	V0000	Wall Masonry	1001,1002,1005,1008,1009,1010,1011,1012,1013 1014,1015,1016,1017,1018,1019,1020,1021,1022	A	0	0	0	0	Non Asbestos	No	

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
			1023,1024,1025,1026,1028,1029,2001,2002,2003 2004,2007,2008,2009,2010,2011,2012,2016,2018 2020								
Asbestos	V0000	Wall Plaster	1010,1012,1015,1027,2004,2013,2021,3002,3003 3004,3005,3006,3007,3008,3012	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Wall Plaster Hwcdsb Sample Agat 19h452440	2003	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Wall Plaster Hard Textured	1014,1016,2006,2015,2016,2017,2019,3001,3009 3010,3011,3012	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Wall Plaster Hard Textured Plaster	2005	A	0	0	0	0	Non Asbestos	No	

Legend:

Sample number		Units			
S####	Asbestos sample collected	SF	Square feet	NF	Non Friable material.
L####	Paint sample collected	LF	Linear feet	F	Friable material
P####	PCB sample collected	EA	Each	PF	Potentially Friable material
M####	Mould sample collected	%	Percentage		
V####	Material visually similar to numbered sample collected				
V0000	Known non Hazardous Material				
V9000	Material is visually identified as Hazardous Material				
V9500	Material is presumed to be Hazardous Material				
[Loc. No.]	Abated Material				

APPENDIX IV
All Data Report

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1 : Presumed Asbestos
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Mechanical Equipment	Boiler	Thermal Insulation		Metal	D	N						V9500	Presumed Asbestos		Presumed Asbestos	F
Mechanical Equipment	Boiler	Refractory Ceramic Fibre			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Door	Caulking			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Electrical Equipment	Cement Product, Transite components in electrical and switchgear equipment			B	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Electrical Wire	Textile, Woven jacketing and insulation	Insulation		B	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Exterior	Masonry			A	Y						V0000	Non-Asbestos		None	
Other	Soffit	Plaster	Exterior		C	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	PF
Other	Window	Caulking			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Structure	Roof	Roofing material			C	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall	Interior	Vermiculite/concrete block walls			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1001 : Kindergarten
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #: 1
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (precast)			C	Y						V0000	Non-Asbestos		None	
Floor		Mastic			D	N						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 Beige Multi-Fleck (Installed 2013)			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1002 : Kindergarten
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #: 2
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (precast)			C	Y						V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in), 2x5 Short Fissure Random Pinhole (date stamped 2005)			C	Y						V0000	Non-Asbestos		None	
Floor		Mastic			D	N						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 Multi-Fleck (Installed 2013)			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1004 : Washroom
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Ceramic Tiles			A	Y						V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y						V0000	Non-Asbestos		None	
Wall		Ceramic Tiles			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1005 : Classroom
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (precast)			C	Y						V0000	Non-Asbestos		None	
Floor		Mastic			D	N						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 Beige Multi-Fleck (installed in 2013)			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1008 : Custodian Closet
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (precast)			C	Y						V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1009 : Stairwell
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (precast)			C	N						V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in), 2x4 Short Fissure Random Pinhole (Date Stamped 2005)			C	Y						V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1010 : Book Room
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	S0003D	None Detected	N.D.	None	
Floor		Terrazzo			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Plaster			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1011 : Boiler Room
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (precast)			C	Y						V0000	Non-Asbestos		None	
Floor		Concrete (poured)			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1012 : Storage
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	S0003E	None Detected	N.D.	None	
Floor		Terrazzo			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1013 : Gym Sink Room
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Bulkhead	Drywall and joint compound			C	Y		100			%	S0004A	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic, Blue, installed post 1990			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1014 : Special ED
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (precast)			C	Y						V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 White with Black Speck			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Plaster, Hard Textured			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1015 : Language Room
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (precast)			C	Y						V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 White with Black Speck			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Plaster			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1016 : Classroom 10
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster, Textured			C	Y		100(7)			%	S0002C	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 beige mulit-fleck			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Plaster, Hard Textured			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1017 : Stairwell
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 Textured Pinhole (date stamped 2005)			C	Y						V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1018 : Girls Washroom
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (precast)			C	Y						V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1019 : Boys Washroom
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (precast)			C	Y						V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1020 : Boys Storage
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (poured)			C	Y						V0000	Non-Asbestos		None	
Duct	Not Found	Abated Material													[Abated]	
Floor		Ceramic Tiles			A	Y						V0000	Non-Asbestos		None	
Piping	All	Fibreglass			C	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Part of 1019

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1021 : Gym Corridor
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 Short Fissure Random Pinhole (date stamped 2005)			C	Y						V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1022 : Boys Storage
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (poured)			C	Y						V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y						V0000	Non-Asbestos		None	
Piping	All	Fibreglass			C	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Part of 1019

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1023 : Storage
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	S0004B	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic, 12x12 Blue (installed post 1990)			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1024 : Kitchenette
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Vinyl Floor Tile and Mastic, 12x12 Blue (installed post 1990)			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0004	None Detected	N.D.	None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1025 : Gym
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Beam Deck Joist	Steel			C	Y						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 Beige Multi-Fleck (installed 2000)			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1026 : Corridor
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 Short Fissure Random Pinhole (date stamped 2005)			C	Y						V0000	Non-Asbestos		None	
Ceiling		Drywall and joint compound			C	N		100			%	S0004C	None Detected	N.D.	None	
Floor		Ceramic Tiles			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1027 : Library
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster, Textured			C	Y		33(7)	1(7)		%	S0005ABC	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2x2 Textured Pattern			C	Y		33			%	S0001ABC	None Detected	N.D.	None	
Floor		Carpet			A	Y						V0000	Non-Asbestos		None	
Floor		Carpet, Grey with white streaks			A	Y						V0000	Non-Asbestos		None	
Floor		Carpet, Grey with white streaks			A	Y						V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 Beige			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Plaster			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1028 : Corridor
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 Short Fissure Random Pinhole (date stamped 2005)			C	Y						V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	N						V0000	Non-Asbestos		None	
Piping		Parging Cement	Fitting		C	N		30(7)	1(7)		EA	V0007	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1029 : Corridor
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 Short Fissure Random Pinhole (date stamped 2005)			C	Y						V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #1030 : Crawlspce
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	S0006A	None Detected	N.D.	None	
Floor		Concrete (poured)			A	Y										
Wall		Plaster			A	Y		100			%	S0006B	None Detected	N.D.	None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #1031 : Crawlspce
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	S0006C	None Detected	N.D.	None	
Floor		Concrete (poured)			A	Y										
Wall		Plaster			A	Y		100			%	V0006	None Detected	N.D.	None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2001 : Classroom 21
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 Pinhole (date stamped 2005)			C	Y						V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 White with White and Grey Fleck (installed post 1990)			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2002 : Classroom
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 Pinhole			C	Y						V0000	Non-Asbestos		None	
Floor		Mastic			D	N						V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 White with White and Grey Fleck (installed post 1990)			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2003 : Classroom 15
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 White with Beige Speck (installed post 1990)			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Plaster, HWCDSB sample AGAT 19H452440			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2004 : Classroom 14
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Mastic			D	N						V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 Beige with Beige Speck (installed post 1990)			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Plaster			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2005 : Lamination Room
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	S0003F	None Detected	N.D.	None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 Pink Marble (installed post 1990)			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Plaster, Hard Textured Plaster			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2006 : Staff Room
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9x9 Grey with Black and White			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9x9 Grey with Black and White			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Plaster, Hard Textured			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2007 : Boys Washroom
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 Drywall			C	Y						V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y						V0000	Non-Asbestos		None	
Piping		Cement Product			C	N		3(7)			LF	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2008 : Girls Washroom
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 Drywall			C	Y						V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2009 : Custodian
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (precast)			C	Y						V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9x9 White with Grey Streaks			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2010 : Classroom 18
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (precast)			C	Y						V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9x9 White with Grey Streaks			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2011 : Classroom 17
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (precast)			C	Y						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, Peach with white fleck			A	Y										
Floor		Vinyl Floor Tile and Mastic, 9x9 green with white and grey fleck			A	Y										
Floor		Vinyl Floor Tile and Mastic, Peach with white fleck			A	Y										
Floor		Vinyl Floor Tile and Mastic, 9x9 green with white and grey fleck			A	Y										
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9x9 White with Grey Streaks			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2012 : Classroom 16
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Concrete (precast)			C	Y						V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9x9 White with Grey Streaks			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2013 : Office
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #: 13
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 Beige Multi Fleck (installed 2013)			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Plaster			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2014 : Conference Room
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x2 Textured Pinhole			C	Y						V0000	Non-Asbestos		None	
Ceiling		Plaster			C	N		100			%	V0003	None Detected	N.D.	None	
Floor		Ceramic Tiles			A	Y						V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2015 : Main Office
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Wood			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass			C	Y						V0000	Non-Asbestos		None	
Wall		Plaster, Hard Textured			A	Y						V0000	Non-Asbestos		None	
Wall		Drywall (no compound)			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2016 : Office
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x2 Textured Pinhole (date stamped 2005)			C	Y						V0000	Non-Asbestos		None	
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Wood			A	Y						V0000	Non-Asbestos		None	
Wall		Plaster, Hard Textured			A	Y						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2017 : Classroom 22
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster, Textured			C	Y		50(7)			%	S0002AB	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12 White with Grey (1990)			A	Y						V0000	Non-Asbestos		None	
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Plaster, Hard Textured			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2018 : Corridor
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 Textured Pinhole			C	Y						V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y						V0000	Non-Asbestos		None	
Other		Fireproofing (Cementitious), (previously sampled)			C	N						V0000	Non-Asbestos		None	
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #2019 : Corridor
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 2x2 pattern with texture			C	Y		100			%	V0001	None Detected	N.D.	None	
Floor		Terrazzo			A	Y						V0000	Non-Asbestos		None	
Wall		Plaster, Hard Textured			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2020 : Corridor
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 Short Fissure Random Pinhole			C	Y						V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y						V0000	Non-Asbestos		None	
Piping		Cement Product			C	N		3(7)			LF	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	N						V0000	Non-Asbestos		None	
Piping		Parging Cement	Fitting		C	N		4(7)	1(7)		EA	S0007ABC	Chrysotile	50-75%	Confirmed Asbestos	F
Wall		Masonry			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #2021 : Classroom Storage
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	S0003G	None Detected	N.D.	None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 12x12			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #3001 : Storage
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Wood			A	Y						V0000	Non-Asbestos		None	
Wall		Plaster, Hard Textured			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #3002 : Storage
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Mastic			D	N						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 Beige Multi-Fleck			A	Y						V0000	Non-Asbestos		None	
Wall		Plaster			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #3003 : Classroom 24
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	S0003B	None Detected	N.D.	None	
Floor		Mastic			D	N						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 Beige Multi-Fleck			A	Y						V0000	Non-Asbestos		None	
Wall		Plaster			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #3004 : Classroom 25
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	S0003C	None Detected	N.D.	None	
Floor		Mastic			D	N						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 9x9 Golden with Red			A	Y		100(7)			%	V9000	Confirmed Asbestos		Confirmed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9"x9" green with golden			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Drywall and joint compound			A	Y						V0000	Non-Asbestos		None	
Wall		Plaster			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #3005 : Classroom 26
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Mastic			D	N						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 9x9 Golden with Red			A	Y		100(7)			%	V9000	Confirmed Asbestos		Confirmed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9x9 Green with Golden			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Plaster			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #3006 : Classroom 27
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9x9 Golden with Red			A	Y		100(7)			%	V9000	Confirmed Asbestos		Confirmed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9x9 Green with Golden			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass	Insulation		C	Y						V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y						V0000	Non-Asbestos		None	
Wall		Plaster			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #3007 : Classroom 23
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Mastic			D	N						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 Beige Multi Fleck			A	Y						V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y						V0000	Non-Asbestos		None	
Wall		Plaster			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #3008 : Storage
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Mastic			D	N						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 Beige Multi-Fleck			A	Y						V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y						V0000	Non-Asbestos		None	
Wall		Plaster			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #3009 : Corridor
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	S0003A	None Detected	N.D.	None	
Floor		Terrazzo			A	Y						V0000	Non-Asbestos		None	
Wall		Plaster, Hard Textured			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #3010 : Custodian Room
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Ceramic Tiles			A	Y						V0000	Non-Asbestos		None	
Floor		Mastic			D	N						V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Drywall and joint compound			A	Y		50			%	V0000	Non-Asbestos		None	
Wall		Plaster, Hard Textured			A	Y						V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Hamilton-Wentworth Catholic District Sch
Location: #3011 : Alcove
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y						V0003	None Detected	N.D.	None	
Floor		Ceramic Tiles			A	Y						V0000	Non-Asbestos		None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Plaster, Hard Textured			A	Y						V0000	Non-Asbestos		None	

Client: Hamilton-Wentworth Catholic District Sch
Location: #3012 : Entry
Survey Date: 2018-07-19

Site: Elementary
Floor:

Building Name: St. John the Baptist
Room #:
Last Re-Assessment: 2022-05-18

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	V0003	None Detected	N.D.	None	
Floor		Mastic			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile (No Mastic), 9x9 Brown with Cream			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Wall		Plaster			A	Y						V0000	Non-Asbestos		None	
Wall		Plaster, Hard Textured			A	Y						V0000	Non-Asbestos		None	

Legend:



Sample number		Units		Other	
S####	Asbestos sample collected	SF	Square feet	A	Access
V####	Material visually similar to numbered sample collected	LF	Linear feet	V	Visible
V0000	Known non-asbestos material	EA	Each	AP	Air Plenum
V9000	Visually identified as an asbestos material	%	Percentage	F	Friable material
V9500	Material is presumed to be an asbestos material			NF	Non Friable material
				PF	Potentially Friable material

Access	
A	Accessible to all building occupants
B	Accessible to maintenance and operations staff without a ladder
C	Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas
D	Not normally accessible

Condition	
Good	No visible damage or deterioration
Fair	Minor, repairable damage, cracking, delamination or deterioration
Poor	Irreparable damage or deterioration with exposed and missing material

Visible	
Y	The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels).
N	The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points.

Air Plenum	
Yes or No	The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation.

Colour Coding	
	The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code).
	The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling.

Action					
(1)	Clean up of ACM Debris	(2)	Precautions for Access Which may Disturb ACM Debris	(3)	ACM removal
(4)	Precautions for Work Which may Disturb ACM in Poor Condition	(5)	Proactive ACM removal (Minimum repair required for fair condition)	(6)	ACM repair
(7)	Management program and surveillance				

APPENDIX V
Drawings

NOT ALL KNOWN OR SUSPECTED ASBESTOS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING.
REFER TO THE ASBESTOS REASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED
ASBESTOS BUILDING MATERIALS.


LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT



905-577-6206 www.pinchin.com

- LEGEND:
- (X) LOCATION NUMBER
 - ⊙ ASBESTOS BULK SAMPLE
- ASBESTOS-CONTAINING MATERIALS:
- P PIPE INSULATION
 - T TRANSITE
 - TEXTURED PLASTER CEILING
 - FLOOR TILES AND MASTIC
 - VINYL FLOOR TILES
 - MASTIC



CLIENT:

Hamilton-Wentworth
Catholic District School Board
Believing, Achieving, Serving

LOCATION:
ST. JOHN THE BAPTIST
115 LONDON ST S
HAMILTON, ONTARIO

TITLE:
ASBESTOS REASSESSMENT
FLOOR LEVEL 1

DATE: AUGUST 2022	PROJECT # : 303992.004
DRAWN BY: EB	DRAWING: 1 OF 3
CHECKED BY: EB	
SCALE: NTS	

NOT ALL KNOWN OR SUSPECTED ASBESTOS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS REASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT



905-577-6206 www.pinchin.com

LEGEND:

- (X) LOCATION NUMBER
- ⊙ ASBESTOS BULK SAMPLE

ASBESTOS-CONTAINING MATERIALS:

- P PIPE INSULATION
- T TRANSITE
- TEXTURED PLASTER CEILING
- FLOOR TILES AND MASTIC
- VINYL FLOOR TILES
- MASTIC



CLIENT:



LOCATION:

ST. JOHN THE BAPTIST
115 LONDON ST S
HAMILTON, ONTARIO

TITLE:

ASBESTOS REASSESSMENT
FLOOR LEVEL 2

DATE:

AUGUST 2022

PROJECT # :

303992.004

DRAWN BY:

EB

CHECKED BY:

EB

SCALE:

NTS

DRAWING:

2 OF 3

BASE PLAN PROVIDED BY CLIENT




905-577-6206

www.pinchin.com

LEGEND:

(X) LOCATION NUMBER

 ASBESTOS BULK SAMPLE

ASBESTOS-CONTAINING MATERIALS:

P PIPE INSULATION

TRANSITE

 TEXTURED PLASTER CEILING

 FLOOR TILES AND MASTIC

VINYL FLOOR TILES

 MASTIC

CLIENT:



Hamilton-Wentworth
Catholic District School Board

Believing, Achieving, Serving

LOCATION:

ST. JOHN THE BAPTIST
115 LONDON ST S
HAMILTON, ONTARIO

TITLE:

ASBESTOS REASSESSMENT
FLOOR LEVEL 3

DATE:

AUGUST 2022

PROJECT # :

303992.004

DRAWN BY:

EB

CHECKED BY:

EB

SCALE:

NTS

3 OF 3

